Comments received

IEEE P802.3az D3.2 Energy Efficient Ethernet comments

C/ 45 SC 45	5.2.1.76a.6	P 122	L 4	# 1	Cl 55	SC	55.4.2.5.15	5 ł	2 20	L 53	# 5	
Booth, Brad		Applied Micro	(AMCC)		Parnaby, (Gavin		Sol	arflare Co	ommunicat		
Comment Type	TR Comm	ent Status X			Comment	Туре	TR	Comment Stat	ıs X		TH	ŀΡ
The fast retrain enable bit has the ability to override a negotiated state of operation. Changing this bit after a negotiated operating mode should not cause that mode to fail. In review of these bits and those in the autonegotiation register set, there are some modifications that should help prevent the above condition from occurring.						Leaving the THP on during coefficient exchange is not a good choice. The increased number of decision levels makes training more difficult in the presence of a severe noise environment. This reduces the value of the fast retrain capability. Coefficient exchange with non-precoded PAM2 is used during the normal training and is more robust.						
Delete hit 1 147	' 3 from Table 45-	53a			Suggestee	dRemed	dy					
Change bit 1.14 Change bit from Replace all the When read as a retrain was sele selected. See 4 On page 135 in to be "Fast retra 45.2.7.10.5a, th See also 45.2.1	77.0 in Table 45-5 n R/W to be RO. paragraphs and n a one, bit 1.147.0 cted. When read 5.2.7.10.5a. Table 45-148 and ain advertised abil at reads: .76a.6.	3a to be Fast retra otes in 45.2.1.76a indicates that durir as a zero, bit 1.14 d in subheading 45 ity". Add sentence se Status O	in enabled (not .6 to read: ng the most rec 7.3 indicates th 5.2.7.10.5a, cha at the end of th	e the "d" at the end). ent autonegotiation fast at fast retrain was not ange "Fast retrain ability" he paragraph in	Chang 'PHYs showr to TRI 55.4.2 PMA_ equiva After t state a perioc THP o Add T	ge the te that su n in Figu UE. This 2.2.2. Af Coeff_t alent to the dete and res ds after disabled 'HP_Tx-	ext in the fii upport the fa ure 55-27b. s causes the fter comple Exch state, 9 LDPC fra- pond with F receiving the d.' <=zeros to	rst paragraph of § ast retrain capabi PHYs may requi- ne transmission o- ting the link failur disabled its THP ame periods. e link failure sign PAM2 signaling w he link failure sign PMA_INIT_FR in	5.4.2.5.1 lity shall ir set a fast i f an easily e signal th , and send I, a PHY s ithin a tim Pal. The P. Figure 55	5 as follows mplement the fas retrain by setting /-detected link fa he PHY shall tran d PAM2 signaling shall transition to he period equival AM2 signaling sh 5-24.	st retrain state diagram the variable loc_fr_requilure signal specified in the signal specified in the state of the g within a time period the PMA_Coeff_Exch ent to 9 LDPC frame hall be transmitted with	
					Proposed	Respor	nse	Response Statu	is O			

CI 55 SC 55.4.2.5.15

IEEE P802.3az D3.2 Energy Efficient Ethernet comments

THP

CI 55	SC 55.4.2.5.15	P 220	L 53	#	4
Bennett, Mich	nael	Lawrence Ber	keley Na		

Comment Type T Comment Status X

This comment is submitted by Mike Bennett on behalf of George Zimmerman

The first paragraph (lines 53-54) describes what happens when the PHY transmits the link failure signal and explicitly says 'shall....keep its THP turned on with its previouslyexchanged coefficients, and send PAM2 signaling...': this text was added after the meeting in Geneva.

The second paragraph (top page 221, lines 1-4) describes what happens after the PHY receives the link failure signal only says 'a PHY shall transition to the PMA Coeff Exch state and respond with PAM2 signaling'. No requirement is stated that the PHY 'shall' respond with THP encoded signaling. This second paragraph is in line with unchanged text in the base standard (802.3-2008) 55.4.2.5.14. (bottom of page 497, top of page 498) paragraph beginning with "Following coefficient exchange", states that following coefficient exchange, "THP is enabled... (and later) "at the closure of the THP loop...", indicating clearly that THP was neither enabled nor closed prior to coefficient exchange. The PICS items (16c/16d) also reflect the wording from the second paragraph, i.e. no

mention of THP.

Fixing these issues results in several changes to the text and the base text to remove ambiguity. In addition to introducing several points of textual ambiguity both with the base standard and 802.3az (only 2 of which I've found, but there are likely more), the addition of THP on fast retrain was a technical error in that it decreases performance (up to 50% greater error rate) and introduces extra training steps in most useful cases, where the new target THP is significantly different from the original.

SuggestedRemedy

Replace "keep its THP turned on with the previously exchanged coefficients" with "disabling its THP, as it would be during normal training in this state"

Proposed Response Response Status W

This comment is submitted by Mike Bennett on behalf of George Zimmerman

C/ 55	SC 55.4.2.5.15	P 220	L 53	#	3	
Dove, Daniel		HP - Hewlett-	Packard			
Comment Ty	pe TR	Comment Status X				THP

Comment Type TR Comment Status X

Comment: The first paragraph (lines 53-54) describes what happens when the PHY transmits the link failure signal and explicitly says 'shall....keep its THP turned on with its previously-

exchanged coefficients, and send PAM2 signaling...'; this text was added after the meeting in Geneva.

The second paragraph (top page 221, lines 1-4) describes what happens after the PHY receives the link failure signal only says 'a PHY shall transition to the PMA Coeff Exch state and respond with PAM2 signaling'. No requirement is stated that the PHY 'shall' respond with THP encoded signaling. This second paragraph is in line with unchanged text in the base standard (802.3-2008) 55.4.2.5.14, (bottom of page 497, top of page 498) paragraph beginning with "Following coefficient exchange", states that following coefficient exchange, "THP is enabled ... (and later) "at the closure of the THP loop ... ", indicating clearly that THP was neither enabled nor closed prior to coefficient exchange. The PICS items (16c/16d) also reflect the wording from the second paragraph, i.e. no mention of THP.

Fixing these issues results in several changes to the text and the base text to remove ambiguity. In addition to introducing several points of textual ambiguity both with the base standard and 802.3az (only 2 of which I've found, but there are likely more), the addition of THP on fast retrain was a technical error in that it decreases performance (up to 50% greater error rate) and introduces extra training steps in most useful cases, where the new target THP is significantly different from the original.

SuggestedRemedy

Replace "keep its THP turned on with the previously exchanged coefficients" with "disabling its THP, as it would be during normal training in this state"

Proposed Response Response Status 0

CI 55	SC 55.4	1.5.1	P 2	29	L14	# 2	
Booth, Bra	ad		Appli	ed Micro	(AMCC)		
Comment	Type El	R Con	nment Status	Х			
			the following	note.			
NÕTE fast_r The n	E- For PHYs etrain_flag i ote does no	which do no s set to FALS t relate to the	t support the SE figure, but ra	fast retr ather to	ain capability, the the variable.	e variable	
NÕTE fast_r The n Suggeste	E- For PHYs etrain_flag i ote does no dRemedy	which do no s set to FALS t relate to the	t support the SE figure, but ra	fast retr ather to	ain capability, the	e variable	
NŎTE fast_r The n Suggeste Move	E- For PHYs retrain_flag i tote does no <i>dRemedy</i> the note to	which do no s set to FALS t relate to the be part of the	t support the SE e figure, but ra	fast retr ather to _flag var	ain capability, the the variable. iable description.	e variable	

C/ 55 SC 55.4.5.1 Page 2 of 2 8/2/2010 6:27:16 PM