

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 45 SC 45.2.1.236a.1 P27 L40 # 1

Curran, Philip

ADI

Comment Type T Comment Status A Registers

The note in 45.2.1.236a.3 indicates that the PMA may take many seconds to recover after exiting from reset or low-power mode. However, the note in 45.2.1.236a.1 does not indicate this.

*SuggestedRemedy*

Add following to note in 45.2.1.236a.1 :

"The data path of the 100BASE-T1L PMA, depending on implementation, may take many seconds to run at optimum error ratio after exiting from reset."

Change note in 45.2.1.236a.3 to end in the following:

"... after exiting from low-power mode."

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.1.236b.1 P28 L44 # 2

Curran, Philip

ADI

Comment Type E Comment Status A EZ

There is an additional "a" in "... supports a an increased ...".

*SuggestedRemedy*

Remove the additional "a".

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.1.236b.3 P29 L3 # 3

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The description of how to interpret 1.2301.2 covers the case where it is read as zero first followed by the case where it is read as one.

Table 45-198b lists the allowed values in the opposite order.

*SuggestedRemedy*

Swap the first and second sentences in the paragraph.

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.3.75c P32 L9 # 4

Curran, Philip

ADI

Comment Type E Comment Status A Registers

The following sentence does not make sense here:

"The default value for each bit of the 100BASE-T1L training register should be chosen so that the initial state of the device upon power up or reset is a normal operational state without management intervention."

Every combination of values corresponds to a normal operational state.

Furthermore, the draft should specify how to handle bits that correspond to abilities that are not supported.

*SuggestedRemedy*

Replace this sentence with the following:

"Only bits representing supported abilities can be set. Default values should reflect the supported abilities and the desired operational state in the application. "

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.3.75c P32 L20 # 5

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The EEE advertisement and RS-FEC advertisement bits are shown at bit positions 1 and 0 whereas they should be at bit positions 15 and 14.

*SuggestedRemedy*

Update Table 45-297c as follows:

Move EEE advertisement from 3.2297.1 to 3.2297.15

Move RS-FEC advertisement from 3.2297.0 to 3.2297.14

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 45 SC 45.2.3.75d P32 L40 # 6

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The following sentence is missing a space at "trainingregister":

"All the bits in the 100BASE-T1L link partner trainingregister are read only ...".

*SuggestedRemedy*

Change "trainingregister" to "training register".

Response Response Status C

ACCEPT.

---

CI 190 SC 190.1.3.3 P42 L1 # 7

Curran, Philip

ADI

Comment Type T Comment Status A EEE

The paragraph beginning "When the PHY LPI refresh status received ..." is incorrect. No indication of low SNR is transmitted when the PHY is in the LPI transmit mode. In that scenario the PHY exits the LPI transmit mode and signals low SNR via the auxiliary bit.

*SuggestedRemedy*

Propose to simply delete the paragraph. Outlining the handling of low SNR seems too detailed for the overview.

Response Response Status C

ACCEPT.

---

CI 190 SC 190.2.2 P44 L39 # 8

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The primitive PMA\_REMRXSTATUS has been renamed PMA\_REMFLRRXSTATUS and the parameter rem\_rcvr\_status has been renamed rem\_flr\_rcvr\_status.

*SuggestedRemedy*

Change PMA\_REMRXSTATUS to PMA\_REMFLRRXSTATUS and change rem\_rcvr\_status to rem\_flr\_rcvr\_status.

Response Response Status C

ACCEPT.

---

CI 190 SC 190.2.2 P45 L18 # 9

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Dot missing in "PMA\_REMPHYIDLErequest".

*SuggestedRemedy*

Insert dot.

Response Response Status C

ACCEPT.

---

CI 190 SC 190.2.2 P45 L41 # 10

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The word 'PHY' is misplaced in Figure 190-3. It should be centered on the horizontal double sided arrow.

*SuggestedRemedy*

Update figure.

Response Response Status C

ACCEPT.

---

CI 190 SC 190.2.2.9 P49 L26 # 11

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The heading uses the name PMA\_REMRXSTATUS which has been changed to PMA\_REMFLRRXSTATUS.

*SuggestedRemedy*

Change the heading text to PMA\_REMFLRRXSTATUS.

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.3 P53 L52 # 12

Curran, Philip

ADI

Comment Type T Comment Status A PCS

There is no PCS Data Transmission Enable function. This is handled by the PCS (8N)B/(8N+1)B Transmit state diagram.

**SuggestedRemedy**

Change text to following:

"The PCS sublayer comprises one PCS Reset function and two simultaneous and asynchronous operating functions. The PCS operating functions are PCS Transmit, and PCS Receive. Both operating functions are started immediately after the successful completion of the PCS Reset function."

Response Response Status C

ACCEPT IN PRINCIPLE.

Replace 2nd paragraph of 190.3 with:

"The PCS sublayer comprises one PCS Reset function and two simultaneous and asynchronous operating functions. The PCS operating functions are PCS Transmit and PCS Receive. Both operating functions are started immediately after the successful completion of the PCS Reset function."

CI 190 SC 190.3 P54 L13 # 13

Curran, Philip

ADI

Comment Type E Comment Status A PCS

There is no PCS Data Transmission Enable function. This is handled by the PCS (8N)B/(8N+1)B Transmit state diagram.

**SuggestedRemedy**

Remove PCS Data Transmission Enable block from Figure 190-4.

Response Response Status C

ACCEPT IN PRINCIPLE.

Accomdated by comment 80.

CI 190 SC 190.3.2.4 P60 L15 # 14

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Table 190-2 uses the symbol /Q/ which should be /R/.

**SuggestedRemedy**

Change /Q/ to /R/ in Table 190-2.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.2.4 P60 L16 # 15

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The even transfer category is specified as "IDLIDL".

**SuggestedRemedy**

Change "IDLIDL" to "IDL".

Response Response Status C

ACCEPT.

CI 190 SC 190.3.2.4 P60 L43 # 16

Curran, Philip

ADI

Comment Type T Comment Status A Editorial

The definition associated with the symbol // is "Normal Inter-Frame, loc\_phy\_ready=OK". This is misleading as it suggests that Normal Inter-Frame signaling may also occur when loc\_phy\_read = NOT\_OK. This is not the case.

**SuggestedRemedy**

Change the definition for // to "Normal Inter-Frame"

Response Response Status C

ACCEPT.

CI 190 SC 190.3.2.4 P60 L49 # 17

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The symbol for Assert Remote Fault is incorrectly name /RI/.

**SuggestedRemedy**

Change /RI/ to /R/.

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.3.2.4 P62 L37 # 18

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The indentation of "if TS\_prev:" is incorrect. It should align with the "else:" that follows at line 39.

*SuggestedRemedy*

Fix indentation by adding spaces before the if.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.2.11 P69 L8 # 19

Curran, Philip

ADI

Comment Type E Comment Status A EZ

It would be better to use a fixed width font for the 6-tuples so that the symbols line up correctly.

*SuggestedRemedy*

Change font in Table 190-5.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.2.12 P72 L33, 36 # 20

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The wake time values are 76.8 us and 105.6 us. Currently the values are incorrectly specified to be in seconds.

*SuggestedRemedy*

Change 76.8 s to 76.8 us and change 105.6 s to 105.6 us.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.4.2 P75 L21 # 21

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The abbreviation PFC should be introduced in the text rather than in the figure.

*SuggestedRemedy*

Change "... among the partial frame count, ..." to "... among the partial frame count (PFC), ..."

Response Response Status C

ACCEPT.

CI 190 SC 190.3.4.2 P75 L24 # 22

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The figure incorrectly uses the abbreviation PCS rather than PFC.

*SuggestedRemedy*

Change "Partial Frame Count (PCS)" to "Partial Frame Count (PFC)"

Response Response Status C

ACCEPT.

CI 190 SC 190.3.4.2.4 P77 L29 # 23

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The advertisement register bits are specified incorrectly.

*SuggestedRemedy*

Change "100BASE-T1L advertisement register bits 3.2282.0 and 3.2282.1" to "100BASE-T1L training register bits 3.2297.14 and 3.2297.15".

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.3.4.2.4 P77 L31 # 24

Curran, Philip

ADI

Comment Type E Comment Status A Registers

The link partner advertisement register bits are specified incorrectly.

#### SuggestedRemedy

Change sentence as follows:

"The 100BASE-T1L link partner training register bits 3.2298.14 and 3.2298.15 reflect the PHY capability bits communicated by the link partner through the received InfoField (see 190.3.4.2.4). "

Response Response Status C

ACCEPT IN PRINCIPLE.

(statement is in 190.3.4.2.4 so the reference needs to change)

Change sentence as follows:

"The 100BASE-T1L link partner training register bits 3.2298.14 and 3.2298.15 reflect the PHY capability bits communicated by the link partner through the received InfoField (see Figure 190-7). "

CI 190 SC 190.3.4.3 P78 L26 # 25

Curran, Philip

ADI

Comment Type E Comment Status A EZ

It would be better to use a fixed width font for the 6-tuples so that the symbols line up correctly.

#### SuggestedRemedy

Change font in Table 190-8.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.4.3 P79 L8 # 26

Curran, Philip

ADI

Comment Type T Comment Status A Editorial

The equation for the sign generation during training does not match the adopted proposal.

#### SuggestedRemedy

Modify in accordance with adopted proposal. See slide 13 of Curran\_3dg\_01a\_01202025.pdf from the January meeting in Phoenix.

I am not able to copy the correct equation reliably into this spreadsheet. Please consult the presentation.

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement suggested remedy with editorial license.

(editor's note to review with Philip and Steffen)

CI 190 SC 190.3.5 P79 L34 # 27

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Clause 190 will handle handle all test modes in 190.5.

#### SuggestedRemedy

Remove heading 190.3.5.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.6 P80 L14 # 28

Curran, Philip

ADI

Comment Type T Comment Status A EEE

Figure 190-11 does not match the adopted proposal.

#### SuggestedRemedy

Modify in accordance with adopted proposal. See slide 21 of Curran\_3dg\_01\_05132025.pdf from the May meeting in New Orleans.

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.3.6 P80 L36 # 29

Curran, Philip

ADI

Comment Type T Comment Status A EEE

Table 190-9 does not match the adopted proposal.

**SuggestedRemedy**

Modify in accordance with adopted proposal. See slide 22 of Curran\_3dg\_01\_05132025.pdf from the May meeting in New Orleans.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.6.1 P81 L13 # 30

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Missing "of" in "... at the beginning any multiple ...".

**SuggestedRemedy**

Change to "... at the beginning of any multiple ...".

Response Response Status C

ACCEPT.

CI 190 SC 190.3.6.2 P81 L41 # 31

Curran, Philip

ADI

Comment Type T Comment Status A EEE

The sentence describing quiet period signaling does not match the adopted proposal.

**SuggestedRemedy**

Change the sentence:

"During quiet periods, the PCS transmitter passes zero data encoded symbols to the PMA via the PMA\_UNITDATA.request primitive."

to the following:

"During the quiet period the PCS transmitter shall pass zeros to the PMA via the PMA\_UNITDATA.request primitive."

Response Response Status C

ACCEPT.

CI 190 SC 190.3.7.1.2 P83 L31, 39 # 32

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The definition of rx\_char and tx\_coded refer to "(8N)B/(8N+1)B". Elsewhere the + symbol is preceded by and followed by spaces.

**SuggestedRemedy**

Change to "(8N)B/(8N + 1)B".

Response Response Status C

ACCEPT.

CI 22 SC 22.2.2.4 P23 L1 # 33

Curran, Philip

ADI

Comment Type E Comment Status A Editorial

Although the editor's note states it is a placeholder, I do not think there has been any adopted proposal to add a link-fault signaling state diagram in Clause 22

**SuggestedRemedy**

Remove

Response Response Status C

ACCEPT IN PRINCIPLE.

Accommodated by comment 107

ACCEPT IN PRINCIPLE.

Delete editor's note at P22 L31 and placeholder figure 22-1 on P23 L1 through 27

CI 190 SC 190.3.7.1.2 P84 L12 # 34

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Typo at "whether to SNR".

**SuggestedRemedy**

Change to "whether the SNR".

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 190 SC 190.3.7.1.2 P84 L17 # 35

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The ".request" is missing in the name of the primitive with base name "PMA\_PCS\_RX\_LPI\_STATUS".

SuggestedRemedy

Add ".request".

Response Response Status C

ACCEPT.

---

CI 190 SC 190.3.7.1.2 P84 L43 # 36

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Alert signaling is not listed in the text "sleep, quiet-refresh, or wake signaling".

SuggestedRemedy

Change to "sleep, quiet-refresh, alert, or wake signaling".

Response Response Status C

ACCEPT.

---

CI 190 SC 190.3.7.1.2 P85 L22 # 37

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Typo in the variable name "rf\_valide".

SuggestedRemedy

Change to "rf\_valid".

Response Response Status C

ACCEPT.

---

CI 190 SC 190.3.7.1.5 P86 L15 # 38

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The draft indicates that the counters rfer\_cnt and rfrx\_cnt are required when EEE is enabled for the link. This is incorrect. These counters are required when RS-FEC is enabled for the link.

SuggestedRemedy

Insert the following before line 15 (before the definition of rfer\_cnt):

"The following counters are required when RS-FEC is enabled for the link."

A knock-on effect is that at line 10 the word "counters" needs to change to "counter".

Response Response Status C

ACCEPT.

---

CI 190 SC 190.3.7.2 P87 L39 # 39

Curran, Philip

ADI

Comment Type T Comment Status A EZ

Exit condition from TX\_WAKE to TX\_MII is incorrectly shown as "tx\_lpi\_active".

SuggestedRemedy

Change condition to "!tx\_lpi\_active".

Response Response Status C

ACCEPT.

---

CI 190 SC 190.4.8.2 P97 L20 # 40

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Missing opening parenthesis at "wt)" in equation 190-8.

SuggestedRemedy

Change to "w(t)".

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 00	SC 0	P99	L15	# 41
-------	------	-----	-----	------

Curran, Philip ADI

Comment Type E Comment Status A EEE

The variable lpi\_refresh\_detect is not defined.

**SuggestedRemedy**

Add the following after line 15:

"The following variable is required when EEE is enabled for the link:

lpi\_refresh\_detect  
Set TRUE when the receiver has reliably detected refresh signaling. It is set FALSE otherwise."

Response Response Status C

ACCEPT.

CI 00	SC 0	P100	L1	# 42
-------	------	------	----	------

Curran, Philip ADI

Comment Type E Comment Status A Editorial

The PMA state diagrams are currently in 190.4.9.3 which is a sub-clause of "190.4.9 State variables". This hierarchy does not seem to make sense.

**SuggestedRemedy**

Modify PMA state diagram hierarchy to match that of the PCS as follows:

190.4.9 Detailed functions and state diagrams  
190.4.9.1 State diagrams parameters  
190.4.9.1.1 Variables  
190.4.9.1.2 Timers  
190.4.9.2 State diagrams

Response Response Status C

ACCEPT.

CI 00	SC 0	P101	L17	# 43
-------	------	------	-----	------

Curran, Philip ADI

Comment Type E Comment Status A EZ

Typo at "FLASE" in SEND\_IDLE\_NOT\_READY state actions.

**SuggestedRemedy**

Change to "FALSE".

Response Response Status C

ACCEPT.

CI 00	SC 0	P101	L20	# 44
-------	------	------	-----	------

Curran, Philip ADI

Comment Type T Comment Status A PHY Control

The transition from SEND\_IDLE\_NOT\_READY to LINK\_FAIL looks like a bad idea. This is the state where the transmit signal switches from PAM2 to PAM3. It is conceivable that there could be a short period after the transition where SNR drops.

There is also no advantage in moving to LINK\_FAIL versus remaining in SEND\_IDLE\_NOT\_READY. In either case the PHY will end up waiting for the link\_fail\_inhibit\_timer to expire in the event that something has gone wrong.

**SuggestedRemedy**

Remove transition from SEND\_IDLE\_NOT\_READY to LINK\_FAIL.

Response Response Status C

ACCEPT.

CI 00	SC 0	P101	L26	# 45
-------	------	------	-----	------

Curran, Philip ADI

Comment Type T Comment Status A PHY Control

The transition from PAM3\_TUNING to LINK\_FAIL looks like a bad idea. This is the state where the receive signal switches from PAM2 to PAM3. It is conceivable that there could be a short period after the transition where SNR drops. The whole point of the PAM3\_TUNING state is to allow for this possibility.

There is also no advantage in moving to LINK\_FAIL versus remaining in PAM3\_TUNING. In either case the PHY will end up waiting for the link\_fail\_inhibit\_timer to expire in the event that something has gone wrong.

**SuggestedRemedy**

Remove transition from PAM3\_TUNING to LINK\_FAIL.

Response Response Status C

ACCEPT.



## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 00 SC 0 P96 L9 # 46

Curran, Philip

ADI

Comment Type T Comment Status A PHY Control

In relation to the previous 2 comments, it seems that there may be a misapprehension that moving to the LINK\_FAIL state immediately causes AN to restart. In fact there is no way for a PHY to cause AN to restart while the link is coming up. The PHY must just wait for the link\_fail\_inhibit\_timer to expire.

I think we should change the text "... PHY Control returns to the LINK\_FAIL state and Auto-Negotiation restarts" to make this clear.

#### SuggestedRemedy

Change to following:

"... PHY Control returns to the LINK\_FAIL state and waits for the link\_fail\_inhibit\_timer to expire and Auto-Negotiation to restart."

Response Response Status C

ACCEPT.

CI 00 SC 0 P49 L38 # 47

Curran, Philip

ADI

Comment Type E Comment Status A EZ

The text is still referring to the old rem\_rcvr\_status parameter name

#### SuggestedRemedy

Change the text to "The rem\_flr\_rcvr\_status parameter ..."

Response Response Status C

ACCEPT.

CI 00 SC 0 P54 L30 # 48

Curran, Philip

ADI

Comment Type E Comment Status A EZ

rem\_rcvr\_status has been renamed rem\_flr\_rcvr\_status, eee\_low\_snr is missing

#### SuggestedRemedy

Rename rem\_rcvr\_status to rem\_flr\_rcvr\_status, add eee\_low\_snr (arrows going to both receive and transmit)

Response Response Status C

ACCEPT.

CI 00 SC 0 P54 L49,50 # 49

Curran, Philip

ADI

Comment Type T Comment Status A Editorial

The paragraph "The control and management interface shall be restored to operation within 10 ms from setting of bit 3.2295.15" should be removed. That is already defined in Clause 45.2.3.75a.1, where the defined time is 0.5 s, which is in contradiction with the value in this paragraph.

#### SuggestedRemedy

Remove this paragraph to avoid inconsistencies with the definition in 45.2.3.75a.1

Response Response Status C

ACCEPT.

CI 00 SC 0 P55 L6 # 50

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Reference to Figure 190-11 is incorrect. I believe it should be Figure 190-12

#### SuggestedRemedy

Change text to "... Figure 190-12", also make it an active cross reference.

Response Response Status C

ACCEPT.

CI 00 SC 0 P55 L29 # 51

Curran, Philip

ADI

Comment Type E Comment Status A EZ

Reference to 190.5.3.6, although not already specified, looks incorrect. It will likely be 190.5.4.x (x TBD).

#### SuggestedRemedy

Change text to "... specified in 190.5.4.x"

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 00	SC 0	P58	L36	# 52
-------	------	-----	-----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

Table 190-1 header shows tx\_enable and tx\_error which are not defined.

*SuggestedRemedy*

Rename "tx\_enable" and "tx\_error" column headers in Table 190-1 to "TX\_EN" and "TX\_ER" respectively.

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P60	L20	# 53
-------	------	-----	-----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	Editorial
--------------	---	----------------	---	-----------

TS is '—', and should be 1.

*SuggestedRemedy*

Change the value of TS from — to 1. Alternatively TS could be defined as:  
!(!(Previous transfer = 1)\*(Odd transfer = DAT)\*(Even transfer = DAT)\*(dly\_enc = TRUE))  
and removed from the table

Response	Response Status	C
----------	-----------------	---

ACCEPT IN PRINCIPLE.

Change the value of TS from — to 1.

---

CI 00	SC 0	P71	L42	# 54
-------	------	-----	-----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

Reference to Table 190-10 is incorrect, it should be Table 190-9

*SuggestedRemedy*

Change text to "Table 190-9"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P72	L4	# 55
-------	------	-----	----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

Reference to 190.3.7 is incorrect, it should be 190.3.6

*SuggestedRemedy*

Change text to "as decribed in 190.3.6"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P77	L40	# 56
-------	------	-----	-----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

"The CRC16 polynomial (x + 1)(x<sup>15</sup> + x + 1) " should use superscripts for the exponents*SuggestedRemedy*

NOTE: Scripts may not show up correctly in Excel online. Change the text to "The CRC16 polynomial (x + 1)(x<sup>15</sup> + x + 1)"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P81	L48	# 57
-------	------	-----	-----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

I think the sentence "...setting all of the bits of each transmit octet, Tx<sub>bn</sub><0:7>, which is shown in figure 190-5 to zero" would be clearer with a comma before "to zero"

*SuggestedRemedy*

Change the text to "..., which is shown in Figure 190-5, to zero"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 00	SC 0	P82	L46, 49	# 58
-------	------	-----	---------	------

---

Curran, Philip

ADI

Comment Type	T	Comment Status	A	EZ
--------------	---	----------------	---	----

IDL\_R is defined as "The set of characters that may occur between packets", and PKT\_R as "The set of characters that may occur within a packet". Strictly that is not correct. /Tp/ occurs between packets, and /Sp/, /Su/ and /Tu/ can occur within a packet.

*SuggestedRemedy*

Remove line 46 in page 82 "The set of characters that may occur between packets".  
In page 82, line 49, remove text "The set of characters that may occur within a packet"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P83	L41	# 59
-------	------	-----	-----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

tx\_mii<2N - 1><0:5> should be tx\_mii<0:(2N - 1)><0:5>

*SuggestedRemedy*

Change the variable name to "tx\_mii<0:(2N - 1)><0:5>"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P85	L8	# 60
-------	------	-----	----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

The reference to 190.3.2.11 is incorrect

*SuggestedRemedy*

Change text to "described in 190.3.2.12"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P92	L16 (17?	# 61
-------	------	-----	----------	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

The reference to Figure 190-14 is incorrect

*SuggestedRemedy*

Change text to "Figure 190-17"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P93	L1	# 62
-------	------	-----	----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

rem\_rcvr\_status has been renamed rem\_flr\_rcvr\_status, eee\_low\_snr is missing

*SuggestedRemedy*

Rename rem\_rcvr\_status to rem\_flr\_rcvr\_status, add eee\_low\_snr in Figure 190-17

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 00	SC 0	P95	L52	# 63
-------	------	-----	-----	------

---

Curran, Philip

ADI

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

rem\_rcvr\_status has been renamed rem\_flr\_rcvr\_status

*SuggestedRemedy*

Change text to "When the Leader  
PHY has trained its receiver and has detected rem\_flr\_rcvr\_status = OK"

Response	Response Status	C
----------	-----------------	---

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 00 SC 0 P31 L5 # 64

Curran, Philip

ADI

Comment Type T Comment Status A Registers

The paragraph "The control and management interface shall be restored to operation within 0.5 s from setting of bit 3.2295.15" should be changed to 10 ms. The "control and management interface" is used in many places in this clause, although it is not defined, and the Clause title is "Management Data Input/Output (MDIO) interface". It may be considered to rephrase the paragraph.

#### SuggestedRemedy

Change the text to "The control and management interface shall be restored to operation within 10 ms from setting of bit 3.2295.15".  
Alternatively could rephrase it to "The reset process should complete within 10 ms from setting of bit 3.2295.15" or "The MDIO interface shall be restored to operation within 10 ms from setting of bit 3.2295.15"

Response Response Status C

ACCEPT IN PRINCIPLE.

Change text to "The MDIO interface or its equivalent for accessing control and status bits shall be restored to operation within 10 ms from setting of bit 3.2295.15"

CI 00 SC 0 P57/58 L47/9,10 # 65

Curran, Philip

ADI

Comment Type E Comment Status A Editorial

The sentence "For values shown as binary, the leftmost bit is the first bit transmitted" may be misleading since the TXD<3:0> values shown subsequently in other subclauses with the MSB (TXD<3>) as the leftmost bit, while according to clause 22, TXD<0> is transmitted first. Since, other than that, binary values are not used in Clause 190, that sentence would better be removed.

#### SuggestedRemedy

Remove line 47 in page 57: "For values shown as binary, the leftmost bit is the first transmitted bit". Also remove the last sentence in page 58 lines 9-10 "Binary values are shown with the first transmitted bit (the LSB) on the left".

Response Response Status C

ACCEPT.

CI Keywor SC Keywords P3 L5 # 66

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

Please remove one of the two commas after "Ethernet" and also keywords "Physical Layer Collision Avoidance" and "PLCA" should be removed, as these are not used within this standard.

#### SuggestedRemedy

As per comment.

Response Response Status C

ACCEPT.

CI 1 SC 1.4 P20 L35 # 67

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

"a octet" should read as "an octet".

#### SuggestedRemedy

As per comment.

Response Response Status C

ACCEPT.

CI 45 SC 45.2.1.16.1aa P26 L37 # 68

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

Bit 1.18.8 has been changed to bit 1.18.9 (as 802.3da has already reserved bit 1.18.8).

#### SuggestedRemedy

Change Bit 1.18.8 to 1.18.9 in headline and following paragraph (in total 3 replacements).  
Modify also editing instruction to reflect changed by IEEE802.3da project.

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 45 SC 45.2.1.236b P28 L39 # 69

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

" , LH = Latching high" is not needed anymore.

SuggestedRemedy

Remove " , LH = Latching high".

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.1.236b.1 P44 L44 # 70

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

In "supports a an increased" the "a" is too much.

SuggestedRemedy

Change to: "supports an increased".

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.3 P30 L19 # 71

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

"100BASE-T1L Advertisement" register is now named "100BASE-T1L training" register.  
"100BASE-T1L Link partner advertisement" register is now "100BASE-T1L link partner training" resister.

SuggestedRemedy

Change from "100BASE-T1L Advertisement" to "100BASE-T1L training". Change from  
"100BASE-T1L Link partner advertisement" to "100BASE-T1L link partner training".

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.3.75b P31 L33 # 72

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

"RS-FEC ability" bit should not be latching high, only read-only.

SuggestedRemedy

Change "RO/LH" to "RO" and remove "LH = Latching high, " from text line below table.

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.3.75d P32 L41 # 73

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

"100BASE-T1L link partner trainingregister" should read as "100BASE-T1L link partner training register". Additionally in line 45 the "l" in "link partner" is missing.

SuggestedRemedy

Change "100BASE-T1L link partner trainingregister" to "100BASE-T1L link partner training register" and add missing "l" in "link partner" in line 45.

Response Response Status C

ACCEPT.

---

CI 45 SC 45.2.3.75d P33 L8 # 74

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

Bits 0 and 1 are also reserved.

SuggestedRemedy

Change "3.2298.13:2" to "3.2298.13:0".

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 190	SC 190.2.2	P44	L39	# 75
--------	------------	-----	-----	------

---

Graber, Steffen

Pepperl+Fuchs SE

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

"PMA\_REMRXSTATUS.request" should be "PMA\_REMFLRRXSTATUS.request".

*SuggestedRemedy*

Change "PMA\_REMRXSTATUS.request" to "PMA\_REMFLRRXSTATUS.request". Change also heading of clause 190.2.2.9 accordingly.

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 190	SC 190.2.2	P45	L18	# 76
--------	------------	-----	-----	------

---

Graber, Steffen

Pepperl+Fuchs SE

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

"PMA\_REMPHYIDLErequest" should be "PMA\_REMPHYIDLE.request".

*SuggestedRemedy*

Change "PMA\_REMPHYIDLErequest" to "PMA\_REMPHYIDLE.request".

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 190	SC 190.2.2.9.1	P49	L38	# 77
--------	----------------	-----	-----	------

---

Graber, Steffen

Pepperl+Fuchs SE

Comment Type	E	Comment Status	A	EZ
--------------	---	----------------	---	----

"rem\_rcvr\_status" should be "rem\_flr\_rcvr\_status".

*SuggestedRemedy*

Change "rem\_rcvr\_status" to "rem\_flr\_rcvr\_status".

Response	Response Status	C
----------	-----------------	---

ACCEPT.

---

CI 190	SC 190.2.2.16	P52	L54	# 78
--------	---------------	-----	-----	------

---

Graber, Steffen

Pepperl+Fuchs SE

Comment Type	E	Comment Status	A	EEE
--------------	---	----------------	---	-----

Needs to be clarified/corrected, which function generates the primitive and which functions receive it.

*SuggestedRemedy*

Change from: "The parameter PMA\_PCS\_TX\_LPI\_STATUS.request conveys to the PCS Transmit and PMA Receive functions information regarding whether the transmit function is in the LPI transmit mode." to: "The parameter PMA\_PCS\_TX\_LPI\_STATUS.request conveys to the PMA Transmit and PMA Receive functions information regarding whether the PCS transmit function is in the LPI transmit mode."

Response	Response Status	C
----------	-----------------	---

ACCEPT IN PRINCIPLE.

(suggested remedy plus correcting the mis-identification of PMA\_PCS\_TX\_LPI\_STATUS.request as a "parameter").

Change from: "The parameter PMA\_PCS\_TX\_LPI\_STATUS.request conveys to the PCS Transmit and PMA Receive functions information regarding whether the transmit function is in the LPI transmit mode."

to: "The primitive PMA\_PCS\_TX\_LPI\_STATUS.request conveys to the PMA Transmit and PMA Receive functions information regarding whether the PCS transmit function is in the LPI transmit mode."

---

CI 190	SC 190.3	P54	L8	# 79
--------	----------	-----	----	------

---

Graber, Steffen

Pepperl+Fuchs SE

Comment Type	T	Comment Status	A	EEE
--------------	---	----------------	---	-----

In figure 190-4 and also figure 190-17 the (dashed) arrow lines indicating eee\_low\_snr from PMA Receive function to PCS Transmit and PCS Receive function (across the PMA/PCS interface) is missing.

*SuggestedRemedy*

Add indication from PMA Receive function to PCS Transmit and PCS Receive functions in figures 190-4 and 190-17.

Response	Response Status	C
----------	-----------------	---

ACCEPT IN PRINCIPLE.

Accommodated by comment 48 & 62

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

---

CI 190	SC 190.3	P54	L 8	# 80
--------	----------	-----	-----	------

---

Graber, Steffen                      Pepperl+Fuchs SE

Comment Type    **T**                      Comment Status    **A**                      PCS

PCS Data Transmission Enable function has been integrated in PCS Transmit function.

*SuggestedRemedy*

Remove block "PCS Data Transmission Enable" from figure 190-4 and connect TX\_ER and TX\_EN directly with the PCS Transmit function block.

*Response*                      Response Status    **C**

ACCEPT IN PRINCIPLE.

Remove block "PCS Data Transmission Enable" from figure 190-4 and connect TX\_ER and TX\_EN directly with the PCS Transmit function block.

Realign existing blocks with editorial license

---

CI 190	SC 190.3	P54	L 30	# 81
--------	----------	-----	------	------

---

Graber, Steffen                      Pepperl+Fuchs SE

Comment Type    **E**                      Comment Status    **A**                      EZ

"rem\_rcvr\_status" has been changed to "rem\_flr\_rcvr\_status".

*SuggestedRemedy*

Change "rem\_rcvr\_status" to "rem\_flr\_rcvr\_status". Do the same in figure 190-17.

*Response*                      Response Status    **C**

ACCEPT.

---

CI 190	SC 190.3.2	P55	L 6	# 82
--------	------------	-----	-----	------

---

Graber, Steffen                      Pepperl+Fuchs SE

Comment Type    **E**                      Comment Status    **A**                      EZ

The Transmit State Diagram should be referenced.

*SuggestedRemedy*

Change "Figure 190-11" to "Figure 190-12".

*Response*                      Response Status    **C**

ACCEPT.

---

CI 190	SC 190.3.2.4	P58	L 36	# 83
--------	--------------	-----	------	------

---

Graber, Steffen                      Pepperl+Fuchs SE

Comment Type    **E**                      Comment Status    **A**                      PCS

The PCS Data Transmission Enable State diagram has been removed. Thus variables tx\_enable and tx\_error are no more generated.

*SuggestedRemedy*

In Table 190-1 change "tx\_enable" to "TX\_EN" and "tx\_error" to "TX\_ER".

*Response*                      Response Status    **C**

ACCEPT.

---

CI 190	SC 190.3.2.4	P60	L 16	# 84
--------	--------------	-----	------	------

---

Graber, Steffen                      Pepperl+Fuchs SE

Comment Type    **E**                      Comment Status    **A**                      EZ

"IDL" is doubled.

*SuggestedRemedy*

Change "IDLIDL" to "IDL".

*Response*                      Response Status    **C**

ACCEPT.

---

CI 190	SC 190.3.2.12	P71	L 41	# 85
--------	---------------	-----	------	------

---

Graber, Steffen                      Pepperl+Fuchs SE

Comment Type    **E**                      Comment Status    **A**                      EZ

"." after "Table 190–10" is missing.

*SuggestedRemedy*

Add dot at the end of the sentence. Also add a dot at the end of the sentence on page 72, line 12.

*Response*                      Response Status    **C**

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.3.2.12 P72 L33 # 86

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A EEE

32 partial frame counts is  $32 * 2.4 \mu s = 76.8 \mu s$ , 44 partial frame counts is  $105.6 \mu s$ .

*SuggestedRemedy*

Change "76.8s" to "76.8  $\mu s$ " and "105.6s" to "105.6  $\mu s$ ".

Response Response Status C

ACCEPT IN PRINCIPLE.

Accomdated by comment 20

CI 190 SC 190.3.3 P72 L42 # 87

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

The Receive state diagram is split into Figure 190-14 and Figure 190-15.

*SuggestedRemedy*

Change "Figure 190-14" to "Figure 190-14 and Figure 190-15".

Response Response Status C

ACCEPT.

CI 190 SC 190.4 P92 L16 # 88

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

The PMA Reference diagram is figure 190-17.

*SuggestedRemedy*

Change reference from figure 190-14 to 190-17.

Response Response Status C

ACCEPT.

CI 190 SC 190.4 P92 L18 # 89

Graber, Steffen

Pepperl+Fuchs SE

Comment Type T Comment Status A Editorial

As the "Refresh monitor block" is incorporated in the PMA Receive function, no separate Refresh monitor block is required.

*SuggestedRemedy*

Remove "Refresh Monitor, " in line 11 on page 92 and also the associated Editor's note in line 18.

Response Response Status C

ACCEPT.

CI 190 SC 190.4.4.1 P95 L21 # 90

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A Registers

The "receive fault" bit has been removed.

*SuggestedRemedy*

Remove sentence "Mapping of MDIO status variables to PMA status variables is shown in Table 190-13." and table 190-13.

Response Response Status C

ACCEPT.

CI 190 SC 190.4.8.2 P97 L20 # 91

Graber, Steffen

Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

Should read as "+ w(t)".

*SuggestedRemedy*

Change "+ wt)" to "+ w(t)"

Response Response Status C

ACCEPT.



## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.4.9.1 P98 L36 # 92

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

"rem\_rcvr\_status" has been renamed to "rem\_flr\_rcvr\_status". "PMA\_REMRXSTATUS" has been renamed to "PMA\_REMFLRRXSTATUS".

SuggestedRemedy

Change "rem\_rcvr\_status" to "rem\_flr\_rcvr\_status". Change "PMA\_REMRXSTATUS.request" to "PMA\_REMFLRRXSTATUS.request".

Response Response Status C

ACCEPT.

CI 190 SC 190.4.9.3 P101 L19 # 93

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A PHY Control

Last interim, it has been suggested to add an exit condition to "LINK\_FAIL" from both "SEND\_IDLE\_NOT\_READY" and "PAM3\_TUNING" state. During the following discussion, the outcome has been, that this should not be implemented, as there is a risk, that for a short time the local receiver status could become unstable, when switching from PAM2 to PAM3 modulation. Adding the two exit conditions would result in a risk, that the link startup sequence fails. As Auto-Negotiation is mandatory, in case the PHY control state machine would get stuck in one of these states, the AN state machine would restart the PHY and thus reset the PHY control state machine.

SuggestedRemedy

Please remove exit condition to "LINK\_FAIL" from "SEND\_IDLE\_NOT\_READY" state and "PAM3\_TUNING" state.

Response Response Status C

ACCEPT IN PRINCIPLE.

Accommodated by comments 44 and 45

CI 190 SC 190.7.2.1 P108 L14 # 94

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A Editorial

The IL20MHz is in dB, thus the "dB" unit needs to be removed in the following lines.

SuggestedRemedy

Change to: "IL20MHz < 16", "16 <= IL20MHz < 18", "18 <= IL20MHz < 21", "21 <= IL20MHz < 23" and "IL20MHz >= 23" (remove "dB"). Do the same on page 109, line 15ff and add "in dB" at the end of line 13 (after "20 MHz").

Response Response Status C

ACCEPT IN PRINCIPLE.

With editorial license to check for consistency (with 802.3 and between pages 108 & 109), and catch any missed "dB" instances

CI 190 SC 190.3.4.2 P76 L18 # 95

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

Closing bracket at the end of the line should be a normal bracket.

SuggestedRemedy

Change "]" to ")" at the end of the line. Do this also in lines 23 and 30.

Response Response Status C

ACCEPT.

CI 190 SC 190.3.6 P79 L46 # 96

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

Should be singular.

SuggestedRemedy

Change "use" to "uses".

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.3.6 P80 L31 # 97  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 Table 190-9 is referenced on page 79, line 47.  
 SuggestedRemedy  
 Remove editorial note.  
 Response Response Status C  
 ACCEPT.

CI 190 SC 190.3.6.1 P81 L12 # 98  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 "of" is missing.  
 SuggestedRemedy  
 Change "... beginning any ..." to "... beginning of any ...". Do the same in line 13.  
 Response Response Status C  
 ACCEPT.

CI 190 SC 190.3.6.1 P81 L # 99  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 "tx\_refresh\_active=true" should be "tx\_refresh\_active = true" to align with the following lines (2 spaces added).  
 SuggestedRemedy  
 Change "tx\_refresh\_active=true" to "tx\_refresh\_active = true". Do the same in table 190-11.  
 Response Response Status C  
 ACCEPT.

CI 190 SC 190.3.7.1.2 P83 L41 # 100  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 In "tx\_mii<2N - 1><0:5>" the lower boundary in the first array dimension is missing.  
 SuggestedRemedy  
 Change "tx\_mii<2N - 1><0:5>" to "tx\_mii<0:(2N - 1)><0:5>".  
 Response Response Status C  
 ACCEPT.

CI 190 SC 190.3.7.1.2 P84 L3 # 101  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 RX\_LPI and RX\_ALERT states are shown in Figure 190-15.  
 SuggestedRemedy  
 Change Figure 190-14 to Figure 190-15. Do the same for the reference on page 86, line 28.  
 Response Response Status C  
 ACCEPT.

CI 190 SC 190.3.7.1.2 P84 L12 # 102  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 The SNR of the remote PHY is meant.  
 SuggestedRemedy  
 Change "to SNR" to "the SNR".  
 Response Response Status C  
 ACCEPT.

CI 190 SC 190.3.7.1.2 P85 L22 # 103  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 "rf\_valid" variable name is used in state machines.  
 SuggestedRemedy  
 Change "rf\_valide" to "rf\_valid".  
 Response Response Status C  
 ACCEPT.

CI 190 SC 190.3.7.2 P89 L1 # 104  
 Graber, Steffen Pepperl+Fuchs SE  
 Comment Type E Comment Status A EZ  
 The Receive state diagram is split into Figure 190-14 and Figure 190-15.  
 SuggestedRemedy  
 Change "Figure 190-14" to "Figure 190-14 and Figure 190-15".  
 Response Response Status C  
 ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190 SC 190.3.7.2 P89 L 22 # 105

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

"PKT R" should be "PKT\_R". "x\_char" (see line 27) should be "rx\_char".

**SuggestedRemedy**

Change "PKT R" to "PKT\_R" (line 22). Change "x\_char" to "rx\_char" (line 27).

Response Response Status C

ACCEPT.

CI 190 SC 190.3.7.2 P91 L 28 # 106

Graber, Steffen Pepperl+Fuchs SE

Comment Type E Comment Status A EZ

"rxrx\_cnt" should be "rfrx\_cnt".

**SuggestedRemedy**

Change "rxrx\_cnt" to "rfrx\_cnt". Apply the same change to line 31.

Response Response Status C

ACCEPT.

CI 22 SC 22.2.2.4 P22 L 31 # 107

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type E Comment Status A Link Fault

The link fault state diagram in clause 46 appears to be necessary specifically to manage the sequence ordered sets. The use in clause 22 is different and doesn't use sequence ordered sets, so I don't believe a signaling state diagram is needed.

**SuggestedRemedy**

Delete editor's note at P22 L31

Response Response Status C

ACCEPT IN PRINCIPLE.

Delete editor's note at P22 L31 and placeholder figure 22-1 on P23 L1 through 27

CI 30 SC 30 P24 L 2 # 108

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type T Comment Status A Management

Content is needed for clause 30. Specifically add 100BASE-T1L to: 30.3.2.1.2 aPhyType, 30.3.2.1.3 aPhyTypeList, 30.5.1.1.2 aMAUType, description in 30.5.1.1.4 aMediaAvailable and 30.6.1.1.5 aAutoNegLocalTechnologyAbility

**SuggestedRemedy**

Add the following to the draft:

30.3.2.1.2 aPHYType

Insert the following new entries in the APPROPRIATE SYNTAX section of 30.3.2.1.2 after the entry for 100BASE-T1:

100BASE-T1L Clause 190 100 Mb/s PAM3

30.3.2.1.3 aPhyTypeList

Insert the following new entries in the APPROPRIATE SYNTAX section of 30.3.2.1.3 after the entry for 100BASE-T1:

100BASE-T1L Clause 190 100 Mb/s PAM3

30.5.1.1.2 aMAUType

Insert the following new entries in the APPROPRIATE SYNTAX section of 30.4.1.1.2 after the entry for 100BASE-T1:

100BASE-T1L Single balanced pair PHY as specified in Clause 190

30.5.1.1.4 aMediaAvailable

Change the fourth sentence of the third paragraph of the BEHAVIOUR DEFINED AS section of 30.5.1.1.4 as shown:

For 10BASE-T1L</UL>, 100BASE-T1L,</UL> and 100BASE-T1, a link\_status of OK maps to the enumeration "available".

(where </UL> indicates where underline begins and ends)

30.6.1.1.5 aAutoNegLocalTechnologyAbility

Insert the following new entries in APPROPRIATE SYNTAX section of 30.6.1.1.5 after the entry for "10BASE-TFD":

100BASE-T1L 100BASE-T1L as specified in Clause 190

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 78 SC 78.1.4 P35 L6 # 109

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type T Comment Status A EEE

need entries in clause 78 for 100BASE-T1L

#### SuggestedRemedy

Add the following at P35 L6, after 78.1.4 header:

Insert the following new row after the 100BASE-T1 row in Table 78-1 (unchanged rows not shown)

(insert table 78-1 -Clauses associated with each PHY or interface type to draft, with header row (as below), and one row shown:

PHY or interface type	Clause
100BASE-T1L	190

Response Response Status C

ACCEPT.

CI 78 SC 78.2 P35 L7 # 110

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type T Comment Status A EEE

need to add placeholders for additional needed parameters for EEE in table 78-2.

#### SuggestedRemedy

Add 78.2 LPI mode timing parameters description to the draft, with editing instruction (and editorial license to fill out the headers, min & max values, as indicated below):

Insert the following new row in Table 78-2, after the row for 10BASE-T1L (unchanged rows not shown):

PHY or interface type	T_s	T_q	T_r
100BASE-T1L	19.2	211.2	19.2

(implementation note, not to be included in the draft - full headers not shown in the comment, min & max times are equal, so the comment doesn't repeat them, but editorial license to populate and format the row per IEEE Std 802.3-2022)

Response Response Status C

ACCEPT IN PRINCIPLE.

Suggested remedy with editorial license.

CI 78 SC 78.2 P35 L8 # 111

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type E Comment Status A EEE

need to add placeholder for needed content in Table 78-4

#### SuggestedRemedy

Add

78.5 Communication link access latency

to the draft, with editing instruction ,

"Insert the following new row in Table 78-4 after row for 10BASE-T1L (unchanged rows not shown):"

add Table 78-4 - Summary of LPI timing parameters for supported PHYs or interfaces to the draft, with header row, and one row for 100BASE-T1L (in PHY or interface type column), and the remaining columns blank.

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement Suggested remedy, adding:

Insert 10th paragraph of 78.5 as follows:

Case-1 of the PHY for 100BASE-T1L applies when the PHY is requested to transmit the Wake signal before transmission of the Sleep signal to the Link Partner is complete. Case-2 of the PHY for 100BASE-T1L applies when the PHY is requested to transmit the Wake signal after transmission of the Sleep signal to the Link Partner is complete.

Show Case-1 and Case-2 (split row for 100BASE-T1L)

Editor's license to conform to style and format of the table  
[REVISIT]

CI 98 SC 98.2 P36 L4 # 112

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type T Comment Status A AutoNeg

need to specify which mode 100BASE-T1L shall use. Suggest using LSM to align with distance and likely pairing with 10BASE-T1L in multimode PHYs

#### SuggestedRemedy

Add the following to the draft, after 98.2 (where </UL> indicates start or stop of underline)

98.2.1 Transmit function requirements

Change the 3rd and 4th sentences of the last paragraph of 98.2.1 as shown:

For link segments with high insertion loss and those requiring 10BASE-T1L</UL> or

100BASE-T1L</UL>, LSM is provided to enable the full reach capability. If Auto-

Negotiation is implemented, 10BASE-T1L </UL>and 100BASE-T1L </UL>PHYs shall

support LSM and may optionally support HSM.

Response Response Status C

ACCEPT.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 98 SC 98.5.1 P36 L5 # 113

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type T Comment Status A AutoNeg

need to add 100BASE-T1L low power register bit to state diagram definition of "power\_on"  
Note, this really needs maintenance so we don't have to call out all the PHYs - but that's outside our scope. MultiGBASE-T1 PHYs are missing here....

#### SuggestedRemedy

Add the following to the draft after 98.2 (and any subclauses added by other comments):  
98.5 Detailed functions and state diagrams  
98.5.1 State diagram variables  
Change the variable power\_on as shown:  
power\_on  
Condition that is true until such time as the power supply for the device that contains the Auto-Negotiation state diagrams has reached the operating region or the device has low-power mode  
set via 1000BASE-T1 PMA control register bit 1.2304.11</UL>, the 100BASE-T1L PMA control register bit 1.2300.11,</UL> or via 10BASE-T1L PMA control register bit 1.2294.11.  
Values:  
false: the device is completely powered (default)  
true: the device has not been completely powered

Response Response Status C

ACCEPT.

CI 104 SC 104 P37 L4 # 114

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type T Comment Status A Power

Need clause 104 content. Suggest that a new PoDL Type be defined to go with 100BASE-T1L, as the coupling frequencies and MDI return loss will likely be different than for 100BASE-T1 or 10BASE-T1L. Suggest that ripple voltage measurement requirements for Types A & C (100BASE-T1) should be sufficient for 100BASE-T1L.

#### SuggestedRemedy

Add (with editorial license to align with clause 104 and editing instruction style):  
104.1.3 PoDL system types  
Insert the following after the last sentence of the second paragraph of 104.1.3 (as part of the same paragraph):  
A Type G PSE and Type G PD are compatible with 100BASE-T1L PHYs.

#### 104.4 Power Sourcing Equipment (PSE)

##### 104.4.1 PSE types

Change 104.4.1 as shown:

For PoDL systems there are multiple types of PSEs—Type A, Type B, Type C, Type D, Type E, </SO>and </SO>Type F</UL>, and Type G</UL> consistent with 104.1.3.

##### 104.4.7 PSE output requirements

##### 104.4.7.3 Power feeding ripple and transients

Change the first sentence of the third paragraph of 104.4.7.3 as shown:

When measuring the ripple voltages for a Type A</SO> or</SO></UL>, </UL>Type C</UL>, or Type G</UL> PSE as specified by Table 104–7 item (4b), the voltage observed at the MDI/PI with the differential probe where  $f_1 = 31.8 \text{ kHz} \pm 1\%$  is post-processed with transfer function  $H_2(f)$  specified in Equation (104–3) where  $f_2 = 1 \text{ MHz} \pm 1\%$ .

Change third sentence of the 2nd paragraph of 104.4.7.3 as shown:

When measuring the ripple voltage for a Type A</SO> or</SO></UL>, </UL>Type C</UL>, or Type G</UL> PSE as specified by Table 104-7 item (4a),  $f_1 = 31.8 \text{ kHz} \pm 1\%$ .

#### 104.5 Powered Device (PD)

##### 104.5.1 PD types

Change 104.5.1 as shown:

For PoDL systems there are six types of PDs—Type A, Type B, Type C, Type D, Type E, </SO>and </SO></UL>, </UL>Type F</UL>, and Type G</UL> consistent with 104.1.3.

##### 104.5.7 PD power

##### 104.5.7.4 PD ripple and transients

Insert the following new last sentence to the second paragraph of 104.5.7.4:

The ripple and transient specifications for a Type G PD shall be met for all operating voltages in the range of  $V_{PD}$  sourced through a dc bias coupling network with MDI return loss as specified by Clause 190 and over the range of  $P_{PD}$ .

Change the third sentence of the third paragraph of 104.5.7.4 as shown:

When measuring the ripple voltage for a Type A </SO>or </SO></UL>, </UL>Type C</UL>, or Type G</UL> PD as specified by Table 104–11 item (3a),  $f_1 = 31.8 \text{ kHz} \pm 1\%$ .

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

Change the first sentence of the fourth paragraph of 104.5.7.4 as shown:

When measuring the ripple voltages for a Type A</SO> or</SO></UL>, </UL> Type C</UL>, or Type G</UL> PD as specified by Table 104–11 item (3b), the voltage observed at the MDI/PI with the differential probe where  $f_1 = 31.8 \text{ kHz} \pm 1\%$  shall be post-processed with transfer function  $H_2(f)$  specified in Equation (104–3) where  $f_2 = 1 \text{ MHz} \pm 1\%$ .

(editor to note  $f_1$ ,  $f_2$ ,  $H_2$ ,  $V_{PD}$ ,  $P_{PD}$  the " " indicates the subscripting, and +/- symbols may be corrupted by the comment tool) check text of 104 for accuracy as the only intent is to add Type G)

104.7 Serial communication classification protocol (SCCP)

104.7.2 Serial communication classification protocols

104.7.2.4 Read\_Scratchpad function command [0xAA]

(Add Table 104\_13 - CLASS\_TYPE\_INFO register table to the draft, with editing instruction)

Change first row of Table 104-13 as shown (unchanged rows not shown):

Bits	Name	Description	R/W
b[15:12]	Type	15 14 13 12	RO
		1 1 1 0 = Type A	
		1 1 0 1 = Type B	
		1 0 1 1 = Type C	
		0 1 1 1 = Type D	
		1 1 0 0 = Type E	
		0 0 1 1 = Type F	
</UL>		0 0 1 0 = Type G</UL>	

104.9 Protocol implementation conformance statement (PICS) proforma for Clause 104, Power over Data Lines (PoDL) of Single-Pair Ethernet

104.9.3 Major capabilities/options

Change table to add rows for Type G PSE and Type G PD functionality, after rows for Type F PSE and PD functionality, respectively (unchanged rows not shown) as shown:

Item	Feature	Subclause	Value/Comment	Status	Support
*PSETG	Implements PSE Type G functionality	104.1.3	Provides support for requirements of Type G Power Sourcing Equipment	O	Yes[] No[]

....

*PDTG	Implements PD Type G functionality	104.1.3	Provides support for requirements of Type G Powered Device Equipment	O	Yes[] No[]
-------	------------------------------------	---------	--	---	------------

104.9.4.3 Powered Device (PD)

Insert new PICS row PD20a after PD20 (Type A or Type C PD ripple and transients) as shown (unchanged rows not shown):

Item	Feature	Subclause	Value/Comment	Status	Support
PD20a	Type G PD ripple and transients	104.1.3	In accordance with specifications shown in Table 104–11 for all operating voltages in the range of $V_{PD}$ sourced through a dc bias coupling network with MDI return loss as specified by Clause 190, and over the range of $P_{PD}$ Power Sourcing Equipment	PDTG:M	Yes[] N/A[]

Response Response Status C

ACCEPT IN PRINCIPLE.

Adopt proposal, with editorial license. See

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general  
 COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed Z/withdrawn  
 SORT ORDER: Comment ID

zimmerman\_3dg\_01\_062525.pdf for clear text reflecting suggested remedy.

CI	104	SC	104.6.2	P	37	L	5	#	115
Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony									
Comment Type E Comment Status A Power									
Fault tolerance requirement requires consideration and is unclear at this time.									

SuggestedRemedy

Add 104.6.2 Fault tolerance to the draft with Editor's note (to be removed prior to initial Working Group Ballot):

Fault tolerance requirement for 100BASE-T1L needs to be proposed, 10BASE-T1L differed from other BASE-T1 PHYs.

Response Response Status C

ACCEPT IN PRINCIPLE.

add 104.6.2 to the draft

104.6.2 Fault Tolerance

Change first paragraph of 104.6.2 as shown:

The PI for Type A, Type B, Type C, and Type F PSEs and PDs shall meet the fault tolerance requirements as specified in 96.8.3. The PI for Type E </UL>and Type G </UL>PSEs and PDs shall meet the fault tolerance requirements as specified in 146.8.6.

CI	190	SC	190.6	P	103	L	44	#	116
Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony									
Comment Type T Comment Status A New Content									
Text needed for 190.6. Text from clause 146 and 802.3da D2p3 can be adapted.									

SuggestedRemedy

Add the following text to 190.6, at P103 L45:

100BASE-T1L uses the management interface as specified in Clause 45. The Clause 45 MDIO register interface and registers are optional. When the MDIO interface is not implemented, provision of an equivalent mechanism for the functions specified in connection to the register bits is required.

Response Response Status C

ACCEPT.

Comment ID 116

Page 22 of 25  
 6/25/2025 9:38:52 AM

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

<b>CI 190</b>	<b>SC 190.6.2</b>	<b>P104</b>	<b>L14</b>	<b># 117</b>
Zimmerman, George		APL Group, ADI, Cisco, Marvell, Onsemi, Sony		
<b>Comment Type</b>	<b>T</b>	<b>Comment Status</b>	<b>A</b>	<b>New Content</b>

Text needed for LEADER-FOLLOW configuration. Text from clause 146 can be adapted.

**SuggestedRemedy**

Add the following text to 190.6.2, replacing the editor's note:  
LEADER-FOLLOWER assignment for each link configuration is necessary for establishing the timing control of each PHY. In 100BASE-T1L, one PHY should be configured as LEADER and one PHY should be configured as FOLLOWER to operate. In the case where both PHYs are configured to be LEADER or both to be FOLLOWER, operation is undefined.

The LEADER-FOLLOWER configuration between the PHYs is established using the method being described in 98.2.1.2.5 and Table 98-4.

<b>Response</b>	<b>Response Status</b>	<b>C</b>
-----------------	------------------------	----------

ACCEPT IN PRINCIPLE.

Add the following text to 190.6.2, and delete the editor's note:

LEADER-FOLLOWER assignment for each link configuration is necessary for establishing the timing control of each PHY. One PHY should be configured as LEADER and one PHY should be configured as FOLLOWER.

The LEADER-FOLLOWER configuration between the PHYs is established by Auto-Negotiation using the method described in 98.2.1.2.5. The LEADER-FOLLOWER configuration is resolved according to Table 98-4. In the case where the "Force" bit is set and both PHYs are configured to be LEADER or both to be FOLLOWER, a configuration fault occurs in Auto-Negotiation and operation of the PHY is undefined.

<b>CI 190</b>	<b>SC 190.7.1.4</b>	<b>P107</b>	<b>L20</b>	<b># 118</b>
Zimmerman, George		APL Group, ADI, Cisco, Marvell, Onsemi, Sony		
<b>Comment Type</b>	<b>E</b>	<b>Comment Status</b>	<b>A</b>	<b>Editorial</b>

The TCL shown in the figure is only for shielded link segments.

**SuggestedRemedy**

Change title of Figure 190-25 to "100BASE-T1L shielded link segment TCL"

<b>Response</b>	<b>Response Status</b>	<b>C</b>
-----------------	------------------------	----------

ACCEPT.

<b>CI 190</b>	<b>SC 190.7.1.4</b>	<b>P107</b>	<b>L22</b>	<b># 119</b>
Zimmerman, George		APL Group, ADI, Cisco, Marvell, Onsemi, Sony		
<b>Comment Type</b>	<b>T</b>	<b>Comment Status</b>	<b>A</b>	<b>Link Segment</b>

Balance on unshielded link segments is unspecified. There is considerable interest in deploying 100BASE-T1L on category 6 cabling.

**SuggestedRemedy**

Insert new paragraph, equation, and figure below Figure 190-25 as follows:  
The TCL requirement for unshielded link segments is specified to align with the use of Category 6 cabling components. Each 100BASE-T1L unshielded link segment shall meet the values determined using Equation (190-4) at all frequencies from 1 MHz to 60 MHz.

(Equation 190-4)  $TCL \geq 50 - 15 \log_{10}(f)$  dB       $1 \leq f \leq 60$   
Where f is the frequency in MHz;  $1 \leq f \leq 60$

Equation (190-4) is plotted in Figure 190-26, which is provided for information only.

(include plot as Figure 190-26 100BASE-T1L unshielded link segment TCL)

<b>Response</b>	<b>Response Status</b>	<b>C</b>
-----------------	------------------------	----------

ACCEPT IN PRINCIPLE.

Insert new paragraph, equation, and figure below Figure 190-25 as follows:  
The TCL requirement for unshielded link segments is specified to align with the use of Category 6 cables and components. Each 100BASE-T1L unshielded link segment shall meet the values determined using Equation (190-4) at all frequencies from 1 MHz to 60 MHz.

(Equation 190-4)  $TCL \geq 50 - 15 \log_{10}(f)$  dB       $1 \leq f \leq 60$   
Where f is the frequency in MHz;  $1 \leq f \leq 60$

Equation (190-4) is plotted in Figure 190-26, which is provided for information only.

(include plot as Figure 190-26 100BASE-T1L unshielded link segment TCL)

with editorial license to align with references used in cabling standards and elsewhere in 802.3.

## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 190	SC 190.9	P109	L48	# 120
Zimmerman, George		APL Group, ADI, Cisco, Marvell, Onsemi, Sony		
Comment Type	T	Comment Status	A	New Content

Need text for Environmental specifications. Text should be similar to 802.3da and Clause 146

**SuggestedRemedy**

Insert text in 190.9:(P109 L48)

**190.9.1 General safety**

Equipment subject to this clause shall conform to the general safety requirements in J.2. An example of an application-specific standard potentially applicable to this clause is IEC 61010-1. All equipment subject to this clause may be additionally required to conform to any applicable local, state, or national standards

**190.9.2 Network safety**

All cabling and equipment subject to this clause is expected to be mechanically and electrically secure in a professional manner. All 100BASE-T1L cabling is expected to be routed according to any applicable local, state, or national standards considering all relevant safety requirements.

**190.9.2.1 Environmental safety**

This subclause sets forth a number of recommendations and guidelines related to safety concerns; this list is neither complete nor does it address all possible safety issues. The designer is urged to consult the relevant local, national, and international safety regulations to ensure compliance with the appropriate requirements. Systems described in this subclause are subject to various environmental hazards during their installation and use. In particular, equipment used in automotive and industrial environments can expect to meet the

potential environmental stresses with respect to their mounting location defined for the application. Stresses expected in these environments may include but are not limited to those found in the listed specifications.

The following specifications define potential environmental stresses in an industrial environment:

- Environmental loads: IEC 60529 and ISO 4892
- Mechanical loads: IEC 60068-2-6 and IEC 60068-2-31
- Climatic loads: IEC 60068-2-1, IEC 60068-2-2, IEC 60068-2-14, IEC 60068-2-27, IEC 60068-2-30, IEC 60068-2-38, IEC 60068-2-52, and IEC 60068-2-78

Additional environment(s) require careful analysis prior to implementation to determine appropriate environmental safety requirements.

**190.9.2.2 Electromagnetic compatibility**

A system integrating the 100BASE-T1L PHY is expected to comply with all applicable local and national codes for electromagnetic compatibility.

**190.9.3 Telephony voltages**

The use of building wiring brings with it the possibility of wiring errors that might connect telephony voltages to a DTE. Other than voice signals, the primary voltages that can be encountered are the "battery" and ringing voltages. Although there is no universal standard,

the following maximums generally apply: Battery voltage to a telephone line is generally 56 V dc, applied to the line through a balanced 400  $\Omega$  source impedance. Ringing voltage is a composite signal consisting of an ac component and a dc component. The ac component is up to 175 Vp at 20 Hz to 60 Hz with a 100  $\Omega$  source resistance. The dc component is 56 V dc with 300  $\Omega$  to 600  $\Omega$  source resistance. Large reactive transients can occur at the start and end of each ring interval. Care should be taken to avoid such connections as they can damage equipment.

**Response****Response Status C**

ACCEPT IN PRINCIPLE.

Suggested remedy with editorial license. See zimmerman\_3dg\_02\_06252026.pdf for clean text.



## IEEE P802.3dg D1.1 100BASE-T1L 2nd Task Force review comments

CI 98 SC 98.5.2 P36 L # 121

Zimmerman, George APL Group, ADI, Cisco, Marvell, Onsemi, Sony

Comment Type T Comment Status A AutoNeg

Need to add in 85ms link fail inhibit timer per Fitzgerald\_3dg\_01\_11132024.pdf slide 7

#### SuggestedRemedy

Add 98.5.2 to the draft, with definition of link fail inhibit timer, and editing instruction:

98.5.2 State diagram timers

Change definition for link fail inhibit timer to add 100BASE-T1L as shown:

link\_fail\_inhibit\_timer\_[HCD]□

Timer for qualifying a link\_status=FAIL indication or a link\_status=OK indication when a specific technology link is first being established. A link will be considered “failed” only if the link\_fail\_inhibit\_timer\_[HCD] has expired and the link has still not gone into the link\_status=OK state. The expiration time of the link\_fail\_inhibit\_timer\_[HCD] shall be dependent on the selected PHY type. For all PHY types, except 10BASE-T1L</UL>, 100BASE-T1L,</UL> and 10BASE-T1S, this timer shall expire 97 ms to 98 ms after entering the AN GOOD CHECK state. For a 10BASE-T1L PHY, this timer shall expire 3030 ms to 3090 ms after entering the AN GOOD CHECK state. </UL> For a 100BASE-T1L PHY, this timer shall expire 85 ms after entering the AN GOOD CHECK state.</UL> For a 10BASE-T1S PHY, this timer shall expire 400 ms to 405 ms after entering the AN GOOD CHECK state.

Add 98.6 PICS to the draft:

98.6 Protocol implementation conformance statement (PICS) proforma for Clause 98, Auto-Negotiation for Single Differential-Pair Media

98.6.3 Major capabilities/options

Insert new row to table after \*10T1S (unchanged rows not shown) as shown:

Item	Feature	Subclause	Value / Comment	Status	Support
*100T1L	100BASE-T1L PHY type	98.5.2		O	

Yes[] No []

98.6.9 State diagram and variable definitions

Change table to change row SD19, and add new row SD 20a after row SD20 (unchanged rows not shown) as shown:

Item	Feature	Subclause	Value / Comment	Status	Support
SD19	link_fail_inhibit_timer_[HCD]	98.5.2	Expire 97 to 98 ms after entering the AN GOOD CHECK state	!	10T1L</UL>!*10T1S!*100T1L:M</UL>
				Yes[]	N/A[]

...

</UL> SD20a | link\_fail\_inhibit\_timer\_[HCD] for 100BASE-T1L PHY | 98.5.2 | Expire 85 ms after entering the AN GOOD CHECK state | 100T1L | Yes[] N/A[] </UL>

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement suggested remedy with editorial license to align. See zimmerman\_3dg\_03\_06252025.pdf for clean text.

CI 98B SC 98B.4 P113 L37 # 122

Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony

Comment Type T Comment Status A LATE

Need to add 100BASE-T1L to priority resolution

#### SuggestedRemedy

Append after 98B.3 (Table 98-1):

98B.4 Priority Resolution

Insert entry for 100BASE-T1L between 1000BASE-T1 and before 100BASE-T1 in the list of the priorities to be resolved.

- 100BASE-T1L

Response Response Status C

ACCEPT IN PRINCIPLE.

Suggested remedy with editorial license.  
(see 802.3cy)