

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

CI 177 SC 177.10 P325 L29 # 1

Marris, Arthur Cadence Design Systems

Comment Type TR Comment Status A (bucket)

Change the "enable" control variables to a single "reset" variable

SuggestedRemedy

In Table 177-6 rename "Inner FEC enable lane 0" to "Inner FEC reset"  
 Make the variable reference be to 177.6.2.1 (where Inner FEC reset is defined)  
 Delete rows for "Inner FEC enable lane 1" to "Inner FEC enable lane 7"  
 Delete editor's note below Table 177-6  
 In Table 45-177a delete rows "Inner FEC enable lane 1" to "Inner FEC enable lane 7" and  
 in the row for "1.2400.0" change "enable" to "reset"  
 On page 320 line 53 for the reset variable change the cross reference from "45.2.1.1.1" to  
 "45.2.1.213a"

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

CI 184 SC 184.9 P535 L15 # 2

Marris, Arthur Cadence Design Systems

Comment Type TR Comment Status A reset variable

Make FEC\_reset reference Inner FEC control register 1.2400

SuggestedRemedy

In Table 184-4 make the MDIO bit 1.2400.0 and reference 45.2.1.213a  
 Change variable name from "FEC\_reset" to "Inner\_FEC\_reset" and also on page 530 line  
 47  
 In Table 45-177a delete rows "Inner FEC enable lane 1" to "Inner FEC enable lane 7" and  
 in the row for "1.2400.0" change "enable" to "reset"  
 On page 530 line 47 for the reset variable change the cross reference from "45.2.1.1.1" to  
 "45.2.1.213a"

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #88.

CI 176 SC 176.11 P300 L15 # 5

Marris, Arthur Cadence Design Systems

Comment Type T Comment Status A (bucket)

Table 176-8 needs populating

SuggestedRemedy

Refer to "Table 45-3—PMA/PMD registers" in IEEE Std 802.3 for the correct MDIO register  
 bit references

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

CI 45 SC 45.2.1.213a P92 L13 # 6

Marris, Arthur Cadence Design Systems

Comment Type T Comment Status A (bucket)

Replace the 8 enable bits with a single reset bit in Table 45-177a

SuggestedRemedy

In Table 45-177a delete rows "Inner FEC enable lane 1" to "Inner FEC enable lane 7" and  
 in the row for "1.2400.0" change "enable" to "reset"

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #1.

CI 178B SC 178B.15 P792 L6 # 7

Marris, Arthur Cadence Design Systems

Comment Type T Comment Status A (bucket)

MDIO register bit references need to be added to Tables 178B-6 and 178B-7

SuggestedRemedy

Consider a proposal on how to do this during the January 2025 802.3dj task force meeting

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #170

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 00 SC 0 P L # 11

Brown, Matt Alphawave Semi

Comment Type E Comment Status A (bucket)

The format used for defining the various status counters for the PCS (175.2.5.3), PMA (176.7.4.1), and Inner FEC (177.5.4.1, 184.5.7) vary wildly from clause to clause. Rewrite/reformat the counter definitions in the same style.

*SuggestedRemedy*

Reformat the counter definitions in 175.2.5.3, 176.7.4.1, 177.5.4.1, and 184.5.7 to be the same format. Use either 175.2.5.3 or 177.5.4.1/184.5.7 as the template.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Reformat the counter definitions in 176.7.4.1, 177.5.4.1, and 184.5.7 to use the same format as 175.2.5.3.  
Implement with editorial license.  
[Editor's note: CC: 176, 177, 184]

Cl 177 SC 177.5.4.1.5 P319 L48 # 13

Brown, Matt Alphawave Semi

Comment Type T Comment Status A (bucket)

The index "i" is typically used for the lane number. Since counters need to be defined per lane, this index "i" will cause some ambiguity in the management variables and MDIO register definitions. For similar bin counters defined in 174A.6 and 176.7.4.1 the index "k" is used for this purpose.

*SuggestedRemedy*

For the bin counters defined in 177.5.4.1.5 change the index "i" to "k". Also update Table 177-7 and definitions in Clause 45 appropriately.

Response Response Status C

ACCEPT.

Cl 119 SC 119.3 P162 L33 # 14

Brown, Matt Alphawave Semi

Comment Type T Comment Status A (bucket)

Error bin counters are provided for 800GBASE-R and 1.6TBASE-R PCS but not for the 200GBASE-R or 400GBASE-R PCS. These counters are needed for accurate testing of a PHY receive path per 174A.7.

*SuggestedRemedy*

In Clause 119 add bin counters FEC\_codeword\_error\_bin\_i as defined in 172.3.6 stating that these counters are optional if the PCS is used in a PHY that includes 200 Gb/s per lane PMD.

Response Response Status C

ACCEPT IN PRINCIPLE.  
In addition to bin counters FEC\_codeword\_error\_bin\_i as defined in 172.3.6, also add FEC\_cw\_counter as defined in 172.3.5. Since these counters are already optional in Clause 172, there is no need to restrict the optionality to "PHYs that includes 200 Gb/s per lane PMD"  
Implement with editorial license.

Cl 176 SC 176.1.3 P270 L32 # 16

Brown, Matt Alphawave Semi

Comment Type E Comment Status A (bucket)

The terms defined in this subclause are not ordered in a consistent way. Typically for definitions we order them alphanumerically according to the rules according to the guidelines here:  
[http://www.ieee802.org/3/WG\\_tools/editorial/requirements/words.html#sort](http://www.ieee802.org/3/WG_tools/editorial/requirements/words.html#sort)

*SuggestedRemedy*

Reorder the terms alphanumerically according to the guidelines.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Implement the suggested remedy with editorial license.

Cl 177 SC 177.10 P326 L9 # 17

Brown, Matt Alphawave Semi

Comment Type T Comment Status A (bucket)

In Table 177-6 the enable bits are never defined in this clause nor are they necessary.

*SuggestedRemedy*

Remove the enable bits from Table 177-6 and delete the editor's note below.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Resolve using the response to comment #1.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 176 SC 176.5.4.1.5 P319 L48 # 20

Brown, Matt Alphawave Semi

Comment Type T Comment Status R (withdrawn)

The index "i" is typically used for the lane number. Since counters need to be defined per lane, this index "i" will cause some ambiguity in the management variables and MDIO register definitions. For similar bin counters defined in 174A.6 and 176.7.4.1 the index "k" is used for this purpose.

SuggestedRemedy

For the bin counters defined in 177.5.4.1.5 change the index "i" to "k". Also update Table 177-7 and definitions in Clause 45 appropriately.

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

Cl 175 SC 175.2.5.3 P254 L41 # 21

Brown, Matt Alphawave Semi

Comment Type T Comment Status A (bucket)

The following description is overly specific: "The following counters shall be implemented to aid a network operator in determining the link quality." It is also for PHY and LINK testing in general.

SuggestedRemedy

Change to "The following counters shall be implemented:"

Response Response Status C

ACCEPT.

Cl 176 SC 176.8 P199 L9 # 22

Brown, Matt Alphawave Semi

Comment Type T Comment Status A PMA delay

Delay limits for 200GBASE-R, 400GBASE-R, and 1.6TBASE-R PMAs are TBD and the one for 800GBASE-R PMAs may need to be refined.

SuggestedRemedy

Expect a contribution with proposals.  
Update Table 116-6, Table 116-7, 169-4, and Table 174-4 with the adopted numbers.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Resolve using the response to comment #451.

Cl 116 SC 116.4 P150 L52 # 24

Brown, Matt Alphawave Semi

Comment Type E Comment Status A (bucket)

Delay limits for the 200GBASE-R Inner FEC are TBD in Table 116-6 but are indeed defined in 177.7.

SuggestedRemedy

Update Table 116-6 with the delay numbers specified in 177.7.

Response Response Status C

ACCEPT.

Cl 116 SC 116.4 P151 L49 # 25

Brown, Matt Alphawave Semi

Comment Type E Comment Status A (bucket)

Delay limits for the 400GBASE-R Inner FEC are TBD in Table 116-7 but are indeed defined in 177.7.

SuggestedRemedy

Update Table 116-7 with the delay numbers specified in 177.7.

Response Response Status C

ACCEPT.

Cl 178 SC 178.7.1 P338 L42 # 28

Brown, Matt Alphawave Semi

Comment Type T Comment Status A (bucket)

The skew numbers from previous generations should be fine.

SuggestedRemedy

Delete the editor's note.

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

CI 178 SC 178.7.2 P339 L12 # 29

Brown, Matt Alphawave Semi  
 Comment Type T Comment Status A (bucket)

Skew constraints for 1.6TBASE-R based on 800GBASE-R should be fine.

SuggestedRemedy

Delete the editor's note.

Response Response Status C

ACCEPT.

CI 182 SC 182.7.1 P471 L27 # 33

Landry, Gary Texas Instruments  
 Comment Type TR Comment Status A (bucket)

OMAouter vs max(TECQ, TDECQ) figure was not updated when the OMAouter (min) values were changed in D1.3.

SuggestedRemedy

Update the figure to match D1.3 data. To be specific, OMAouter (min) line should be -0.3 dBm for max(TECQ, TDECQ) < 0.9 dB and 1.2+max(TECQ, TDECQ) dBm for > 0.9 dB.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license.

CI 177 SC 177.4.2 P311 L25 # 34

Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)

The text here seems a bit repetitive. The four paragraphs that start at line 25 spell out the delays for each delay line for each rate in detail, and then at line 50 there is a more abstract specification of the same thing.

SuggestedRemedy

Rewrite the first paragraphs to be algorithmic rather than per-rate:  
 "The first line (Delay Line 0) delays the data by 4x2xQ RS-FEC symbols, the second line (Delay Line 1) by 4x1xQ RS-FEC symbols, and the last line (Delay Line 2) adds no delay. The values of Q are shown in table 177-X."  
 Add a table with a column for the rate (200GBASE-R, 400GBASE-R, etc.) and a column for the value of Q.  
 Delete the sentence at lin 51 that starts with "The number Q differs for each..." and the bullet list that follows (this information is replaced by the table).

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

CI 184 SC 184.4.5 P522 L5 # 35

Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)

The description of the parity polynomial says "A parity polynomial p(x) of degree 15 is defined as the remainder from the division (modulo 2) of m(x) x x^16 by the generator polynomial shown in Equation (184-2)". The intent of this is that the resulting parity polynomial p(x) is in equation 184-2 (with the generator polynomial in (184-1), but that isn't what the text says.

SuggestedRemedy

Change the text to read: "A parity polynomial p(x) of degree 15 is defined as the remainder from the division (modulo 2) of m(x) x x^16 by the generator polynomial, as shown in Equation (184-2)."

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Change: "A parity polynomial p(x) of degree 15 is defined as the remainder from the division (modulo 2) of m(x) x x^16 by the generator polynomial shown in Equation (184-2)" to: "A parity polynomial p(x) of degree 15 (shown in Equation 184-2) is defined as the remainder from the division (modulo 2) of m(x) x x^16 by the generator polynomial shown in Equation (184-1)"  
 Implement with editorial license.

CI 186 SC 186.2.2 P568 L23 # 37

Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)

The AM field was renamed FAM to clarify that it is not the 800GBASE-R AMs.

SuggestedRemedy

Change OH/AM to OH/FAM

Response Response Status C

ACCEPT.

CI 186 SC 186.2.3.6 P572 L51 # 38

Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)

With the addition of the AML field, the overhead is no longer a subset of what is in the OIF IA. Also, the reference to ITU-T G.709.6 should be to ITU-T G.709.1

SuggestedRemedy

Revise the text to read: "The frame overhead is based on the frame defined in subclause 4.3.3 of OIF-800ZR-01.0, which is a subset of what is defined in Recommendation ITU-T G.709.1."

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 186 SC 186.3.3.1.2 P589 L17 # 40  
 Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)  
 In figure 186-13, 'mfas' should be 'faw' to align with the text in 186.3.3.1.5 (faw is used here to avoid conflict with the MFAS field in the PCS frame structure in clause 186.2)  
 SuggestedRemedy  
 Change mfas to faw  
 Response Response Status C  
 ACCEPT.

Cl 186 SC 186.4.2.1 P597 L6 # 41  
 Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)  
 As is tersely explained in 186.2.3.5.1 (with reference to G.709.6, where there is additional detail), the FAM field contains 32 bytes that are providing the frame alignment pattern, and 28 bytes that are reserved (0x00). The alignment process should only be looking at the 32 bytes; the 28 bytes that are transmitted as 0x00 are not required to match.  
 SuggestedRemedy  
 Revise the definition of fam\_valid to consider only the 32 bytes that have the frame alignment pattern rather than the entire FAM field:  
 "A Boolean variable that is set to true if the first 256 bits of the FAM field are a valid PCS frame alignment mechanism sequence..."  
 Response Response Status C  
 ACCEPT.

Cl 169 SC 169.2.4 P172 L50 # 42  
 Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)  
 This clause should include a reference to the 800GBASE-ER1 PMA  
 SuggestedRemedy  
 Add a sentence: The 800GBASE-ER1 PMA is specified in clause 186.3  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 169 SC 169.4 P178 L22 # 43  
 Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)  
 Table 169-4 is missing rows for the 800GBASE-ER1 PCS and PMA  
 SuggestedRemedy  
 Add a row for the PMA. Depending on the disposition of other comments about ER1 architecture, add a row for the ER1 PCS or the ER1 FEC. The values for both in clause 186 are still TBD.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 169 SC 169.4 P178 L23 # 44  
 Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)  
 Clause 176 has delay constraints for 800G 32:4 and 4:4 PMAs, clause 177 has values for 800GBASE-R inner FEC, and clause 184 has values for the LR1 inner FEC  
 SuggestedRemedy  
 Replace the TBDs with the appropriate values from Table 176-7, Table 177-5, and from clause 184.7 for the LR1 inner FEC.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.4.1.3 P310 L47 # 45  
 Huber, Thomas Nokia  
 Comment Type T Comment Status A (bucket)  
 The wording here is a bit awkward - the intent is to define a much stricter maximum skew tolerance in the inner FEC than in 800GBASE-R PCS, but the text says "... Skew between PCSLs is removed as defined in 172.2.5.1, except that the 800GBASE-R deskew function shall support a maximum Skew of 25 ns between PCS lanes..."  
 SuggestedRemedy  
 Use language more like what 172.2.5.1 uses. Change the text to read "... Skew between PCSLs is removed as defined in 172.2.5.1, except that a maximum Skew of 25 ns is supported between PCS lanes..."  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.4.1.3 P310 L52 # 46

Huber, Thomas

Nokia

Comment Type T Comment Status A (bucket)

The wording here is a bit awkward - the intent is to define a much stricter maximum skew tolerance in the inner FEC than in 800GBASE-R PCS, but the text says "... Skew between PCSs is removed as defined in 172.2.5.1, except that the 1.6TBASE-R deskew function shall support a maximum Skew of 25 ns between PCS lanes..."

SuggestedRemedy

Use language more like what 175.2.5.1 uses. Change the text to read "... Skew between PCSs is removed as defined in 175.2.5.1, except that a maximum Skew of 25 ns is supported between PCS lanes..."

Response Response Status C

ACCEPT IN PRINCIPLE.  
Implement the suggested remedy with editorial license.

Cl 185 SC 185.2 P542 L36 # 71

Sluyski, Mike

Cisco

Comment Type E Comment Status R (bucket)

Does IEEE style allow embedded parameter values as part of the text (e.g. BERadded equal to  $3.2 \times 10^{-5}$  and BERadded equal to  $6.4 \times 10^{-5}$ )

SuggestedRemedy

A small table might be clearer than values buried in text.

Response Response Status C

REJECT.  
Stating parameter values as text is supported by IEEE and widely used in IEEE Std 802.3-2022.  
No changes to the draft.  
[Editor's note: changed subclause from 185.5.2 Error ratio allocation to 185.2]

Cl 185 SC 185.3.1.1 P545 L13 # 72

Sluyski, Mike

Cisco

Comment Type E Comment Status R (bucket)

This clause include a reference (184.4.11.1) and later to (185.5.2).

SuggestedRemedy

Would it be better and clearer to reference Figure 185-2 instead of text 184.4.11.1 (Picture is clearer than words). Likewise Reference to Figure 185-5 than text in 185.5.2.

Response Response Status C

REJECT.  
Subclause 185.3.1.1 specifies the receipt of the PMD:IS\_UNITDATA.request primitive. The noted referce to 184.4.11.1 specifies how the primitive is created and contains relevent information not included in the Figure 185-2 or 185-3.  
No change to the draft  
[Editor's note: changed subclause from 185.3.1.1 800GBASE-L to 185.3.1.1]

Cl 187 SC 187.1 P614 L8 # 74

Sluyski, Mike

Cisco

Comment Type E Comment Status A (bucket)

The optical signal generated by these PMD types are modulated using a dual polarization 16-state quadrature amplitude modulation

SuggestedRemedy

either signal is plural as in signals or the are should be is if singular.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Change "The optical signal generated by these PMD types are modulated" to "The optical signals generated by these PMD types are modulated".

Cl 187 SC 187.2 P615 L34 # 75

Sluyski, Mike

Cisco

Comment Type E Comment Status A (bucket)

Reference 174A.4 is not linked.

SuggestedRemedy

Link reference to 174A.4

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 187 SC 187.3.1.1 P618 L13 # 76

Sluyski, Mike

Cisco

Comment Type E Comment Status R (bucket)

This clause include a reference (186.3.3.1.6) and later to (187.5.2).

*SuggestedRemedy*

Would it be better and clearer to reference Figure 187-2 instead of text 186.3.3.1.6 (Picture is clearer than words). Likewise Reference to Figure 187-5 than text in 187.5.2.

Response Response Status C

REJECT.

Subclause 187.3.1.1 specifies the receipt of the PMD:IS\_UNITDATA.request primitive.

The noted referece to 186.3.3.1.6 specifies how the primitive is created and contains relevent information not included in the Figure 187-2 or 187-3.

No change to the draft

[Editor's note: changed subclause from "187.3.1.1 800GBASE-E" to 187.3.1.1]

Cl 176 SC 176.4.4.3 P291 L2 # 84

Opsasnick, Eugene

Broadcom

Comment Type TR Comment Status A (bucket)

The initial condition (open arrow) to enter the LOSS\_OF\_ALIGNMNET state in Figure 176-9 is "reset + !all\_locked\_mux". (!signal\_ok\_mux) should be added to this condition

*SuggestedRemedy*

Change the open arrow condition to enter LOSS\_OF\_ALIGNMENT state from:

reset + !all\_locked\_mux

to:

reset + !signal\_ok\_mux + !all\_locked\_mux

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement the suggested remedy with editorial license.

Cl 176 SC 176.2 P274 L17 # 85

Opsasnick, Eugene

Broadcom

Comment Type TR Comment Status A (bucket)

In the last sentence of the pargraph right before Table 176-5, the statement "[the parameter] is set to the value of the received SIGNAL\_OK value" is ambiguous. Which received SIGNAL\_OK is to be used? There are two different SIGNAL\_OK inputs.

The same kind of statement is made in the last sentence of the paragraph immediately before Table 176-6 on page 275, in subclause 176.3, line 29.

Both of these statements should be made more clear.

*SuggestedRemedy*

In 176.2, immediately prior to Table 176-5 change the sentence from:

"For the n:n PMAs, the SIGNAL\_OK parameter at the client interface is set to the value of the received SIGNAL\_OK value.

to:

"For the n:n PMAs, the SIGNAL\_OK parameter at the client interface is set to the value of the received SIGNAL\_OK parameter from the sublayer below the PMA (inst:IS\_SIGNAL.indication(SIGNAL\_OK))."

And in subclause 176.3, change the last sentence immediately prior to Table 176-6 from:

"For the n:n PMAs, the SIGNAL\_OK parameter at the interface below the PMA is set to the value of the received SIGNAL\_OK value."

to:

"For the n:n PMAs, the SIGNAL\_OK parameter at the interface below the PMA is set to the value of the received SIGNAL\_OK parameter from the sublayer above the PMA (PMA:IS\_SIGNAL.request(SIGNAL\_OK))."

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 174 SC 174.3.2 P235 L20 # 87

Opsasnick, Eugene Broadcom

Comment Type T Comment Status R (bucket)

In Figure 174-4 (1.6T Inter-sublayer interfaces with Inner FEC), there is no AUI. The Inner FEC will (almost) always be in an optical module below an AUI connection to a host. It would be better to show the Inner FEC below an AUI in this figure since the layer stack shown, while logically correct, will rarely, if ever, be used.

*SuggestedRemedy*

Add a "1.6T BASE-R 8:8 PMA" between the "1.6T BASE-R 16:8 PMA" on line 14 and the "1.6TBASE-R Inner FEC" on line 20 which creates an AUI interface between the two PMAs. And then add the necessary inter-layer signals on the AUI connection between the two PMAs.

Response Response Status C

REJECT.

The intent of this diagram (see figure title) is to show intersublayer interfaces not provide an exhaustive set of implementation configurations, which is provided instead in Annex 176B.

Cl 177 SC 177.6.2.1 P320 L53 # 88

Opsasnick, Eugene Broadcom

Comment Type T Comment Status A reset variable

FEC\_reset is referred to in the definition of the "reset" variable, but FEC\_reset is not defined except through a cross-reference to 45.2.1.1.1. The MDIO control variable table (Table 177-6) should instead be used for the cross reference to CL 45 registers).

*SuggestedRemedy*

Remove the cross-reference text "(see 45.2.1.1.1)" from the definition of reset in 177.6.2.1.

Add the definition of "FEC\_reset" to the list of variables in 177.6.2.1 as: "Boolean variable that is true when set by a management entity and is false otherwise".

Add FEC\_reset to the MDIO control variables table (Table 177-6) in subclause 177.10 with cross-references to 177.6.2.1 and 45.2.1.1 and the MDIO register bit number, 1.0.15.

Response Response Status C

ACCEPT IN PRINCIPLE.

Editorial slides with topic "Reset variables" in the following contribution was reviewed by the CRG:

[https://www.ieee802.org/3/dj/public/25\\_01/brown\\_3dj\\_03a\\_2501.pdf](https://www.ieee802.org/3/dj/public/25_01/brown_3dj_03a_2501.pdf)

Implement the proposed changes in slides 10 to 18 in brown\_3dj\_03a\_2501, except that in Annex 178B align with the resets defined for PMA and PMD, rather than as proposed on slide 17.

Implement with editorial license.

Cl 184 SC 184.6.2.2 P530 L47 # 89

Opsasnick, Eugene Broadcom

Comment Type T Comment Status A reset variable

FEC\_reset is referred to in the definition of the "reset" variable, but FEC\_reset is not defined except through a cross-reference to 45.2.1.1.1. The MDIO control variables table (Table 184-4) already has a cross reference to 184.6.2.2 as well as CL 45 and the MDIO register bit number,

*SuggestedRemedy*

Remove the cross-reference text "(see 45.2.1.1.1)" from the definition of reset in 184.6.2.2.

Add the definition of "FEC\_reset" to the list of variables in 184.6.2.2 as: "Boolean variable that is true when set by a management entity and is false otherwise".

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #88.

Cl 179 SC 179.14 P400 L10 # 90

Opsasnick, Eugene Broadcom

Comment Type TR Comment Status A reset variable

In Table 179-20, the variable PMD\_reset has a variable reference to subclause 178B.14.2.1; however, that subclause does not define "PMD\_reset".

*SuggestedRemedy*

Suggest adding a subclause to CL 179 (perhaps 179.8.10) to define the PMD\_reset variable similar to 180.5.6, 181.5.6, 182.5.6, 183.5.6, and 185.5.6 and 187.5.6 with title "PMD reset function" and subclause text: "If the variable PMD\_reset is asserted, the PMD shall be reset as defined in 45.2.1.1.1".

And change the cross-reference in Table 179-20 from 178B.14.2.1 to this new subclause in Clause 179.

A similar subclause should also be added as 178.8.10 titled "PMD reset function" with the same text as above.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #88.



EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 45 SC 45.2.1.213a P92 L14 # 91

Nicholl, Shawn

AMD

Comment Type TR Comment Status A (bucket)

Description column of fields in "Table 45-177a - Inner FEC control register bit definitions" is inconsistent with other MDIO registers.

SuggestedRemedy

Propose the following text for the description column of 1.2400.7 row:

1 = Enable Inner FEC on lane 7

0 = Disable Inner FEC on lane 7

Propose similar update to description column of 1.2400.0 through 1.2400.6 rows.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #1.

Cl 73 SC 73.6.2.5.3 P122 L46 # 92

Nicholl, Shawn

AMD

Comment Type TR Comment Status A (bucket)

The paragraph that begins "The variable an\_rs\_fec\_int\_negotiated\_control indicates that RS-FEC-Int ..." is located in the incorrect sub-clause.

SuggestedRemedy

Propose to move the paragraph such that it is inserted after the second paragraph of 73.6.2.5.4 (consistent with editorial guidance found in 802.3ck-2022, Sub-Clause "73.6.5.3 FEC control variables").

Response Response Status C

ACCEPT.

Cl 73 SC 73.6.4 P125 L25 # 93

Nicholl, Shawn

AMD

Comment Type E Comment Status A (bucket)

Currently says "D[10:0] and D[47:16] contains the Unformatted Code Field ...", but should use the singular verb.

SuggestedRemedy

Propose "D[10:0] and D[47:16] contain the Unformatted Code Field"

Response Response Status C

ACCEPT.

Cl 73 SC 73.8 P128 L21 # 94

Nicholl, Shawn

AMD

Comment Type ER Comment Status A (bucket)

Typo mr\_lp\_adv\_extened\_ability[32:1] in "Table 73-6-Backplane Ethernet Auto-Negotiation variable to MDIO register mapping"

SuggestedRemedy

Propose mr\_lp\_adv\_extended\_ability[32:1]

Response Response Status C

ACCEPT.

Cl 171 SC 171.9.5.5 P216 L22 # 95

Nicholl, Shawn

AMD

Comment Type TR Comment Status A (bucket)

Currently says "transmits what it receives from the 800GMII". However, this sub-clause pertains to 1.6TXS.

SuggestedRemedy

Propose "transmits what it receives from the 1.6TMII".

Response Response Status C

ACCEPT.

Cl 176 SC 176.4.2.4.2 P281 L32 # 96

Nicholl, Shawn

AMD

Comment Type TR Comment Status A (bucket)

Currently says "... and for the 400GBASE-R 32:4 PMA, the odd lanes ..."

SuggestedRemedy

Propose "... and for the 400GBASE-R 16:2 PMA, the odd lanes ..."

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 73A SC 73A.1a P640 L40 # 97

Nicholl, Shawn

AMD

Comment Type E Comment Status A (bucket)

Currently says "... indicates additional abilities that were not accommodated in the link codeword Base Page ..." Present tense seems more appropriate.

SuggestedRemedy

Propose "... indicates additional abilities that are not accommodated in the link codeword Base Page ..."

Response Response Status C

ACCEPT.

Cl 174A SC 174A.7.1.4 P667 L35 # 106

Mi, Guangcan

Huawei Technologies Co., Ltd

Comment Type TR Comment Status A (bucket)

The last sentence of this subclause "The measured codeword error ratio is expected be less than 1.45 e-11." is misleading.

At the beginning, it states "The following method is used to calculate the block error ratio using FEC bin counters provided in the PCS."  
Step h defines the block error ratio as Hms(16), not the code word error ratio.

CL174A.8 provides the definition of FEC codeword error ratio, which seems to be Hm(16).

It is unclear which error ratio should be less than 1.45e-11.

SuggestedRemedy

change to "the measured block error ratio is expected to be less....". Or state the relation between codeword error ratio and block error ratio in the subclause.

Response Response Status C

ACCEPT IN PRINCIPLE.

Change "The measured codeword error ratio"  
To "The measured block error ratio"

Cl 177 SC 177.5.4.1.4 P319 L45 # 108

Mi, Guangcan

Huawei Technologies Co., Ltd

Comment Type ER Comment Status A (bucket)

inner FEC bin counters can be used to roughly measure pre-Inner FEC BER. Pre-FEC BER is implicit.

SuggestedRemedy

change to "pre-Inner-FEC BER"

Response Response Status C

ACCEPT IN PRINCIPLE.  
Implement the suggested remedy with editorial license.

Cl 182 SC 182.12 P490 L3 # 109

Mi, Guangcan

Huawei Technologies Co., Ltd

Comment Type ER Comment Status R (withdrawn)

type 400GBASE-DR4 is not the PMD type of clause 182

SuggestedRemedy

change to type" 200GBASE-DR1-2, 400GBASE-DR2-2, 800GBASE-DR4-2, and 1.6TBASE-DR8-2"

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

Cl 182 SC 182.12 P490 L8 # 110

Mi, Guangcan

Huawei Technologies Co., Ltd

Comment Type ER Comment Status R (withdrawn)

PMD types should be updated in the text.

SuggestedRemedy

change "type 400GBASE-DR4" to " type 200GBASE-DR1-2, 400GBASE-DR2-2, 800GBASE-DR4-2, and 1.6TBASE-DR8-2"

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 116 SC 116.1.4 P138 L18 # 114  
 Slavick, Jeff Broadcom  
 Comment Type E Comment Status A (bucket)  
 Table 116-3b has a thick bar on the right side of clause 73 M  
 SuggestedRemedy  
 address the formatting issue  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.4.2 P311 L42 # 115  
 Slavick, Jeff Broadcom  
 Comment Type TR Comment Status A (bucket)  
 The deskewed data is fed into the covolutioner.  
 SuggestedRemedy  
 Change " The input data from the FEC service interface lane is fed into"  
 to: "The data from deskewed PMA lane is fed into"  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.2 P318 L19 # 116  
 Slavick, Jeff Broadcom  
 Comment Type E Comment Status A (bucket)  
 The statement that you can identify flow 0 and how its done should be one paragraph  
 SuggestedRemedy  
 Combine paragraph 4 & 5 in 177.5.2.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.4.1.1 P319 L24 # 117  
 Slavick, Jeff Broadcom  
 Comment Type T Comment Status A (bucket)  
 There is a reference to clause 45 here, I think we want that all to be in the tables  
 SuggestedRemedy  
 Delete the "(see 45.2.1.213h)"  
 In 177.5.4.1 add the following senetence "Mapping of the counters to management  
 variables is specified in 177.10"  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.4..1.5 P319 L52 # 118  
 Slavick, Jeff Broadcom  
 Comment Type T Comment Status A (bucket)  
 We're specifying the behavior of bin 3, so starting with "Note' could be a bit misleading  
 SuggestedRemedy  
 Change the last sentence to read "Error bin 3 incrmets when three or more bits are  
 corrected in an Inner FEC codeword."  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.6.3 P322 L22 # 119

Slavick, Jeff Broadcom

Comment Type TR Comment Status A (bucket)

In Fig 177-10 the exit from INNER\_FEC\_SYNC can't be all\_sync because that's false when any sync\_flow is false and in that state we set it false and need to go through the sync process to set it to true.

*SuggestedRemedy*

Create new variable "none\_synced" -- A Boolean variable that is set to true when sync\_flow<x> is false for all eight flows and is set to false when sync\_flow<x> is true for any x.

In Fig. 177-10 replace the all\_sync criteria from INNER\_FEC\_SYNC\_INIT to GET\_BLOCK to be UCT

In Fig 177-11 replace the restart\_inner\_fec\_sync criteria for entering FAS\_LOCK\_INIT with none\_synced

Response Response Status C

ACCEPT IN PRINCIPLE.  
Resolve using the response to comment #504.

Cl 177 SC 177.4.1.1 P310 L29 # 120

Slavick, Jeff Broadcom

Comment Type TR Comment Status A (bucket)

The demultiplexing function refers to "service interface below the PMA" but this is above the Inner FEC.

*SuggestedRemedy*

Add "with the exception that it operates on the Inner FEC service interface input lanes"

Response Response Status C

ACCEPT IN PRINCIPLE.  
Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.7 P320 L15 # 122

Slavick, Jeff Broadcom

Comment Type TR Comment Status A (bucket)

We're restoring to the data stream to its original order, but it could have errors in the so we can't state it's the original data from the SM-PMA and that'd be the far end SM-PMA not the local one.

*SuggestedRemedy*

Change "to restore the original data received from the BASE-R SM-PMA." to be "to restore the order of the data received to be compatible with the BASE-R SM-PMA."

Response Response Status C

ACCEPT IN PRINCIPLE.  
Implement the suggested remedy with editorial license.

Cl 177 SC 177.5 P317 L27 # 123

Slavick, Jeff Broadcom

Comment Type TR Comment Status A (bucket)

Introductory sentence could be useful

*SuggestedRemedy*

Add the following to 177.5 "The following processes are performed independently on each PMD service interface input lane.

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 178B SC 178B.14.2.1 P783 L13 # 124

Slavick, Jeff Broadcom

Comment Type TR Comment Status A Interfaces

"other" interface is a bit ambiguous and the listed situations are the typical use case but does not cover all use cases. As a remote PCS (after a XS) could do either local or clock forwarding modes.

SuggestedRemedy

Rename client\_is\_pcs to be "uses\_local\_clock\_only" and update the definition to be "Boolean variable that indicates if the PMA will never swap to a forwarded clock. For example this will be true for the first PMA below the RS."

Replace both uses of client\_is\_pcs with uses\_local\_clock\_only in Fig 178B-7

Response Response Status C

ACCEPT IN PRINCIPLE.

Related slides in the following contribution were reviewed by the CRG:  
[https://www.ieee802.org/3/dj/public/25\\_01/brown\\_3dj\\_03a\\_2501.pdf](https://www.ieee802.org/3/dj/public/25_01/brown_3dj_03a_2501.pdf)

Implement the changes provided on slide 26 of brown\_3dj\_03a\_2501 with editorial license.

Cl 186 SC 186.2.4.1 P580 L20 # 127

Slavick, Jeff Broadcom

Comment Type T Comment Status A (bucket)

Don't have the counters be their own sub-headings, just be inline functionality that is part of the decoder.

SuggestedRemedy

Add this sentence prior to the 186.2.4.1.1 heading "The following counters shall be implemented to aid a network operator in determining the link quality."

Remove the sub-headings of 186.2.4.1.1-4 and make them inline definitions like is done in 175.2.5.3

Update the references in Table 186-8  
 Implement with editorial license.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license

Cl 174A SC 174A.7.1.3 P667 L1 # 129

Slavick, Jeff Broadcom

Comment Type T Comment Status A (bucket)

This section is not really "measuring" or comparing the histograms to anything it's just acquiring the data. In 174A.6.1.3 we don't include the word measurement in the section title.

SuggestedRemedy

Remove the word "measurement" from the title of 174A.7.1.3

Response Response Status C

ACCEPT IN PRINCIPLE.

The text literally says that these are measurements "An error histogram using PCS counters is measured using the following method:"  
 However, it makes sense to align the subclause titles in 174A.6.1.3 and 174A.7.1.3.  
 Change the title of 174A.6.1.3 to "PMA error histogram measurement"

Cl 178B SC 178B.14.3.5 P789 L41 # 141

Slavick, Jeff Broadcom

Comment Type TR Comment Status A (bucket)

Ambiguous transition if timer\_done and tf\_lock both occur simultaneously

SuggestedRemedy

Add "!recovery\_timer\_done \*" to the transition back to TRAIN\_LOCAL

Response Response Status C

ACCEPT.

Cl 178B SC 178B.14.3.5 P790 L20 # 142

Slavick, Jeff Broadcom

Comment Type E Comment Status A (bucket)

Fig 178B-9 has text box overlapping lines

SuggestedRemedy

tf\_offset in GET\_NEW\_MARKER is covering up lies

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Fix the GET\_NEW\_MARKER box and text to avoid overlap.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 178B SC 178B.14.3.5 P790 L20 # 143  
 Slavick, Jeff Broadcom  
 Comment Type E Comment Status A (bucket)  
 Fig 178B-9 has an extraneous line  
 SuggestedRemedy  
 extran | to th right of the UCT exiting POLARIY\_INVERT  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Remove extraneous line from Figure 178B-9.

Cl 178B SC 178B.14.3.5 P790 L27 # 144  
 Slavick, Jeff Broadcom  
 Comment Type TR Comment Status A State diagram  
 Fig 178B-9 needs to clarify the transitions out of TEST\_MARKER.  
 SuggestedRemedy  
 Change the transition from TEST\_MARKER to INVALID\_MARKER to be "(!valid\_marker \* !inverse\_valid\_marker) + (polarity\_correction \* inverse\_valid\_marker)"  
 Change the transition from TEST\_MARKER to POLARITY\_INVERT to be "!polarity\_correction \* inverse\_marker\_valid"  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Related slides in the following contribution were reviewed by the CRG:  
[https://www.ieee802.org/3/dj/public/25\\_01/brown\\_3dj\\_03a\\_2501.pdf](https://www.ieee802.org/3/dj/public/25_01/brown_3dj_03a_2501.pdf)  
 Implement the changes on either slide 30 or slide 32, at the editor's discretion, of brown\_3dj\_03a\_2501 with editorial license.

Cl 176 SC 176.4.4.3 P290 L34 # 145  
 He, Xiang Huawei  
 Comment Type T Comment Status A (bucket)  
 The index y is not a PMAL but a PAML number.  
 SuggestedRemedy  
 Change "where y is the input PMAL" to "where y is the input PMAL number"  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.4.2 P311 L18 # 146  
 He, Xiang Huawei  
 Comment Type T Comment Status A (bucket)  
 The term "PMA lane" is not accurate. Within the Inner FEC sublayer, it is an "Inner FEC lane".  
 SuggestedRemedy  
 Change "PMA lane" to "Inner FEC lane", to be consistent within the clause.  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.10 P325 L9 # 147  
 He, Xiang Huawei  
 Comment Type T Comment Status A (bucket)  
 "Inner FEC enable lane x" variables are not defined or backed by any proposal, and should be removed in the next draft.  
 SuggestedRemedy  
 Remove rows "Inner FEC enable lane 0" through "Inner FEC enable lane 7" in Table 177-6.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #1.

Cl 116 SC 116.3.3.4.1 P150 L12 # 152  
 Bruckman, Leon Nvidia  
 Comment Type E Comment Status A (bucket)  
 Missing comma  
 SuggestedRemedy  
 To make consistent with the text in the previous section penultimate paragph, add a comma before: but it is considered...  
 Or delete the coma in the previous section penultimate paragph, wathever makes sense grammatically.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 On page 149 line 27 delete comma preceding " but it is considered".

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 169 SC 169.4 P178 L23 # 154  
 Bruckman, Leon Nvidia  
 Comment Type TR Comment Status A (bucket)  
 The values for 800GBASE-R Inner FEC and 800GBASE-LR1 are defined in the respective referenced sections.  
 SuggestedRemedy  
 Fill the TBDs in Table 169-4 for 800GBASE-R Inner FEC and 800GBASE-LR1 with the values in the referenced sections  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #44.

Cl 187 SC 187.8.6 P628 L8 # 160  
 Bruckman, Leon Nvidia  
 Comment Type ER Comment Status A (bucket)  
 Redundant "is".  
 SuggestedRemedy  
 Change: "ETCC is the quality metric is used to define"  
 To: "ETCC is the quality metric used to define"  
 Response Response Status C  
 ACCEPT.

Cl 174A SC 174A.4 P662 L3 # 161  
 Bruckman, Leon Nvidia  
 Comment Type TR Comment Status A (bucket)  
 Pre-FEC BER should be  $2.21 \times 10^{-4}$ .  
 SuggestedRemedy  
 Change: " $2.21 \times 10^{-14}$ ."  
 To: " $2.21 \times 10^{-4}$ ."  
 Response Response Status C  
 ACCEPT.

Cl 174A SC 174A.6.1.3 P664 L35 # 162  
 Bruckman, Leon Nvidia  
 Comment Type TR Comment Status A (bucket)  
 In Hm is not clear what is the meaning of "m"  
 SuggestedRemedy  
 Define the meaning of "m" in Hm or remove the "m"  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 H\_m is a set of measured histograms.  
 Change: "Hm(i)(k) is a set of 17-bin histograms"  
 To: "Hm(i)(k) is a set of measured 17-bin histograms"

Cl 174A SC 174A.6.1.3 P664 L41 # 163  
 Bruckman, Leon Nvidia  
 Comment Type TR Comment Status R (bucket)  
 The polynomial for PRBS31Q is not defined  
 SuggestedRemedy  
 Define that the PRBS31Q is produced by the polynomial defined in Equation (49-2) and shown in Figure 49-9.  
 Response Response Status C  
 REJECT.  
 The PRBS31Q test pattern is defined in the either the PMA clause or the Inner FEC clause. This detail is beyond the scope of this annex. The proposed change does not improve clarity or accuracy of the draft.

Cl 174A SC 174A.6.1.4 P665 L24 # 165  
 Bruckman, Leon Nvidia  
 Comment Type TR Comment Status R (bucket)  
 Define the ranges of k and i  
 SuggestedRemedy  
 Change: "for all k and i."  
 To: "for k = 0 to 16 and i = 0 to p-1"  
 Response Response Status C  
 REJECT.  
 The lane index i and number of lanes p are defined in 174A.6.1.2. It is not necessary to repeat this elsewhere.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 174A SC 174A.7.1.4 P667 L26 # 168  
 Bruckman, Leon Nvidia  
 Comment Type TR Comment Status A (bucket)  
 Point e) is unclear  
 SuggestedRemedy  
 Change: "substituting Hms(k) for Hx(k) for Hms (i)(k) for Hy(k)"  
 To: "substituting Hms(k) for Hx(k) and Hms (i)(k) for Hy(k)"  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 180 SC 180.9.5 P430 L4 # 171  
 Johnson, John Broadcom  
 Comment Type TR Comment Status A SER  
 The TDECQ test method points to clause 121.8.5.3, which uses a target SER of 4.8e-4, which is not appropriate for 200G/lane AUIs. As given in Table 174A-1, the appropriate value for 200G/lane AUIs should be 4.56e-4 for uncorrelated bit errors.  
 SuggestedRemedy  
 Add a new exception to the list:  
 "Target PAM4 symbol error ratio of 4.56e-4."  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Add a new exception to the list:  
 "The target PAM4 symbol error ratio is 4.56e-4 and the related Q\_t value is 3.428."  
 Implement with editorial license.

Cl 180 SC 180.9.5 P430 L32 # 172  
 Johnson, John Broadcom  
 Comment Type TR Comment Status A taps  
 In Table 180-18, the minimum number of equalizer pre-cursor taps is TBD. In the absence of further proposals, this value should be 0, consistent with the 5-tap FFE defined in 121.8.5.4.  
 SuggestedRemedy  
 Change TBD in Table 180-18 to 0.  
 Delete the associated editors note.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #186

Cl 181 SC 181.9.5 P454 L4 # 173  
 Johnson, John Broadcom  
 Comment Type TR Comment Status A SER  
 The TDECQ test method points to clause 121.8.5.3, which uses a target SER of 4.8e-4, which is not appropriate for 200G/lane AUIs. As given in Table 174A-1, the appropriate value for 200G/lane AUIs should be 4.56e-4 for uncorrelated bit errors.  
 SuggestedRemedy  
 Add a new exception to the list:  
 "Target PAM4 symbol error ratio of 4.56e-4."  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Add a new exception to the list:  
 "The target PAM4 symbol error ratio is 4.56e-4 and the related Q\_t value is 3.428."  
 Implement with editorial license.

Cl 181 SC 181.9.5 P454 L31 # 174  
 Johnson, John Broadcom  
 Comment Type TR Comment Status A taps  
 In Table 181-13, the minimum number of equalizer pre-cursor taps is TBD. In the absence of further proposals, this value should be 0, consistent with the 5-tap FFE defined in 121.8.5.4.  
 SuggestedRemedy  
 Change TBD in Table 181-13 to 0.  
 Delete the associated editors note.  
 For the editor's consideration: If the specs are identical, delete Table 181-13 completely and refer to Table 180-18.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #186



EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 182 SC 182.9.5 P483 L25 # 175

Johnson, John Broadcom

Comment Type TR Comment Status A taps

In Table 182-18, the minimum number of equalizer pre-cursor and post-cursor taps is left blank. In the absence of further proposals, this FFE definition should be the same as given in Table 180-18, and the value for minimum pre-cursor taps should be 0, consistent with the 5-tap FFE defined in 121.8.5.4.

*SuggestedRemedy*

Format Table 182-18 to be the same as Table 180-18 (delete the row for number of post-cursor taps), and change the minimum number of pre-cursor taps to 0.

Delete the associated editors note.

For the editor's consideration: If the specs are identical, delete Table 182-18 completely and refer to Table 180-18.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #186

Cl 183 SC 183.9.5 P509 L14 # 176

Johnson, John Broadcom

Comment Type TR Comment Status A taps

In Table 183-14, the minimum number of equalizer pre-cursor taps is TBD. In the absence of further proposals, this value should be 0, consistent with the 5-tap FFE defined in 121.8.5.4.

*SuggestedRemedy*

Change TBD in Table 183-14 to 0.

Delete the associated editors note.

For the editor's consideration: If the specs are identical, delete Table 183-14 completely and refer to Table 180-18.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #186.

Cl 175 SC 175.2.4.6.1 P247 L1 # 181

Brown, Matt Alphawave Semi

Comment Type E Comment Status A (bucket)

The acronym AM (and plural AMs) is used a few times but never defined. Better to just spell it out.

*SuggestedRemedy*

Change "AM" to "alignment marker" is several places at page/line: 247/1, 248/12, 249/42, 249/51,249/54, 251/32 x2, 253/16 x2

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement suggested remedy with editorial license.

Cl 186 SC 186 P576 L6 # 182

Brown, Matt Alphawave Semi

Comment Type E Comment Status A (bucket)

The acronym AMs is used but never defined. Better to just spell it out. Exception is if it is used specifically for a field name of "AM".

*SuggestedRemedy*

Change "AMs" to "alignment markers".

Response Response Status C

ACCEPT IN PRINCIPLE.

Make suggested change throughout clause 186. Implement with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

CI 180 SC 180.9.4 P430 L32 # 186

Brown, Matt

Alphawave Semi

Comment Type T Comment Status A taps

Value for minimum "number of equalizer pre-cursor taps" is TBD.

*SuggestedRemedy*

Either set the the value to 0 allowing the number of pre-cursor taps to vary from 0 to 3 or straddle the minimum/maximum columns with a value of 3, permitting only a value of 3.

Response Response Status C

ACCEPT IN PRINCIPLE.

Based on the results of straw polls TF-1/2/3, in Table 180-18, Table 181-13, Table 182-18, Table 183-14 set the minimum number of pre-cursor taps to 0.

In Table 182-18, delete the row specifying number of post-cursor taps.

Implement with editorial license.

Straw poll #TF-1 (Chicago rules) #TF-2 (choose 1) -- directional

In Table 180-18, Table 181-13, Table 182-18, Table 183-14, I support setting minimum number of pre-cursor taps to:

- A: 0
- B: 1
- C: 2
- D: 3
- TF-1: A: 41 B: 24 C: 21 D: 30
- TF-2: A: 34 B: 7 C: 7 D: 20

Straw poll #TF-3 (choose 1) -- directional

In Table 180-18, Table 181-13, Table 182-18, Table 183-14, I support setting minimum number of pre-cursor taps to:

- A: 0
- B: 3
- A: 43 B: 22

CI 181 SC 181.9.5 P454 L30 # 187

Brown, Matt

Alphawave Semi

Comment Type T Comment Status A taps

Value for minimum "number of equalizer pre-cursor taps" is TBD.

*SuggestedRemedy*

Either set the the value to 0 allowing the number of pre-cursor taps to vary from 0 to 3 or straddle the minimum/maximum columns with a value of 3, permitting only a value of 3.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Resolve using the response to comment #186

CI 183 SC 183.9.5 P509 L14 # 188

Brown, Matt

Alphawave Semi

Comment Type T Comment Status A taps

Value for minimum "number of equalizer pre-cursor taps" is TBD.

*SuggestedRemedy*

Either set the the value to 0 allowing the number of pre-cursor taps to vary from 0 to 3 or straddle the minimum/maximum columns with a value of 3, permitting only a value of 3.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Resolve using the response to comment #186.

CI 182 SC 182.9.5 P483 L25 # 189

Brown, Matt

Alphawave Semi

Comment Type T Comment Status A taps

Value for minimum "number of equalizer pre-cursor taps" is not specified.

*SuggestedRemedy*

Either set the the value to 0 allowing the number of pre-cursor taps to vary from 0 to 3 or straddle the minimum/maximum columns with a value of 3, permitting only a value of 3.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Resolve using the response to comment #186

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 186 SC 186.5 P605 L40 # 192  
 Brown, Matt Alphawave Semi  
 Comment Type T Comment Status R (withdrawn)  
 Delay constraints are TBD.  
 SuggestedRemedy  
 Expect a contribution with proposals.  
 Response Response Status Z  
 REJECT.  
 This comment was WITHDRAWN by the commenter.

Cl 176C SC 176C.5.1 P711 L37 # 203  
 Brown, Matt Alphawave Semi  
 Comment Type E Comment Status A (bucket)  
 46.25 has orange highlight.  
 SuggestedRemedy  
 Remove highlight.  
 Response Response Status C  
 ACCEPT.

Cl 179B SC 179B.4.6 P811 L8 # 216  
 Brown, Matt Alphawave Semi  
 Comment Type E Comment Status A (bucket)  
 It is out of convention to specify a value "Less than xxx".  
 Similar issue in Table 179B-5.  
 SuggestedRemedy  
 Change "Integrated near-end crosstalk noise voltage" to "Integrated near-end crosstalk noise voltage (max)"  
 Change "Less than TBD" to "TBD"  
 Make similar updates in Table 179B-5.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license.  
 Note that comment #217 proposes a value to use in place of TBD.

Cl 176 SC 176.8 P299 L6 # 222  
 de Koos, Andras Microchip Technology  
 Comment Type T Comment Status A PMA delay  
 For Table 176-6, the delay of the 1:8 and 8:1 (for 200GBASE-R) and 2:16 and 16:2 (for 400GBASE-R) PMAs is complicated because of the 2CW skew introduced. Must be careful to avoid double-accounting the delay due to this skew! The max delay constraint (which is for the \*sum\* of Rx and Tx) should thus be calculated as the max base delay plus the intentional skew, (not 2x the intentional skew). This way, the total constraint will count the skew's contribution only once.

SuggestedRemedy  
 For the 1:8, 8:1, PMAs use the base max delay value (same as the 800GBASE-R 4:32 PMA or 32:4 PMA, presumably?) plus the intentional skew.  
 Skew = 2 FEC CWs = 51.2ns for 200Gbps  
 200GBASE-R 1:8 PMA or 8:1 PMA :  
 Maximum (bit time): 36864 + 40960 = 77824  
 Maximum (pause\_quanta): 72 + 80 = 152  
 Maximum (ns): 46.08 + 51.2 = 97.28  
 For the 2:16, 16:2, PMAs use the base max delay value (same as the 800GBASE-R 4:32 PMA or 32:4 PMA, presumably?) plus the intentional skew.  
 Skew = 2 FEC CWs = 25.6ns for 400Gbps

400GBASE-R 2:16 PMA or 16:2 PMA :  
 Maximum (bit time): 36864 + 20480 = 57334  
 Maximum (pause\_quanta): 72 + 40 = 112  
 Maximum (ns): 46.08 + 25.6 = 71.68  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #451.

Cl 176 SC 176.8 P299 L6 # 223  
 de Koos, Andras Microchip Technology  
 Comment Type T Comment Status A PMA delay  
 Should the 4-codeword deskew (compensating for skew across an AUI) be included in the PMA delay constraint? I think not. This should be seen as the delay of the AUI itself, and should not be included in the PMA's delay constraint.

SuggestedRemedy  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #451.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 176 SC 176.8 P299 L21 # 224

de Koos, Andras

Microchip Technology

Comment Type T Comment Status A PMA delay

Whatever method is used to specify the max delay for the 1:8, 8:1, 2:16, 16:2 SM-PMAs in Table 176-6, a footnote to the table is required to explain the method. Otherwise, readers may get confused: looking at the delay through the Rx PMA in isolation, and the Tx PMA in isolation, one could conclude that they should each have a 2CW delay for the skew.

*SuggestedRemedy*

Add the following note after the table:

Note that since the delay constraint is respect to the sum of Rx and Tx delays, the intentional skew for the 1:8 and 8:1 PMAs (51.2ns) and for the 2:16 and 16:2 PMAs (25.6ns) contributes only ONCE.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #451.

Cl 176 SC 176.8 P299 L6 # 225

de Koos, Andras

Microchip Technology

Comment Type T Comment Status A PMA delay

The max delay values for the '1.6TBASE-R 8:16 PMA or 16:8 PMA' should be roughly equal to those of the 800GBASE-R 4:32 PMA or 32:4 PMA. It is true that the 1.6T PMA does not have the 'Delay odd PCSs by one symbol' function (176.4.2.4.1), but the latency of one 10-bit symbol is negligible in the context of these delays.

*SuggestedRemedy*

For the '1.6TBASE-R 8:16 PMA or 16:8 PMA' delay constraints, use the same values as the '800GBASE-R 4:32 PMA or 32:4 PMA'

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #451.

Cl 176 SC 176.8 P299 L6 # 226

de Koos, Andras

Microchip Technology

Comment Type T Comment Status A PMA delay

In the table, why is the value for a 4:4 PMA so large (2x the 4:32 / 32:4 PMA)? Wouldn't it just be a wire?

Is it because it could reasonably be implemented with a 4:32 PMA in series with a 32:4 PMA?

Assuming the 4:4 PMA value is correct, the same rules can be used for the 1:1, 2:2 and 8:8 PMAs, i.e double the values of the 1:8, 2:16 , and 8:16 PMA, respectively.

*SuggestedRemedy*

For the '200GBASE-R 1:1 PMA' delay constraint values, double the delay constraint values of the '200GBASE-R 1:8 PMA or 8:1 PMA' delay constraints.

For the '400GBASE-R 2:2 PMA' delay constraint values, double the delay constraint values of the '400GBASE-R 2:16 PMA or 16:2 PMA' delay constraints.

For the '1.6TBASE-R 8:8 PMA' delay constraint values, double the delay constraint values of the '1.6TBASE-R 8:16 PMA or 16:8 PMA' delay constraints.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #451.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 180 SC 180.3 P412 L15 # 227

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status A signal ok

Signal\_OK as shown in Fig 180-2 is from the Inner sublayer above then goes into ILT box on TX and another ILT box on the RX has Signal\_OK out. We talk about Signal\_OK then jump into inter-suplayer variables before intorudcing ILT.

*SuggestedRemedy*

Referencing Fig 180-2 would be helfull here. After the 1st paragraph add sentence: The PMD in this clause support Inter-sublayer Layer Training (ILT) type O1, see Annex 178B.

Response Response Status C

ACCEPT IN PRINCIPLE.

A definitive statement as proposed in the suggested remedy is beyond the intent of the service interface clause, which is defining interfaces between sublayers.

However, it would be helpful to the reader to point out references for each of the major functions in the block diagram.

In 180.3, change "training\_status of the inter-sublayer training function" to "training\_status of the inter-sublayer training (ILT) function (see 180.5.12)". Update 181.3, 182.3, 183.3 in a similar way.

In 180.5.1 add text pointing out reference to subclauses defining these. Update , 181.5.1, 182.5.1, and 183.5.2 in similar way.

Implement with editorial license.

Cl 181 SC 181.3 P440 L2 # 228

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status A signal ok

Signal\_OK as shown in Fig 180-2 is from the Inner sublayer above then goes into ILT box on TX and another ILT box on the RX has Signal\_OK out. We talk about Signal\_OK then jump into inter-suplayer variables before intorudcing ILT.

*SuggestedRemedy*

Referencing Fig 180-2 would be helfull here. After the 1st paragraph add sentence: The PMD in this clause support Inter-sublayer Layer Training (ILT) type O1, see Annex 178B.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #227

Cl 182 SC 182.3 P465 L6 # 229

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status A signal ok

Signal\_OK as shown in Fig 180-2 is from the Inner sublayer above then goes into ILT box on TX and another ILT box on the RX has Signal\_OK out. We talk about Signal\_OK then jump into inter-suplayer variables before intorudcing ILT.

*SuggestedRemedy*

Referencing Fig 180-2 would be helfull here. After the 1st paragraph add sentence: The PMD in this clause support Inter-sublayer Layer Training (ILT) type O1, see Annex 178B.

Response Response Status C

ACCEPT IN PRINCIPLE.

See resolution to comment #227

Cl 183 SC 183.3 P494 L6 # 230

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status A signal ok

Signal\_OK as shown in Fig 180-2 is from the Inner sublayer above then goes into ILT box on TX and another ILT box on the RX has Signal\_OK out. We talk about Signal\_OK then jump into inter-suplayer variables before intorudcing ILT.

*SuggestedRemedy*

Referencing Fig 180-2 would be helfull here. After the 1st paragraph add sentence: The PMD in this clause support Inter-sublayer Layer Training (ILT) type O1, see Annex 178B.

Response Response Status C

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #227

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl **180** SC **180.9.5** P**430** L**22** # **240**

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type **TR** Comment Status **A** TDECQ

TDECQ masuremnt needs to define test condition when there is an optional AUI

*SuggestedRemedy*

Add following codition to the list of requiremetns in 180.9.5: Where AUI is exposed, a conforming implementation must meet TDECQ with the exposed AUI configured for applicable module stress input test as in 176C.4.4.5 Receiver jitter tolerance, 120G.3.4.3 Module stressed input tolerance, or 120E.3.4.1 Module stressed input test and the recovered AUI clock driving the TDECQ pattern. See Ghiasi\_3dj\_01\_2501

Response Response Status **C**

ACCEPT IN PRINCIPLE.

The following contribution was reviewed by the CRG:  
[https://www.ieee802.org/3/dj/public/25\\_01/ghiasi\\_3dj\\_01a\\_2501.pdf](https://www.ieee802.org/3/dj/public/25_01/ghiasi_3dj_01a_2501.pdf)

Add the following TDECQ exceptions to be appropriately reworded:

- Counter-propagating asynchronous optical signals (crosstalk) as specified for the aggressor used in receiver stress tests is applied to all the PMD receive inputs at TP3. For Clause 180/181, the crosstalk test pattern can be pattern 3, 5, or 7. For Clause 182/183, the crosstalk pattern can be pattern 5 or 7.

Note that another comment proposes adding a new pattern: PRBS31 encoded by the xBASE-R Inner FEC, which if adopted may also be used for Clause 182/183.

- Where transmit direction where AUI is exposed, the AUI input recovered clock is the clock source for the SSPRQ test pattern. The AUI pattern may be either PRBS31Q or a valid xBASE-R signal.

Implement with editorial license.

Straw poll TF-4 (choose 1) -- directional

I support adoption of additional criteria for TDECQ where counter-progagating signals with data stream asynchronous with the transmit path are applied to the receive optical inputs as proposed in ghiasi\_3dj\_01.

Yes: 48

No: 18

Straw poll TF-5 -- directional

I support adoption of additional criteria for TDECQ where PMD transmit clock is synchronized to the clock recovered on the AUI input (with or without jitter stress) as proposed in ghiasi\_3dj\_01.

Yes: 42

No: 24

Straw poll TF-6 -- decision

I support adopting exception "- Counter-propagating asynchronous optical signals (crosstalk) as specified for the aggressor used in receiver stress tests is applied to all the PMD receive inputs at TP3. For Clause 180/181, the crosstalk test pattern can be pattern 3, 5, or 7. For Clause 182/183, the crosstalk pattern can be pattern 5 or 7."

Yes: 47

No: 20

Straw poll TF-7 -- decision

I support adopting TDECQ exception "- Where transmit direction where AUI is exposed, the AUI input recovered clock is the clock source for the SSPRQ test pattern. The AUI pattern may be either PRBS31Q or a valid xBASE-R signal.

Yes: 38

No: 28

Cl **181** SC **181.9.5** P**454** L**22** # **241**

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type **TR** Comment Status **A** TDECQ

TDECQ masuremnt needs to define test condition when there is an optional AUI

*SuggestedRemedy*

Add following codition to the list of requiremetns in 180.9.5: Where AUI is exposed, a conforming implementation must meet TDECQ with the exposed AUI configured for applicable module stress input test as in 176C.4.4.5 Receiver jitter tolerance, 120G.3.4.3 Module stressed input tolerance, or 120E.3.4.1 Module stressed input test and the recovered AUI clock driving the TDECQ pattern. See Ghiasi\_3dj\_01\_2501

Response Response Status **C**

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #240

Cl **182** SC **182.9.5** P**483** L**17** # **242**

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type **TR** Comment Status **A** TDECQ

TDECQ masuremnt needs to define test condition when there is an optional AUI

*SuggestedRemedy*

Add following codition to the list of requiremetns in 180.9.5: Where AUI is exposed, a conforming implementation must meet TDECQ with the exposed AUI configured for applicable module stress input test as in 176C.4.4.5 Receiver jitter tolerance, 120G.3.4.3 Module stressed input tolerance, or 120E.3.4.1 Module stressed input test and the recovered AUI clock driving the TDECQ pattern. See Ghiasi\_3dj\_01\_2501

Response Response Status **C**

ACCEPT IN PRINCIPLE.

Resolve using the response to comment #240

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 183 SC 183.9.5 P509 L4 # 243

Ghiasi, Ali Ghiasi Qunatum/Marvell  
 Comment Type TR Comment Status A TDECQ

TDECQ masuremnt needs to define test condition when there is an optional AUI

SuggestedRemedy

Add following codition to the list of requiremetns in 180.9.5: Where AUI is exposed, a conforming implementation must meet TDECQ with the exposed AUI configured for applicable module stress input test as in 176C.4.4.5 Receiver jitter tolerance, 120G.3.4.3 Module stressed input tolerance, or 120E.3.4.1 Module stressed input test and the recovered AUI clock driving the TDECQ pattern. See Ghiasi\_3dj\_01\_2501

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #240

Cl 183 SC 183.9.5 P509 L14 # 248

Ghiasi, Ali Ghiasi Qunatum/Marvell  
 Comment Type TR Comment Status A taps

Number of pre-cursor is maximum with min TBD

SuggestedRemedy

What was agreed during Sept 2024 meeting to go with fixed 3 pre-cursors and not a floating at least for now, given than agreement merge the TBD and max line and just enter 3 similar to FFE length of 15.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #186.

Cl 182 SC 182.9.5 P483 L25 # 249

Ghiasi, Ali Ghiasi Qunatum/Marvell  
 Comment Type TR Comment Status A taps

Number of pre-cursor is not maximum but rather just 3

SuggestedRemedy

What was agreed during Sept 2024 meeting to go with fixed 3 pre-cursors and not a floating at least for now, given than agreement merge the cell with max cell and just enter 3 similar to FFE length of 15.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #186

Cl 181 SC 181.9.5 P454 L30 # 250

Ghiasi, Ali Ghiasi Qunatum/Marvell  
 Comment Type TR Comment Status A taps

Number of pre-cursor is maximum with min TBD

SuggestedRemedy

What was agreed during Sept 2024 meeting to go with fixed 3 pre-cursors and not a floating at least for now, given than agreement merge the TBD and max line and just enter 3 similar to FFE length of 15.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #186

Cl 180 SC 180.9.5 P430 L30 # 251

Ghiasi, Ali Ghiasi Qunatum/Marvell  
 Comment Type TR Comment Status A taps

Number of pre-cursor is maximum with min TBD

SuggestedRemedy

What was agreed during Sept 2024 meeting to go with fixed 3 pre-cursors and not a floating at least for now, given than agreement merge the TBD and max line and just enter 3 similar to FFE length of 15.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #186

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 1 SC 1.4.92a P53 L10 # 269

Ran, Adeo Cisco  
 Comment Type E Comment Status R (withdrawn)

The definition of 1.6TAUI-n includes "used for chip-to-chip or chip-to-module electrical interfaces" followed by "For chip-to-module interfaces and for chip-to-chip interfaces". This duplicity is not helpful.

Following the new descriptions introduced in the new AUI annexes, the clarity of this definition can be improved.

Similar concerns exist in the definitions of 200GAUI-n, 400GAUI-n, and 800GAUI-n.

*SuggestedRemedy*

Change the definition text to:  
 "A physical instantiation of the PMA service interface over n lanes, enabling partitioning of a 1.6 Tb/s Physical Layer implementation across multiple devices. Specified separately for chip-to-chip and chip-to-module electrical interfaces. Two widths of 1.6TAUI-n are defined: 16-lane (1.6TAUI-16 C2C and 1.6TAUI-16 C2M), and eight-lane (1.6TAUI-8 C2C and 1.6TAUI-8 C2M)."

Apply corresponding changes in the definitions of 200GAUI-n, 400GAUI-n, and 800GAUI-n.

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

Cl 45 SC 45.2.1 P70 L7 # 271

Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)

The base text of 45.2.1 includes references to multiple PMA sublayers and how MMD addresses are allocated. This text points to 83.1.4, 109.1.4, and 120.1.4, but does not include the corresponding references to the new PMAs: 173.1.4 (apparently missed by 802.3df) and 176.11.

*SuggestedRemedy*

Bring in the first paragraph of 45.1.2 and add references to 173.1.4 and 176.11.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Bring in the first paragraph of 45.2.1 from the base standard and add references to 173.1.4 and 176.1.5

Cl 45 SC 45.2.1 P70 L7 # 272

Ran, Adeo Cisco  
 Comment Type T Comment Status R (bucket)

Inner FEC registers are contained in the PMA/PMD section but there is no reference to the inner FEC positioning in the stack, nor to the clauses where it is defined (177 and 184).

*SuggestedRemedy*

Add test describing the inner FEC MDIO positioning (in the same MMD as the PMD).

Response Response Status C

REJECT.  
 There is precedence for having FEC control and status registers in the PMA/PMD address space and the positioning of this FEC functionality is not called out in 45.2.1. There is no justification for making an exception for the inner FEC registers.

Cl 00 SC 0 P261 L47 # 273

Ran, Adeo Cisco  
 Comment Type TR Comment Status A Management interface

"If the MDIO Interface is not implemented, provision of an equivalent mechanism to access the variables is recommended."  
 This sentence is repeated in multiple clauses and annexes (14 instances).

Access to the management variables is required ("shall") if MDIO is implemented, but otherwise it is only recommended to have them accessible.

MDIO is optional but access to the management variables should be a requirement even if it is not implemented.

*SuggestedRemedy*

Change "provision of... is recommended" to "shall be provided", with editorial license, in all instances

Response Response Status C

ACCEPT IN PRINCIPLE.  
 In 175.8, 176.11, 177.10, 178.13, 179.14, 180.11, 181.11, 182.11, 184.9, 185.11, 186.7, 187.11, and 178B.15.  
 Change "If the MDIO Interface is not implemented, provision of an equivalent mechanism to access the variables is recommended."  
 To: "If the MDIO Interface is not implemented, an alternate mechanism to access management variables shall be provided."  
 Implement with editorial license.



EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

CI 177 SC 177.4.1 P309 L32 # 276  
 Ran, Adee Cisco  
 Comment Type ER Comment Status A (bucket)  
 "4-symbol" is used only here, elsewhere the term "symbol quartet" is used instead.  
 SuggestedRemedy  
 Change to "symbol quartet"  
 Response Response Status C  
 ACCEPT.

CI 177 SC 177.4.1.5 P311 L15 # 277  
 Ran, Adee Cisco  
 Comment Type T Comment Status A (bucket)  
 The reader may be curious why symbol multiplexing is not performed for 200GBASE-R and 400GBASE-R PHYs.  
 This is because the data on each PCS lane already includes 4-way RS-FEC interleaving performed by the PMA (as illustrated in Figure 176–6). But that may be difficult to understand if not stated explicitly.  
 SuggestedRemedy  
 Add an informative note at the end of 177.4.1.5:  
 "NOTE--In 200GBASE-R and 400GBASE-R PHYs, this operation is not required, since the output of the PMA below the PCS is already symbol multiplexed with 4-way interleaving (see Figure 176–6)."  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

CI 177 SC 177.4.2 P311 L24 # 278  
 Ran, Adee Cisco  
 Comment Type T Comment Status R (withdrawn)  
 The last delay line (labeled "Delay Line 2") is actually not a delay line.  
 The interleaver can be described as being composed of three data paths, of which the first two include delay lines (0 and 1) and the third does not.  
 SuggestedRemedy  
 Rephrase the text in this subclause and change Figure 177-4 per this comment, changing "Delay Line n" to "interleaver path n".  
 Implement any additional edits required by this change with editorial license.  
 Response Response Status Z  
 REJECT.  
 This comment was WITHDRAWN by the commenter.

CI 177 SC 177.4.2 P311 L26 # 279  
 Ran, Adee Cisco  
 Comment Type ER Comment Status A (bucket)  
 Commas are missing in the 4 paragraphs about delay lines, and periods are inconsistent.  
 SuggestedRemedy  
 In the first paragraph, add commas after "200GBASE-R" and before "and the last line". Similarly for the other 3 paragraphs.  
 Add a period at the end of the second and third paragraphs.  
 Response Response Status C  
 ACCEPT.

CI 177 SC 177.4.4 P312 L34 # 280  
 Ran, Adee Cisco  
 Comment Type ER Comment Status A (bucket)  
 The last sentence in 177.4.4 is "Within each RS-FEC symbol, bit 0 is transmitted first and bit 9 is transmitted last". The transmission order is relevant for the 120-bit block creation, not for the circular shift (circular shift would be the same regardless of the bit order within a symbol).  
 SuggestedRemedy  
 Move the quoted sentence to 177.4.3.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.4.5 P313 L24 # 281  
 Ran, Adee Cisco  
 Comment Type ER Comment Status A (bucket)  
 Missing commas  
 SuggestedRemedy  
 Add a comma after "flows".  
 Add commas before and after "m<119:0>".  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.4.5 P313 L51 # 282  
 Ran, Adee Cisco  
 Comment Type ER Comment Status A (bucket)  
 the integer i is a scalar, not a vector, so it should not be in boldface here (it is not bold in other instances)..  
 SuggestedRemedy  
 Remove the boldface format from i.  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.4.5 P313 L51 # 283  
 Ran, Adee Cisco  
 Comment Type TR Comment Status A (bucket)  
 "(s<sub>0,i</sub>, s<sub>1,i</sub>, s<sub>2,i</sub>, s<sub>3,i</sub>, s<sub>4,i</sub>, s<sub>5,i</sub>, s<sub>6,i</sub>) is the binary vector corresponding to the element  $\alpha_i$  in the Galois Field GF(2<sup>7</sup>) with primitive polynomial  $x^7 + x^3 + 1$ "  
 This reads as if the s bits are the binary representation of the 128 elements of the field - but per Equation 177-2 these are actually the binary coefficients in the linear combination of  $\alpha_0$  through  $\alpha_6$  that creates  $\alpha_i$ . I suspect these are not the same.  
 SuggestedRemedy  
 Move the quoted sentence after the subsequent one (which states that the elements can be expressed as a linear combination), and change "binary vector corresponding to" to "binary coefficients of the linear combination that creates".  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.4.5 P314 L1 # 284  
 Ran, Adee Cisco  
 Comment Type ER Comment Status A (bucket)  
 The second sentence in the first paragraph spans 5 lines and includes 6 commas, 3 instances of "and", and 2 instances of "where". It is difficult to follow.  
 It also includes "first", but there seems to be no further steps.  
 SuggestedRemedy  
 Rewrite this sentence, preferably breaking it into more readable pieces.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.4.7 P315 L10 # 285  
 Ran, Adee Cisco  
 Comment Type TR Comment Status A (bucket)  
 "The rate... is..."  
 The exact rate depends on the input rate which has some tolerance.  
 It would be helpful for the reader to write the ratio of the output rate and the input rate. This information should preferably be placed in the "summary of functions" in 117.1.3 as well.  
 SuggestedRemedy  
 Change "the rate" to "the nominal rate".  
 Add a statement about the ratio, here and in 177.1.3.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.4.9 P317 L4 # 286

Ran, Adeo Cisco  
 Comment Type TR Comment Status A (bucket)

"These test patterns are used to test adjacent layer interfaces or to perform testing between an Inner FEC and external testing equipment"

Which adjacent layer interfaces? and what is "testing between"?

These generators are only in the output direction, so they can only be used to drive the PMD service interface (which is then used with external testing equipment).

*SuggestedRemedy*

Change to  
 "If implemented, these test patterns can be used to drive the PMD service interface for PMD testing purposes".

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.4.9 P317 L5 # 287

Ran, Adeo Cisco  
 Comment Type TR Comment Status A (bucket)

It is not specified what happens when more than one generator is enabled on the same lane.  
 The definitions in clause 120 which are referenced include different control variables and MDIO mappings, and the case where two are enabled is only covered in 45.2.1.170.

Note that some of the patterns in clause 120 are not per-lane but here all patterns have enable bits per lane.

*SuggestedRemedy*

Add text in 177.4.9 stating that all generators are per-lane, that enabling any of the pattern generators on a lane affects only that lane, and that the behavior when more than one generator is enabled on the same lane is not specified.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.2 P318 L7 # 289

Ran, Adeo Cisco  
 Comment Type TR Comment Status A (bucket)

"Blind 1:8 bit-pair deinterleaving (each pair of bits corresponding to a PAM4 symbol) is performed to eight Inner FEC flows"

It is unclear what "blind" refers to in this operation. "blind" is not defined in 802.3 and its occasional use is inconsistent.

Perhaps "initial" is more adequate here.

*SuggestedRemedy*

Change "blind" to "initial" in the quoted sentence and the one with the other instance of "blind" in this subclause.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Change the first sentence to:  
 "1:8 bit-pair deinterleaving (each pair of bits corresponding to a PAM4 symbol) is performed to eight Inner FEC flows. The initial position is not specified."

Cl 177 SC 177.5.2 P318 L7 # 290

Ran, Adeo Cisco  
 Comment Type TR Comment Status A (bucket)

The initial ("blind") deinterleaving and synchronization is performed on bit pairs, since they cannot rely on the FEC decoder.  
 The source of the bit pairs is likely hard decoding of the input symbols into PAM4 and then into bits.  
 However, the same deinterleaving is later performed on the input symbols, which are more than bit pairs. This is currently not stated.

*SuggestedRemedy*

Add text stating that the alignment found by the initial synchronization based on the PAM4 hard decoding is used for deinterleaving of soft inputs into the Inner FEC decoding.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.5.4 P319 L10 # 291

Ran, Adeo Cisco  
 Comment Type E Comment Status A (bucket)

"The Inner FEC decoder is a soft-decision decoder that requires a higher resolution than two bits for each received PAM4 symbols"

Wording can be improved.

*SuggestedRemedy*

Change to  
 "The Inner FEC decoding assumes soft-decision operation that requires a resolution of more than two bits for each received symbol".

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.4 P319 L11 # 292

Ran, Adeo Cisco  
 Comment Type TR Comment Status A (bucket)

The assumed correction capability of the decoder is not stated.  
 Also, it is not stated what happens when a codeword is uncorrectable. I assume the decoder does not mark the data as error in any way (since it is an inner code) but it is not stated. The error patterns that appear in this case are not described.

Compare to the RS-FEC decoder specification in 91.5.3.3 (where there are normative specifications for correction capability and uncorrectable error marking).

This is important information for testing, monitoring and analyzing the performance of an implementation.

The suggested remedy is based on slide 9 of  
[https://www.ieee802.org/3/df/public/22\\_05/22\\_0517/bliss\\_3df\\_01a\\_220517.pdf](https://www.ieee802.org/3/df/public/22_05/22_0517/bliss_3df_01a_220517.pdf).

*SuggestedRemedy*

Add some test e.g.  
 "The decoder is expected to correct all codewords in which hard decision would result in up to one bit error and most codewords with up to three bit errors. Codewords that are not decoded correctly will contain at least four bit errors"  
 Or modifications of the above if necessary.

If there is no consensus for additional text (either the one above or otherwise), add an editor's note inviting contributions in this area.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.4 P319 L11 # 293

Ran, Adeo Cisco  
 Comment Type TR Comment Status A (bucket)

"The decoder evaluates the incoming codeword and determines the most likely codeword value"

Then input to the decoder is not a codeword (a codeword is a member of a set of 128-bit vectors). The input is a vector of "soft" samples that corresponds to a transmitted codeword.

*SuggestedRemedy*

Change to "The decoder evaluates the incoming block of 64 rx\_symbol inputs and determines the most likely codeword value".

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

Cl 177 SC 177.5.4.1.1 P319 L21 # 294

Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)

"The output of the Inner FEC decoder will recognize the miscorrected codewords as corrected codewords."

The output is not a separate entity, it is a block of 120 bits that has no information about the type of codeword it came from. The counter is internal to the decoder.

*SuggestedRemedy*

Change to  
 "The Inner FEC decoder will treat any miscorrected codeword as a corrected codeword."

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Change to:  
 "The Inner FEC decoder interprets miscorrected codewords as corrected codewords."  
 Implement with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.6.2.1 P320 L34 # 296

Ran, Adee Cisco  
 Comment Type ER Comment Status A (bucket)

The definition of all\_synced does not (strictly) cover the case where sync\_flow<x> is true for all eight flows but the Inner FEC flow 0 is not identified.  
 Also, "and" here has no special meaning and should not be capitalized.

SuggestedRemedy

Change "set to false when sync\_flow<x> is false for any x" to "set to false otherwise".  
 Change "AND" to "and".

Response Response Status C

ACCEPT.

Cl 177 SC 177.10. P325 L9 # 298

Ran, Adee Cisco  
 Comment Type TR Comment Status A (bucket)

Table 177-6 includes control variables for per-lane inner FEC enable. As stated in the editor's note, these variables are not defined.

There idea of disabling the FEC and the behaviors of the encoder and decoder in this state have never been discussed.

If the intent is to have a way to power down the FEC logic, then the adjacent PMD's output enable and signal detect functions can be used. However, this would not be observable and need not be specified in a standard.

SuggestedRemedy

Delete the "Inner FEC enable" control variables in table 177-6 and the corresponding MDIO registers in clause 45.

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #1.

Cl 177 SC 177.10. P325 L39 # 299

Ran, Adee Cisco  
 Comment Type TR Comment Status A (bucket)

The status variable name "pml\_locked\_demux" is not mentioned in the referenced 177.4.1.2. It is defined in 176.4.4.2.1.  
 Also, it is a per-lane variable.

SuggestedRemedy

Either change the cross-reference to clause 176, or add text in 177.4.1.2 that the inner FEC has separate status variables for this function (only in the transmit direction? Or both?)  
 Add "lane 0 through 7".

Response Response Status C

ACCEPT IN PRINCIPLE.  
 Change the cross reference to clause 176, and implement with editorial license.

Cl 00 SC 0 P338 L30 # 302

Ran, Adee Cisco  
 Comment Type T Comment Status R (withdrawn)

The Skew and Skew Variation at SP2 are specified with the words "is limited to", while for all other measurement points it is specified with "shall be less than".  
 "is limited to" reads like an informative statement, but it is a normative requirement (it is not related to the fact that SP2 may not be accessible; the same is true for SP5).

This wording appears in multiple places in the draft (per PMD and data rate). Note that the same wording is used in multiple clauses of the base standard. If necessary, it can be dealt with in maintenance.

SuggestedRemedy

Change "is limited to" to "shall be less than" in all instances of Skew and Skew variation at SP2.

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 179 SC 179.12 P399 L21 # 315

Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)

The PMD is specified in 179.8 and 179.9. 179.14 contains management variable mapping and is irrelevant here.

SuggestedRemedy

Change the reference per the comment.

Response Response Status C

ACCEPT.

Cl 180 SC 180.5.4 P415 L1 # 318

Ran, Adeo Cisco  
 Comment Type TR Comment Status A (bucketp)

"The state of the Global\_PMD\_signal\_detect variable is conveyed to PMD client sublayers via the PMD service interface"

This is not true anymore; the service interface conveys the state of the ILT function (as shown in the diagram). The variable has a different semantic and is only accessible through management.

SuggestedRemedy

Delete the quoted sentence.

Implement similarly in other optical PMD clauses as necessary, with editorial license.

Response Response Status C

ACCEPT.

Cl 180 SC 180.7.1 P418 L12 # 319

Ran, Adeo Cisco  
 Comment Type T Comment Status R (withdrawn)

The maximum optical return loss tolerance in 200GBASE-DR1 is different than in the other PMDs.

I assume this is due to the transmitter's connector; if that's true, should there be a different specification for a 200GBASE-DR1 with a multi-fiber MDI (breakout)? The receiver in that case can still have a single-lane MDI.

Should the transmitter's RINxxOMA in this case be measured with a reflectance corresponding to a single-lane MDI?

SuggestedRemedy

Not sure what the answer is and where this distinction should be made.

Whatever the solution is, implement similarly in clause 182 as necessary, with editorial license.

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

Cl 180 SC 180.8 P421 L41 # 321

Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)

The words "shall meet the" appear twice in succession.

SuggestedRemedy

Delete once.

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 180 SC 180.8 P421 L42 # 322

Ran, Adeo Cisco

Comment Type TR Comment Status A (bucket)

"per the definitions in 180.9" seems irrelevant. There are not specifications related to Table 180-10 in 180.9.

SuggestedRemedy

Delete "per the definitions in 180.9".

Implement similarly in other optical PMD clauses as necessary, with editorial license.

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement suggested remedy with editorial license.

Cl 180 SC 180.8.3.1.1 P424 L1 # 328

Ran, Adeo Cisco

Comment Type ER Comment Status A (bucket)

Table 180-14 is for 800GBASE-DR4.

SuggestedRemedy

Change the reference to Table 180-13.

Response Response Status C

ACCEPT.

Cl 180 SC 180.9.5 P430 L35 # 331

Ran, Adeo Cisco

Comment Type TR Comment Status A (bucket)

Footnote a of Table 180-18 says "Relative to main tap".

"Main tap" is not defined anywhere, though it may be assumed that it is the largest positive value.

Even with that assumption, It is unclear whether this means that the coefficient limits are normalized by the main tap's coefficient or that the coefficient indices are such that the main tap index is 0, or both.

I suspect the answer is "both" but it is not clear from the text.

SuggestedRemedy

Change footnote a to read "The main tap is marked by  $i=0$ . The minimum and maximum values are relative to this tap's coefficient."

Implement similarly in other optical PMD clauses as necessary, with editorial license.

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement suggested remedy (also in 181, 182, and 183) with editorial license.

[Editor's note: CC: 180, 181, 182, 183]

Cl 180 SC 180.10.1 P433 L47 # 336

Ran, Adeo Cisco

Comment Type ER Comment Status A (bucket)

Why is "IEC 62368-1" in green? It is not expected to become an active cross-reference.

Similarly for IEC references in 180.10.2.

SuggestedRemedy

Change the format of these references to regular text.

Implement similarly in other optical PMD clauses as necessary, with editorial license.

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 180 SC 180.11 P435 L46 # 337  
 Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)  
 "PMD\_signal\_detect\_3, to PMD\_signal\_detect\_2"  
 SuggestedRemedy  
 Delete "to".  
 Implement similarly in other optical PMD clauses as necessary, with editorial license.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license

Cl 181 SC 181.1 P438 L49 # 338  
 Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)  
 169.2 is included in this amendment.  
 SuggestedRemedy  
 Make it an active link.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license.

Cl 181 SC 181.3 P440 L6 # 339  
 Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)  
 "where i = 0 to n-1"  
 For this PMD, the number of PMD lanes is always 4 (as stated on the subsequent line).  
 Using "n" just makes life harder for the reader, especially since n (with this meaning) only  
 appears a few times in the clause, and in some places (e.g. Figure 181-2, 181.5.2, 181.5.3)  
 explicit numbers are used.  
 Note that the "n" in 800GAUI-n is a different variable and should be kept as is.  
 SuggestedRemedy  
 Change to "where i = 0 to 3".  
 Delete "The number of parallel streams, n, is 4."

In 181.5.4 change n to 4.  
 In 181.5.5, in Table 181-15, and in Table 181-16, change "n-1" to 3.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license.

Cl 181 SC 181.4.1 P440 L25 # 340  
 Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)  
 169.4 is included in this amendment.  
 SuggestedRemedy  
 Make it an active link.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license.

Cl 181 SC 181.4.2 P440 L28 # 341  
 Ran, Adeo Cisco  
 Comment Type ER Comment Status A (bucket)  
 169.5 is included in this amendment.  
 SuggestedRemedy  
 Make it an active link (twice).  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license.



Cl 182 SC 182.9.5 P483 L1 # 346

Ran, Adee Cisco

Comment Type TR Comment Status A SER

"Target PAM4 symbol error ratio of  $9.6 \times 10^{-3}$ "  
 If this value is used instead of  $4.8e-4$  as TDECQ was originally defined, then TDECQ of an ideal transmitter would be negative, because the normalization factor  $Q_t$  is "consistent with the BER and target symbol error ratio for Gray coded PAM4" (which is  $4.8e-4$ ).

This makes TDECQ something other than a "penalty" as it is typically understood.

In addition, as demonstrated by several presentations, TDECQ with such high SER is not feasible, as test signal achieving the maximum TDECQ cannot be measured..

It would make more sense to keep the target PAM4 SER as  $4.8e-4$  (with the same  $Q_t$ ) and instead relax the maximum TDECQ value in this clause by a factor corresponding to the lower Q function of the higher SER, to allow a more closed eye:

- For  $SER=4.8e-4$ :  $Q(SER^{*2/3})=-3.414$  (as in 121.8.5.3)

- For  $SER=9.6e-3$ :  $Q(SER^{*2/3})=-2.489$

-  $10 \cdot \log_{10}(3.414/2.489)=1.37$  dB

Thus the relaxation should be 1.37 dB.

*SuggestedRemedy*

Change the target PAM4 SER to  $4.8e-4$ .

Change the maximum TDECQ and TECQ from 3.2 dB to  $3.2+1.37=4.57$  dB.

Make corresponding changes to the receiver specifications (SECQ) in Table 181–6.

Implement similarly in clause 183 with modified values as necessary, with editorial license.

Response Response Status C

ACCEPT IN PRINCIPLE.

Similar as comment #146 to D1.2. A strawpoll was held and it was agreed to maintain the SER value  $9.6 \times 10^{-3}$ . The comment does not contain sufficient evidence that this value not sufficient.

However, the  $Q_t$  value should be adjusted to align with the SER value.

In 182.9.5...

Change: "Target PAM4 symbol error ratio of  $9.6 \times 10^{-3}$ ."

To: "The target PAM4 symbol error ratio is  $9.6 \times 10^{-3}$  and the related  $Q_t$  value is 2.489."

In 183.9.5...

Change: "Target PAM4 symbol error ratio of  $9.6 \times 10^{-3}$  for 800GBASE-FR4 and 800GBASE-LR4"

To: "The target PAM4 symbol error ratio is  $9.6 \times 10^{-3}$  and the related  $Q_t$  value is 2.489."

Implement with editorial license.

Cl 178B SC 178B.5 P766 L33 # 355

Ran, Adee Cisco

Comment Type E Comment Status A (bucket)

The first two paragraphs of 178B.5 are not about the protocol, but about AUI components and PMDs.

They seem to belong to 178B.4, based on its title.

*SuggestedRemedy*

Move these paragraphs to 178B.4.

Response Response Status C

ACCEPT IN PRINCIPLE.

The first paragraph of 178B.5 is related to the section, so it should stay in 178B.5.

Move the second paragraph of 178B.5 to the begining of 178B.4

Implement with editorial license.

Cl 178A SC 178A P757 L26 # 360

Shakiba, Hossein Huawei Technologies Canada

Comment Type T Comment Status R Quantization noise

Add quantization noise.

*SuggestedRemedy*

Add a new sub-section "178A.1.7.6 Quantization Noise". Please refer to slides 2-4 of the supporting document for the proposed sub-section content and text.

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

Cl 178A SC 178A.1.7 P754 L50 # 361

Shakiba, Hossein Huawei Technologies Canada

Comment Type T Comment Status R Quantization noise

Following first comment, Figure 178A-7 should show addition of the quantization noise after the sampler.

*SuggestedRemedy*

Add quantization noise to the figure. Please refer to slide 5 of the supporting document for the proposed change.

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

**Cl 178A**    **SC 178A.1.7**                      **P755**            **L2**            # **362**

Shakiba, Hossein                                      Huawei Technologies Canada

**Comment Type**    **T**                      **Comment Status**    **R**                      **Quantization noise**

Following first comment, Table 178A-9 should include quantization noise parameters.

**SuggestedRemedy**

Add two quantization noise parameters to the table. Please refer to slide 6 of the supporting document for the proposed change.

**Response**                                      **Response Status**    **Z**

REJECT.

This comment was WITHDRAWN by the commenter.

**Cl 178A**    **SC 178A.1.7**                      **P755**            **L15**            # **365**

Shakiba, Hossein                                      Huawei Technologies Canada

**Comment Type**    **T**                      **Comment Status**    **R**                      **Quantization noise**

Following first comment, "sampler" should be replaced with "quantizer".

**SuggestedRemedy**

Change "sampler" to "quantizer".

**Response**                                      **Response Status**    **Z**

REJECT.

This comment was WITHDRAWN by the commenter.

**Cl 178A**    **SC 178A.1.7**                      **P755**            **L19**            # **363**

Shakiba, Hossein                                      Huawei Technologies Canada

**Comment Type**    **T**                      **Comment Status**    **R**                      **Quantization noise**

Following first comment, Equation (178A-14) should include quantization noise PSD.

**SuggestedRemedy**

Add quantization noise PSD to the equation and its description to the descriptions. Please refer to slide 7 of the supporting document for the proposed change.

**Response**                                      **Response Status**    **Z**

REJECT.

This comment was WITHDRAWN by the commenter.

**Cl 178A**    **SC 178A.1.8.1**                      **P757**            **L43**            # **366**

Shakiba, Hossein                                      Huawei Technologies Canada

**Comment Type**    **T**                      **Comment Status**    **R**                      **Quantization noise**

Following first comment, "sampler" should be replaced with "quantizer".

**SuggestedRemedy**

Change "sampler" to "quantizer".

**Response**                                      **Response Status**    **Z**

REJECT.

This comment was WITHDRAWN by the commenter.

**Cl 178A**    **SC 178A.1.7**                      **P754**            **L32**            # **364**

Shakiba, Hossein                                      Huawei Technologies Canada

**Comment Type**    **T**                      **Comment Status**    **R**                      **Quantization noise**

Following first comment, "sampler" should be replaced with "quantizer".

**SuggestedRemedy**

Change "sampler" to "quantizer".

**Response**                                      **Response Status**    **Z**

REJECT.

This comment was WITHDRAWN by the commenter.

**Cl 178A**    **SC 178A.1.8.1**                      **P757**            **L18**            # **367**

Shakiba, Hossein                                      Huawei Technologies Canada

**Comment Type**    **T**                      **Comment Status**    **R**                      **Quantization noise**

Following first comment, quantization noise should be added before sampler output is applied to the feed-forward filter in Figure 178A-9.

**SuggestedRemedy**

Add quantization noise to the figure. Please refer to slide 8 of the supporting document for the proposed change.

**Response**                                      **Response Status**    **Z**

REJECT.

This comment was WITHDRAWN by the commenter.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 178A SC 178A.1.9 P761 L10 # 368  
 Shakiba, Hossein Huawei Technologies Canada  
 Comment Type T Comment Status R Quantization noise  
 Following first comment, Equation (178A-34) should include quantization noise PSD.  
*SuggestedRemedy*  
 Add quantization noise PSD to the equation. Please refer to slide 9 of the supporting document for the proposed change.  
 Response Response Status Z  
 REJECT.  
 This comment was WITHDRAWN by the commenter.

Cl 178A SC 178A.1.10.2 P761 L51 # 369  
 Shakiba, Hossein Huawei Technologies Canada  
 Comment Type T Comment Status R Quantization noise  
 Following first comment, more text should be added to describe the procedure for deriving the probability density function of the quantization noise and its addition to the probability distribution function of the noise and interference.  
*SuggestedRemedy*  
 Add the suggested text in slides 10-11 of the supporting document before the last sentence of the paragraph.  
 Response Response Status Z  
 REJECT.  
 This comment was WITHDRAWN by the commenter.

Cl 178A SC 178A.1.11 P762 L39 # 370  
 Shakiba, Hossein Huawei Technologies Canada  
 Comment Type T Comment Status R Quantization noise  
 Following first comment, quantization noise should be added before sampler output is applied to the feed-forward filter in Figure 178A-10.  
*SuggestedRemedy*  
 Add quantization noise to the figure. Please refer to slide 12 of the supporting document for the proposed change.  
 Response Response Status Z  
 REJECT.  
 This comment was WITHDRAWN by the commenter.

Cl 176B SC 176B.3 P683 L12 # 378  
 D'Ambrosia, John Futurewei, U.S. Subsidiary of Huawei  
 Comment Type E Comment Status A (bucket)  
 This subclause is included to highlight the co-existence of bit and symbol muxing in an implementation, but the figure uses generic language for the PMA sublayers that doesn't help.  
*SuggestedRemedy*  
 Add "BM-" or "SM-" as appropriate to the PMA sublayer boxes in Fig 176B-4.  
 Response Response Status C  
 ACCEPT.

Cl 179B SC 179B.4.1 P806 L1 # 380  
 D'Ambrosia, John Futurewei, U.S. Subsidiary of Huawei  
 Comment Type ER Comment Status R (bucket)  
 There doesn't appear to be a figure - was it deleted? is this an editorial issue?  
*SuggestedRemedy*  
 add figure to 179B-2  
 Response Response Status C  
 REJECT.  
 The issue is not editorial. The suggested remedy does not provide sufficient detail to implement.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 178B SC 178B.5 P767 L1 # 381  
 Healey, Adam Broadcom Inc.  
 Comment Type T Comment Status A (bucket)  
 The "continue training" bit is in the control field. Also the cross-reference to 178B.8.8 does not point to the definition of the "Continue training" bit.  
 SuggestedRemedy  
 Change to "The continue training bit in the control field of the training frames (see 178B.7.2) if training is enabled."  
 Response Response Status C  
 ACCEPT.

Cl 178B SC 178B.14.2.1 P783 L31 # 382  
 Healey, Adam Broadcom Inc.  
 Comment Type T Comment Status A (bucket)  
 The "Continue training" bit is in the control field.  
 SuggestedRemedy  
 Change the last sentence of the definition of local\_rts to "The logical-NOT of this variable is encoded as the "continue training" bit in the control field of transmitted training frames."  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement suggested remedy with editorial license.  
 Also in the definition of remote\_rts change: "of the status field" to "of the control field".

Cl 174A SC 174A.7.1.4 P667 L17 # 385  
 Healey, Adam Broadcom Inc.  
 Comment Type T Comment Status R (withdrawn)  
 An "error mask" test method can also be defined for PCS-based measurements. This option can be used for lane-by-lane testing and would enable a quick assessment of whether or not the block error ratio requirement is met with reduced (or no additional) post-processing. As is the case for PMA-based measurements, failure to meet the error mask does not necessarily mean the block error ratio requirement is not met. It instead means that the method currently defined in 174A.7.1.4 would need to be used to confirm whether the block error ratio requirement is, or is not, met.  
 SuggestedRemedy

Consider adding a subclause for "Error mask test method using PCS-based measurements". The error mask is computed in the same way as defined in 174A.6.1.4 (using the value of BERadded appropriate for PCS-based measurements). The new subclause should also note that errors on unstressed lanes will be (incorrectly) attributed to the lane under test and should be minimized for the most accurate results.  
 Response Response Status Z  
 REJECT.  
 This comment was WITHDRAWN by the commenter.

Cl 177 SC 177.5.4.1.5 P319 L49 # 395  
 Shrikhande, Kapil Marvell  
 Comment Type T Comment Status A (bucket)  
 The definition of the inner fec codeword error bin counters in 177.5.4.1.5 could be edited to better align to the FEC codeword error bin counter in 175.2.5.3.  
 SuggestedRemedy  
 Align bin counter definition format in 177.5.4.1.5 to the bin counter in 175.2.5.3.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #11.

Cl 185 SC 185.12.4.1 P562 L10 # 401  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Transmitter nominal center frequency is not applicable to this PMD.  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

CI 185 SC 185.12.4.1 P562 L13 # 402  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Receiver nominal center frequency is not applicable to this PMD  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

CI 185 SC 185.12.4.24 P562 L40 # 403  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 PMD receive center frequency ability is not applicable to this PMD  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

CI 185 SC 185.12.4.4 P563 L34 # 405  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Adjustable range of transmit optical power is not defined for clause 185  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

CI 185 SC 185.12.4.4 P563 L36 # 406  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Minimum average channel power at maximum adjustable power setting is not applicable to clause 185 PMDs  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

CI 187 SC 187.12.4.1 P634 L10 # 410  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Transmitter nominal center frequency is not applicable to this PMD.  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

CI 187 SC 187.12.4.1 P634 L13 # 411  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Receiver nominal center frequency is not applicable to this PMD  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

CI 187 SC 187.12.4.2 P634 L40 # 412  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 PMD receive center frequency ability is not applicable to this PMD  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 187 SC 187.12.4.4 P635 L34 # 413  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Adjustable range of transmit optical power is not defined for clause 187  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

Cl 187 SC 187.12.4.4 P635 L36 # 414  
 Maniloff, Eric Ciena  
 Comment Type T Comment Status A (bucket)  
 Minimum average channel power at maximum adjustable power setting is not applicable to clause 187 PMDs  
 SuggestedRemedy  
 Delete this entry.  
 Response Response Status C  
 ACCEPT.

Cl 176B SC 176B.6.2 P695 L28 # 417  
 Nicholl, Gary Cisco Systems  
 Comment Type TR Comment Status A (bucket)  
 Incorrect reference. Reference to "Figure 176B-2" should be "Figure 176B-3"  
 SuggestedRemedy  
 Change "Figure 176B-2" to "Figure 176B-3".  
 Response Response Status C  
 ACCEPT.

Cl 171 SC 171.7 P200 L41 # 418  
 Nicholl, Gary Cisco Systems  
 Comment Type TR Comment Status A (bucket)  
 Annex 176B does not show any MMD numbering.  
 SuggestedRemedy  
 Change the second sentence from:  
 "Annex 173A and Annex 176B show additional examples of 800GXS partitioning and MMD numbering"  
 to:  
 "Annex 173A shows additional examples of 800GXS partitioning and MMD numbering using the BM PMA. 176B.6.2 shows additional examples of 800GXS partitioning using both BM PMA and SM PMA".  
 Change the second sentence of the second paragraph from:  
 "Annex 176B shows additional examples of 1.6TXS partitioning and MMD numbering."  
 to:  
 "176B.7.2 shows additional examples of 1.6TXS partitioning"  
 Change the title of 171.7 from:  
 "800GXS and 1.6TXS partitioning example"  
 to:  
 "800GXS and 1.6TXS partitioning examples"  
 Make sure to underline any added text and to strikethrough any deleted text.  
 Response Response Status C  
 ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.4.1.2 P310 L36 # 419

Nicholl, Gary Cisco Systems

Comment Type T Comment Status A (bucket)

I think the sentence "The data stream is not altered.", although accurate, is confusing/contradictory as the first sentence in the subclause states that "The alignment marker lock function is performed as defined in 176.4.3.3.", , and 176.4.3.3 by definition does alter the data stream.

I think it would be better to update Figure 177-3 to show the symbol demultiplex and alignment marker lock functions for 200G/400G to be "off to the side" from the main data path, with the main data path drawn as a straight arrow from top to bottom of diagram (indicating that the main data path is passthrough and is not altered in any way).

SuggestedRemedy

Delete the sentence "The data path is not altered" on line 36.

Update the 200GBASE-R/400GBASE-R portion of Figure 177-3 as described in the comment.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Keep the "data stream is not altered", and update the diagram to show a straight arrow.  
Otherwise implement the suggested remedy with editorial license.

Cl 177 SC 177.4.7.1 P316 L6 # 421

Dudek, Mike Marvell

Comment Type T Comment Status A (bucket)

The FAS descriptions in table 177-4 have the MSB transmitted first as other clauses do and as is shown with the vectors in Annex 177A. In other clauses the MSB is also transmitted first and is shown as the left most bit in diagrams. Figure 177-8 however might be interpreted as the FAS being transmitted in the other order.

SuggestedRemedy

Clarify Figure 177-8 to match the text and Annex

Response Response Status C

ACCEPT IN PRINCIPLE.  
Implement the suggested remedy with editorial license.

Cl 180 SC 180.9.5 P430 L32 # 422

Dudek, Mike Marvell

Comment Type TR Comment Status A taps

For commonality of implementation and because there is no expected reason for needing a different tap allocation for the TDECQ reference equalizer for the different clauses the TDECQ reference equalizer should be made the same for the clauses 180,181,182 and 183. In D1.3 all the clauses have the same 15 FFE length and the same 3 maximum number of pre-cursor taps however the minimum number of equalizer pre-cursor taps for the TDECQ reference equalizer is TBD in table 180-18 (for 200GBASE-DR1 etc.) as it is for 800GBASE-FR4-500 in table 181-13 and 800GBASE-FR4 etc. in table 183- 14 whereas for 200GBASE-DR1-2 etc in table 182-18 the format is different with a maximum number of post cursor taps of 13 implying a minimum number of pre-cursor taps of 2.

SuggestedRemedy

Make the format of the tables the same. Adopt a minimum number of pre-cursor taps of 2 and maximum number of pre-cursor taps of 3 for all the tables.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Resolve using the response to comment #186

Cl 120F SC 120F.1 P645 L53 # 428

Dudek, Mike Marvell

Comment Type E Comment Status A (bucket)

The reference to 120F.4 should be a hot link as this is changed in 802.3dj

SuggestedRemedy

Make it so.

Response Response Status C

ACCEPT.

Cl 120F SC 120F.1 P646 L9 # 429

Dudek, Mike Marvell

Comment Type ER Comment Status R (withdrawn)

The reference to 135F.3.2.1 is not correct. That subsection is about Receiver Signalling rate.

SuggestedRemedy

Change the reference to 135F.5

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 174A SC 174A.6.1.3 P664 L48 # 432  
 Dudek, Mike Marvell  
 Comment Type T Comment Status A (bucket)  
 Wrong equation reference  
 SuggestedRemedy  
 Change Equation 174A-3 to 174A-1  
 Response Response Status C  
 ACCEPT.

Cl 174A SC 174A.9 P668 L16 # 433  
 Dudek, Mike Marvell  
 Comment Type E Comment Status A (bucket)  
 Footnote a should be applied to the xAUI-n C2C in the bottom row as well as the top.  
 SuggestedRemedy  
 Make this change in tables 174A-1 and 174A-2 Also in a74A-1 delete the extraneous "at" in the last sentence of footnote a where it says "to meet at the BER allocations .."  
 Response Response Status C  
 ACCEPT.

Cl 176 SC 176.8 P299 L4 # 451  
 Shrikhande, Kapil Marvell  
 Comment Type TR Comment Status A PMA delay  
 In Table 176-7, complete the TBD delay values for the SM-PMAs.  
 SuggestedRemedy  
 A presentation will be provided for the TBD values in Table 176-7.  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 The following contribution was reviewed by the CRG.  
[https://www.ieee802.org/3/dj/public/25\\_01/shrikhande\\_3dj\\_01b\\_2501.pdf](https://www.ieee802.org/3/dj/public/25_01/shrikhande_3dj_01b_2501.pdf)  
 Implement the proposals on slide 16 and 17 for all sublayers listed on slide 16, including changing CR/KR PMD delay values to 74.24 ns.  
 Implement with editorial license.

Cl 179B SC 179B.2.1 P803 L39 # 453  
 Sekel, Steve Wilder Technologies  
 Comment Type T Comment Status R (withdrawn)  
 ILdd is listed as TBD  
 SuggestedRemedy  
 Proposed values and equations will be presented with measurement data in contribution during January 802.3 Interim meeting.  
 Response Response Status Z  
 REJECT.

This comment was WITHDRAWN by the commenter.

Cl 179B SC 179B.(new) P811 L54 # 455  
 Sekel, Steve Wilder Technologies  
 Comment Type T Comment Status R (withdrawn)  
 Reference impedance is 92.5 ohm differential, with test instruments being 100 ohm differential (50 ohm single ended). This introduces a discontinuity in the test environment which does not exist in application environment. Lab measurements suggest the location (in time delay) of this discontinuity will change some compliance measurement results. The location within the test fixtures should be specified in a new sub-clause in section 179B.4

SuggestedRemedy  
 Problem will be presented with proposed location of 92.5 to 100 ohm discontinuity within the compliance test fixtures will be presented in contribuion during 802.3 interim meeting  
 Response Response Status Z  
 REJECT.

This comment was WITHDRAWN by the commenter.

Cl 179A SC 179A.5 P799 L16 # 458  
 Kocsis, Sam Amphenol  
 Comment Type T Comment Status R (withdrawn)  
 ILddCA,min is greater than ILddCH,min  
 SuggestedRemedy  
 Add an Editor's note to provide context and explain that testing the ILddCH,min condition is not possible.  
 Response Response Status Z  
 REJECT.

This comment was WITHDRAWN by the commenter.



EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 174A SC 174A.9 P668 L29 # 468

Maki, Jeffery Juniper Networks

Comment Type T Comment Status R (bucket)

"Frame loss ratio for entire PHY" is wrong or at least has been unnecessarily truncated to one significant digit. In turn, the "Codeword error ratio for entire PHY" is wrong and the "BER for entire PHY (BERTotal)" is wrong.

SuggestedRemedy

Change "Frame loss ratio for entire PHY" to  $6.2 \times 10^{-11}$ , "Codeword error ratio for entire PHY" to  $1.50 \times 10^{-11}$ , and change "BER for entire PHY (BERTotal)" to  $2.93 \times 10^{-4}$ .

Response Response Status C

REJECT.  
Resolve using the response to comment #467.

Cl 174A SC 174A.5 P668 L14 # 469

Maki, Jeffery Juniper Networks

Comment Type T Comment Status R (bucket)

"Frame loss ratio for entire PHY" is wrong or at least has been unnecessarily truncated to one significant digit compared to other cases in the draft and in the published 802.3-2022 standard.

SuggestedRemedy

Change "Frame loss ratio for entire PHY" to  $6.2 \times 10^{-11}$ .

Response Response Status C

REJECT.  
Resolve using the response to comment #467.

Cl 174A SC 174A.5 P668 L17 # 470

Maki, Jeffery Juniper Networks

Comment Type T Comment Status R (bucket)

"Frame loss ratio for entire PHY" is wrong or at least has been unnecessarily truncated to one significant digit. In turn, the "Codeword error ratio for entire PHY" is wrong.

SuggestedRemedy

Change "Codeword error ratio for entire PHY" to  $1.50 \times 10^{-11}$ .

Response Response Status C

REJECT.  
Resolve using the response to comment #467.

Cl 174A SC 174A.5 P668 L19 # 471

Maki, Jeffery Juniper Networks

Comment Type T Comment Status R (bucket)

"Frame loss ratio for entire PHY" is wrong or at least has been unnecessarily truncated to one significant digit. In turn, the "BER for entire PHY (BERTotal)" is wrong.

SuggestedRemedy

Change "BER for entire PHY (BERTotal)" to  $2.93 \times 10^{-4}$ .

Response Response Status C

REJECT.  
Resolve using the response to comment #467.

Cl 175 SC 175.2.4.6.2 P266 L2 # 476

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

Typo in variable name tx\_acrambled\_f1\_i<256:0>.

SuggestedRemedy

Change tx\_acrambled\_f1\_i<256:0> to be tx\_scrambled\_f1\_i<256:0>.

Response Response Status C

ACCEPT.

Cl 176 SC 176.1.4 P271 L33 # 477

Opsasnick, Eugene Broadcom

Comment Type E Comment Status R (bucketp)

Should modify "Delay alternating PCSs by two RS-FEC codewords ..." to be "Delay of alternating PCSs by two RS-FEC codewords ..."

SuggestedRemedy

Change:  
"Delay alternating PCSs by two RS-FEC codewords ..."  
To:  
"Delay of alternating PCSs by two RS-FEC codewords ...".

Response Response Status Z

REJECT.

This comment was WITHDRAWN by the commenter.

Cl 176 SC 176.1.4 P271 L42 # 478

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

Now that PMAL is a defined term, the parenthetical "(lanes)" on line 43 should be updated to "(PMALs)".

*SuggestedRemedy*

Replace "(lanes)" with: (PMALs).

Response Response Status C

ACCEPT IN PRINCIPLE.

Since PMAL has been defined as lanes operating at 212.5Gb/s, it will be better to simply replace "... and data streams (lanes) operating at 212.5 Gb/s" with "and PMALs". Implement the suggested remedy with editorial license.

Cl 176 SC 176.3 P275 L6 # 479

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

Verb tense is not correct.

*SuggestedRemedy*

Change: "..., the m:n PMAs sends n parallel symbol streams ..." to: "..., the m:n PMAs send n parallel symbol streams ...".

And on line 11 of the same page 275,

Change: "..., the n:m PMAs sends m parallel symbol streams ..." to: "..., the n:m PMAs send m parallel symbol streams ...".

And on line 18 of the same page 275,

Change: "..., the n:n PMAs sends n parallel symbol streams ..." to: "..., the n:n PMAs send n parallel symbol streams ...".

Response Response Status C

ACCEPT.

Cl 176 SC 176.4 P276 L16 # 481

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

Now that PMAL is a defined term, it can be used to replace term "212.5 Gb/s interface lanes".

*SuggestedRemedy*

Replace:

"Note that m equals the number of PCSs and n equals the number 212.5 Gb/s interface lanes for each xBASE-R m:n PMA."

With:

"Note that m equals the number of PCSs and n equals the number PMALs for each xBASE-R m:n PMA."

Similar updates can be made throughout Clause 176 where there are references to "212.5 Gb/s interface lanes" such as line 51 on page 292.

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

CI 176 SC 176.4.1 P276 L21 # 482

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

Should add "PMAL" term when referring to the appropriate PMA interface lanes.

SuggestedRemedy

Replace:

"In the transmit (multiplexing) direction, the m:n PMAs perform a transmit function which multiplexes RS-FEC symbols from m PCSL input lanes received at the PMA service interface to n output lanes at the service interface below the PMA. In the receive (demultiplexing) direction, the m:n PMAs perform a receive function which demultiplexes RS-FEC symbols from n input lanes at the service interface below the PMA to m PCSL output lanes toward the PMA service interface."

With:

"In the transmit (multiplexing) direction, the m:n PMAs perform a transmit function which multiplexes RS-FEC symbols from m PCSL input lanes received at the PMA service interface to n PMAL output lanes at the service interface below the PMA. In the receive (demultiplexing) direction, the m:n PMAs perform a receive function which demultiplexes RS-FEC symbols from n PMAL input lanes at the service interface below the PMA to m PCSL output lanes toward the PMA service interface."

Similar updates can be made to 176.5.1.

Response Response Status C

ACCEPT IN PRINCIPLE.

In 176.4.1

Change:

"In the transmit (multiplexing) direction, the m:n PMAs perform a transmit function which multiplexes RS-FEC symbols from m PCSL input lanes received at the PMA service interface to n output lanes at the service interface below the PMA. In the receive (demultiplexing) direction, the m:n PMAs perform a receive function which demultiplexes RS-FEC symbols from n input lanes at the service interface below the PMA to m PCSL output lanes toward the PMA service interface."

To:

"In the transmit (multiplexing) direction, the m:n PMAs multiplex RS-FEC symbols from m PCSLs at the PMA service interface to n PMALs at the service interface below the PMA. In the receive (demultiplexing) direction, the m:n PMAs demultiplex RS-FEC symbols from n PMALs at the service interface below the PMA to m PCSLs toward the PMA service interface."

In 176.5.1

Change:

"In the transmit (demultiplexing) direction, the n:m PMAs perform a transmit function which demultiplexes RS-FEC symbols from n input lanes at the PMA service interface to m PCSL output lanes at the service interface below the PMA. In the receive (multiplexing) direction, the n:m PMAs perform a receive function which multiplexes RS-FEC symbols from m

PCSL input lanes at the service interface below the PMA to n output lanes at the PMA service interface."

To:

"In the transmit (demultiplexing) direction, the n:m PMAs demultiplex RS-FEC symbols from n PMALs at the PMA service interface to m PCSLs at the service interface below the PMA. In the receive (multiplexing) direction, the n:m PMAs multiplex RS-FEC symbols from m PCSLs at the service interface below the PMA to n PMALs at the PMA service interface."

Implement the with editorial license.

CI 176 SC 176.4.4.2.1 P289 L25 # 483

Opsasnick, Eugene Broadcom

Comment Type T Comment Status A (bucket)

Definition of variable restart\_lock\_demux<y> states that it is set to true in the SYMBOL\_LOCK\_RESTART state, but is actually set to true in two separate states in state diagram Figure 176-10.

SuggestedRemedy

Change: "Boolean variable that is set to true in the SYMBOL\_LOCK\_RESTART state to restart ..."

To: "Boolean variable that is set to true in the SYMBOL\_LOCK\_RESTART and SLIP\_CONTROL states to restart ..."

Response Response Status C

ACCEPT IN PRINCIPLE.

Implement the suggested remedy with editorial license.

CI 176 SC 176.4.4.2.3 P290 L4 # 484

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

Numbers less than or equal to 10 (ten) should be written out.

SuggestedRemedy

Change: "Counts 3 alignment marker intervals."

To: "Counts three alignment marker intervals."

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 176 SC 176.4.4.3 P292 L17 # 485  
 Opsasnick, Eugene Broadcom  
 Comment Type E Comment Status A (bucket)  
 In Figure 176-10, the state transitions out of SLIP\_CONTROL and SYMBOL\_LOCK\_RESTART do not have a condition.  
 SuggestedRemedy  
 Unconditional state transitions should be labelled "UCT".  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 In Fig 176-10, label the unconditional state transitions out of SLIP\_CONTROL and SYMBOL\_LOCK\_RESTART with "UCT"

Cl 177 SC 177.5.4 P319 L10 # 488  
 Opsasnick, Eugene Broadcom  
 Comment Type E Comment Status A (bucket)  
 Typo in tense of "PAM4 symbols".  
 SuggestedRemedy  
 Change: "... for each received PAM4 symbols."  
 To: "... for each received PAM4 symbol."  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.4.2.5 P311 L10 # 489  
 Opsasnick, Eugene Broadcom  
 Comment Type E Comment Status A (bucket)  
 The plural of PCSL ahouls be PCSLS, not PCSLS.  
 SuggestedRemedy  
 Change "PCSLs" to "PCSLS" (lowercase s).  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.4.2.5 P311 L50 # 490  
 Opsasnick, Eugene Broadcom  
 Comment Type TR Comment Status A (bucket)  
 Incorrect cross-reference.  
 SuggestedRemedy  
 Change "Figure 177-5" to "Figure 177-4".  
 Response Response Status C  
 ACCEPT.

Cl 177 SC 177.5.1.1 P317 L43 # 491  
 Opsasnick, Eugene Broadcom  
 Comment Type E Comment Status A (bucket)  
 The second and third sentences of the third paragraph of 177.5.1.1 is hard to understand. Also, this is the first use of "ILT" in this clause and it should be spelled out.  
 SuggestedRemedy  
 Suggest changing:  
 "If ILT function is enabled by the management variable mr\_training\_enable (see 178B.15), the precoding state on the link partner transmitter is requested using the ILT function. If ILT is disabled by the management variable mr\_training\_enable, the precoding state on the link partner transmitter is set by management."  
 to:  
 "If inter-sublayer link training (ILT) is enabled by the control variable mr\_training\_enable (see 178B.15), precoding of the received data is enabled at the link partner (transmitter) as requested by the receiver using ILT. If ILT is disabled, then the precoding of data at the transmitter is controlled by a management entity."  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

CI 177 SC 177.6.2.1 P320 L43 # 492  
 Opsasnick, Eugene Broadcom  
 Comment Type ER Comment Status A (bucket)  
 The word boolean should be capitalized.  
 SuggestedRemedy  
 Replace "boolean" with "Boolean" in the definition of these variables:  
 fas\_valid  
 Inner\_FEC\_sync\_status  
 slip\_done  
 test\_cw  
 test\_fas  
 Response Response Status C  
 ACCEPT.

CI 177 SC 177.6.2.1 P320 L33 # 493  
 Opsasnick, Eugene Broadcom  
 Comment Type E Comment Status A (bucket)  
 The word AND should be lowercase.  
 SuggestedRemedy  
 Change: "... for all eight flows AND the Inner FEC ..."  
 to: "... for all eight flows and the Inner FEC ..."  
 Response Response Status C  
 ACCEPT.

CI 177 SC 177.6.2.1 P321 L13 # 497  
 Opsasnick, Eugene Broadcom  
 Comment Type TR Comment Status A (bucket)  
 The definition of sync\_flow<x> should be made more clear. What does it mean to be "in a flow of Inner FEC"? Also, a range of values should be given as "A to B" instead of "A:B".  
 SuggestedRemedy  
 Suggest changing the definition of sync\_flow<x> from:  
 "A Boolean variable that is set to true when the receiver has found the correct boundary of codewords in a flow of Inner FEC, where x = 0:7"  
 to:  
 "A Boolean variable that is set to true after the inner FEC codeword boundary is found for an inner FEC flow, where x=0 to 7 and represents an inner FEC flow ID before identifying the actual inner FEC flow numbering."

Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement the suggested remedy with editorial license.

CI 177 SC 177.6.2.1 P321 L2 # 498  
 Opsasnick, Eugene Broadcom  
 Comment Type T Comment Status A (bucket)  
 The definition of the variable restart\_inner\_fec\_sync states it is set by a process, but it can now be set by two separate processes.  
 SuggestedRemedy  
 Replace: "A Boolean variable that is set by the Inner FEC synchronization process ..."  
 with: "A Boolean variable that is set by the Inner FEC synchronization process or the Inner FEC pad detection process ..."  
 Response Response Status C  
 ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.6.3 P321 L53 # 499

Opsasnick, Eugene Broadcom

Comment Type TR Comment Status A (bucket)

Should add a statement that the 8 self-sync processes operate independantly of each other and spell out the word synchronization. Should also state that 8 such processes are required on each input lane.

SuggestedRemedy

Change:

"The Inner FEC sublayer shall implement eight self-sync processes as shown in Figure 177–10 to identify the boundaries of the Inner FEC codewords."

to:

"The Inner FEC sublayer shall implement eight self-synchronization processes as shown in Figure 177–10 for each input lane in the receive direction. Each synchronization process operates independantly on an Inner FEC flow to identify the boundaries of the Inner FEC codewords."

Response Response Status C

ACCEPT IN PRINCIPLE.  
Implement the suggested remedy with editorial license.

Cl 177 SC 177.6.3 P321 L54 # 500

Opsasnick, Eugene Broadcom

Comment Type TR Comment Status A (bucket)

Should add a statement that a PAD detection process is required for each input lane.

SuggestedRemedy

Change:

"Pad detection process follows the process shown in Figure 177–10."

to:

"An inner FEC Pad detection process as illustrated in the state diagram in Figure 177–10 shall be implemented for each input lane in the receive direction."

Response Response Status C

ACCEPT.

Cl 177 SC 177.5.2 P318 L4 # 501

Opsasnick, Eugene Broadcom

Comment Type ER Comment Status A (bucket)

Extra "to" and missing verb in second sentence of 177.5.2.

SuggestedRemedy

Change:

"The eight codewords inserted as pad (see 177.4.7) are used to frame to the data stream and then removed before the received data is processed."

to:

"The eight codewords inserted as pad (see 177.4.7) are used to frame the data stream and are then removed before the received data is processed further."

Response Response Status C

ACCEPT.

Cl 177 SC 177.6.2.3 P321 L45 # 502

Opsasnick, Eugene Broadcom

Comment Type TR Comment Status A (bucket)

The definion of "fas\_cnt" is "Counts the interval of Inner FEC codewords between two adjacent pads." What is the interval value? How many codewords?

SuggestedRemedy

Add a number to to explicitly state the number of codewrds that need to be counted or else add a cross-reference to the subclause with this information.

Response Response Status C

ACCEPT IN PRINCIPLE.  
Add a cross-reference to the subclause, and implement this change with editorial license.

Cl 177 SC 177.6.3 P322 L10 # 504

Opsasnick, Eugene Broadcom

Comment Type TR Comment Status A (bucket)

In figure 176-10, the condition to transition out of stte INNER\_FEC\_SYNC\_INIT is incorrect.

SuggestedRemedy

Change the condition from:"all\_synced" to "UCT"

Response Response Status C

ACCEPT.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 177 SC 177.6.3 P322 L12 # 505

Opsasnick, Eugene Broadcom

Comment Type ER Comment Status A (bucket)

In figure 176-10, in CW\_CHECK\_3 state, the extra space between variable names and increment operator ++ should be removed.

SuggestedRemedy

Replace "cw\_cnt ++" with "cw\_cnt++"  
and  
replace "bad\_cw\_cnt ++" with "bad\_cw\_cnt++"

Response Response Status C

ACCEPT.

Cl 177 SC 177.6.3 P322 L21 # 506

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

In figure 176-10, the new state UNSYNC could use a better name.

SuggestedRemedy

Rename state "UNSYNC" to be "RESTART\_SYNC"

Response Response Status C

ACCEPT.

Cl 177 SC 177.6.3 P322 L4 # 507

Opsasnick, Eugene Broadcom

Comment Type E Comment Status A (bucket)

In figure 176-10, a space is needed between the logical-OR (+) operator and variable name.

SuggestedRemedy

Replace "+restart\_inner\_fec\_sync" with "+ restart\_inner\_fec\_sync".

And make the same change in Figure 177-11 on page 323, line 4.

Response Response Status C

ACCEPT.

Cl 177 SC 177.6.3 P323 L9 # 509

Opsasnick, Eugene Broadcom

Comment Type TR Comment Status A (bucket)

In figure 177-11, there is an incomplete change to FAS\_LOCK\_INIT state from D1.2 comment #389.

SuggestedRemedy

In FAS\_LOCK\_INIT state, add:  
"fas\_lock <= false"

Response Response Status C

ACCEPT.

Cl 177 SC 177.6.3 P323 L13 # 510

Opsasnick, Eugene Broadcom

Comment Type ER Comment Status A (bucket)

In figure 177-11, in BAD\_FAS state, the extra space between variable names and increment operator ++ should be removed.

SuggestedRemedy

Replace "bad\_fas\_cnt ++" with "bad\_fas\_cnt++"

Response Response Status C

ACCEPT.

Cl 179D SC 179D.1.1 P828 L34 # 518

Dawe, Piers Nvidia

Comment Type T Comment Status A (bucket)

This says "a common set of electrical parameters specified in 179.11, enabling a 1 m length". What length(s) it enables is not relevant to this discussion of connector types and breakout, and it is not accurate.

SuggestedRemedy

Delete "enabling a 1 m length"

Response Response Status C

ACCEPT IN PRINCIPLE.

The current project scope supports multiple cable types of varying lengths, and so the current text is incorrect.

Implement the suggested remedy with editorial license.

EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 179C SC 179C.1 P814 L12 # 519  
 Dawe, Piers Nvidia  
 Comment Type E Comment Status A (bucket)  
 Media Dependent Interface  
 SuggestedRemedy  
 Medium Dependent Interface  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Medium Dependent Interface is consistent with the current nomenclature definitions.  
 Change "Media Dependent Interface" to "Medium Dependent Interface" across the draft with editorial license.

Cl 185A SC 185A P839 L6 # 520  
 Dawe, Piers Nvidia  
 Comment Type TR Comment Status A (bucket)  
 ETCC is normative, like TDECQ or COM.  
 SuggestedRemedy  
 Change "informative" to "normative."  
 Response Response Status C  
 ACCEPT.

Cl 179A SC 179A.5 P802 L13 # 531  
 Dawe, Piers Nvidia  
 Comment Type TR Comment Status A (bucket)  
 13 dB ... = (16+4.45+4.45)-(2\*9.75)  
 SuggestedRemedy  
 13 dB ... = (16+8.25+8.25)-(2\*9.75)  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Resolve using the response to comment #560.

Cl 179A SC 179A.5 P801 L47 # 532  
 Dawe, Piers Nvidia  
 Comment Type TR Comment Status A (bucket)  
 17.5  
 SuggestedRemedy  
 17.75, twice  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 The comment indicates a typo in a label in Figure 179A-2. Replace 17.5 with 17.75 and Implement formatting with editorial license.

Cl 178A SC 178A.1.8.1 P758 L33 # 534  
 Dawe, Piers Nvidia  
 Comment Type E Comment Status A (bucket)  
 If Nb is the number of feedback taps, Nf is the number of feedforward taps. Obvs. Although OIF use it for something else. 10GBASE-LRM uses EqNf and EqNb. 802.3ck has:  
 DFE maximum span including floating taps N\_f (but it doesn't have receiver FFE taps so the contradiction doesn't apply) and  
 Number of DFE floating tap banks N\_bg.  
 SuggestedRemedy  
 Change Number of (FFE) taps per floating tap group, from Nf to N\_fg  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 For consistency with the notation used in Annex 93A, change "Number of floating tap groups" from N\_{g} to N\_{wg} and change "Number of taps per floating tap group" from N\_{f} to N\_{wf}. The change from "b" to "w" in the subscripts indicates that this floating tap structure is in the feed-forward filter defined in Annex 178A, whose tap coefficients are denoted as w(i), and not in the feedback filter as defined in Annex 93A.  
 Implement with editorial license.  
 [Editor's note: CC: 178, 179, 176C, 176D.]



EEE P802.3dj D1.3 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet 4th Task Force review comment

Cl 178B SC 178B P765 L19 # 542  
 Dawe, Piers Nvidia  
 Comment Type TR Comment Status R Introduction  
 This annex needs an introductory diagram, and the terminology needs cleaning up  
 SuggestedRemedy  
 Per comment  
 Response Response Status C  
 REJECT.  
 The suggested remedy does not provide sufficient detail to implement.

Cl 73 SC 73.10.2 P130 L14 # 546  
 Dawe, Piers Nvidia  
 Comment Type E Comment Status R (bucket)  
 This is contrary to the standard order (slow to fast).  
 SuggestedRemedy  
 Put the new entry immediately below the 100G/lane one. As the base document is out of order and this project amendment cannot deliver a properly ordered table without cleaning it up, bring the other two link\_fail\_inhibit\_timer rows into the draft and put them in the right order.  
 Response Response Status C  
 REJECT.  
 This would be best addressed at the revision project to create the updated base standard. Bringing in additional rows not relevant to 802.3dj scope would not be useful.

Cl 178 SC 178.10.1 P350 L38 # 558  
 Heck, Howard TE Connectivity  
 Comment Type E Comment Status A (bucket)  
 The value for COM single-ended receiver termination resistance is highlighted in orange. This value is consistent with those in 179 and 176C.  
 SuggestedRemedy  
 Remove the orange highlighting.  
 Response Response Status C  
 ACCEPT.

Cl 176C SC 176C.5.1 P711 L37 # 559  
 Heck, Howard TE Connectivity  
 Comment Type E Comment Status A (bucket)  
 The value for COM single-ended receiver transmitter termination resistance in Table 176C-6 is highlighted in orange. This value is consistent with those in 178 and 179.  
 SuggestedRemedy  
 Remove the orange highlighting.  
 Response Response Status C  
 ACCEPT.

Cl 179A SC 179A.5 P802 L12 # 560  
 Heck, Howard TE Connectivity  
 Comment Type T Comment Status A (bucket)  
 The first channel min calculation in Figure 179A-3 contains an error. The equation states that 13 dB @ 53.125 GHz = (16+4.45+4.45)-(2\*9.75). The correct equation is 13 dB = (16+8.25+8.25)-(2\*9.75). The 8.25 dB is taken from Table 179A-3 (Minimum insertion loss budget values at 53.125 GHz)  
 SuggestedRemedy  
 Change the equation in Figure 179A-3 to "Channel Min (TP0d-TP5d) = 13 dB @ 53.125 GHz = (16+8.25+8.25)-(2\*9.75)  
 Response Response Status C  
 ACCEPT IN PRINCIPLE.  
 Implement as proposed in suggested remedy.