

**P802.3z Draft 3.2
Summary Report**

CI	00	SC	CommentType	Comment Status		Author
				E / D / W	#	
	00	SC		E / D / W	# 60	Bob Grow
Editing instructions for existing clauses are not consistent. <CR>This may cause unnecessary complications in the publication of<CR>802.3						
	00	SC	global	E / D / W	# 85	Joe Gwinn
The ".pdf" documents containing 802.3z/d3.2 (and earlier) were not <CR>"optimised", making use of the documents by reviewers needlessly						
	01	SC	1.1.2.2(d)	E / D / W	# 68	Rich Seifert
The GMII does not support operation at any speed other than 1000 Mb/s.						
	01	SC	1.4	E / D / W	# 189	Kelly McClellan
typographical:<CR>'specialtyshielded' is run together						
	01	SC	1.4	E / D / W	# 191	Kelly McClellan
definition of 'differential sensitivity' should include<CR>reference to BER						
	01	SC	1.4	E / D / W	# 190	Kelly McClellan
definition of 'differential skew' should be <CR>closer to useage in Clause 39						
	01	SC	1.4	E / D / W	# 78	Joe Gwinn
We use the term "power penalty" in a number of places in section 01, <CR>but never define it. There was a definition in section 01 of draft 3						
	01	SC	1.4	E / D / W	# 124	David Law
1000BASE X should read 1000BASE-X.						
	01	SC	1.4	E / D / W	# 126	David Law
Suggest that definition should mentioned that 1000BASE-T runs on four pairs<CR><CR>of Cat-5 cabling.						
	01	SC	1.4	E / D / W	# 125	David Law
The definition used here does not include the changes that were made by<CR>802.3y.						
	01	SC	1.4	E / D / W	# 128	David Law
Suggest reword of this definition to match others.						
	01	SC	1.4	E / D / W	# 127	David Law
"The definitions for 'Physical Coding Sublayer (PCS)', Physical Layer<CR>entity (PHY)' and 'Physical Media Attachment (PMA)' seem to be						
	01	SC	1.4	E / D / W	# 38	Kevin Daines
"Physical Media Attachment (PMA) sublayer" is incorrect.<CR>References - .3u 1.4.150 (page 15)<CR> - .3z Figure 1-1 (page 1.2)						
	04	SC	4.2.3	E / D / O	# 12	Shimon Muller
Style of the sentence.						
	04	SC	4.2.3.4	E / D / O	# 87	Edmund Chen
In Fig. 4-7, the FCS Coverage should not include the FCS field.						
	04	SC	4.2.7.2	E / D / O	# 129	David Law
The close } is missing from the interFrameSpacingPart2 definition.						
	04	SC	4.3.3	E / D / O	# 13	Shimon Muller
The NOTE that was deleted from the text should still appear in this version of<CR>the standard, and be shown in "strikethrough" type.						
	04	SC	4.4.2.1	E / D / O	# 197	Devendra Tripathi
The last part of the sentence "..and the clock skew" should be "... and the<CR>clock tolerances", just like line 27 of page 4.36.						

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 04 Add a note like used for 10 and 1000 Mb/s speeds regarding interframe<CR>spacing in terms of bit time.	SC 4.4.2.3	E / D / O	# 198	Devendra Tripathi
CI 04 Spelling error	SC 4.4.2.4	E / D / O	# 35	Kevin Daines
CI 05 Is 32 bit wide xmt octet counter good enough for Gbit/s speed ?	SC 5.2.4.2	1 / D / O	# 199	Devendra Tripathi
CI 05 In full duplex mode carrier sense is not defined. Thus<CR>LayerMgmtTransmitCounters may remain on line 36 forever.	SC 5.2.4.2	1 / D / O	# 200	Devendra Tripathi
CI 05 Is 32 bit wide receive octet counter good enough for Gbit ?	SC 5.2.4.3	1 / D / O	# 201	Devendra Tripathi
CI 05 The value assigned on line 44 overwrites any other assignments.	SC 5.2.4.3	1 / D / O	# 202	Devendra Tripathi
CI 22 Capitalization error. Reference: clause 37	SC 22.2.4	E / D / W	# 37	Kevin Daines
CI 22 I have been informed that the IEEE editor has included editorial changes in 802.3x&y as requested in my ballot comment on 802.3aa. As a r	SC 22.2.4	E / D / W	# 66	Bob Grow
CI 22 The context of a single speed PHY has been changed.	SC 22.2.4.1.3	1 / D / W	# 64	Brad Booth
CI 22 Clause 28 does not define register 8, thus reference to 28.2.4.1 is not<CR>correct.	SC 22.2.4.2.16	E / D / O	# 203	Devendra Tripathi
CI 22 Style of the sentence.	SC 22.2.4.2.8	E / D / W	# 14	Shimon Muller
CI 22 Verify if the subclause references in PICs items MF39 through 51 of 802.3x&y have been corrected as requested on my ballot comment on 8	SC 22.7.3.4	E / D / O	# 67	Bob Grow
CI 22 The context of a single speed PHY has been changed in PICS MF12.	SC 22.7.3.4	1 / D / W	# 62	Brad Booth
CI 22 The context of a single speed PHY has been changed in PICS MF13.	SC 22.7.3.4	1 / D / W	# 63	Brad Booth
CI 22 Is the status correct. It reads that the registers are dependent on the<CR>implementation of the GMII. Aren't these registers in fact depende	SC 22.7.3.4	E / D / O	# 150	David Law
CI 22 Incorrect subclause reference	SC 22.7.3.4	E / D / O	# 149	David Law
CI 30 Typo.	SC 30.2.2.2.2	E / D / O	# 146	David Law
CI 30 Typo.	SC 30.2.2.2.2	E / D / O	# 147	David Law

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 30 Typo.	SC 30.2.2.2.2	E / D / O	# 148	David Law
CI 30 Spelling error.	SC 30.3.1.1.24	E / D / O	# 184	Kevin Daines
CI 30 "Typo, missing space."	SC 30.3.1.1.24	E / D / O	# 145	David Law
CI 30 Suggest we should be consistent in the use of project names.	SC 30.3.1.1.25	E / D / O	# 144	David Law
CI 30 "Typo, missing space."	SC 30.3.2.1.2	E / D / O	# 143	David Law
CI 30 "The carrier event is not necessarily valid, it is just a carrier event."	SC 30.3.2.1.5	E / D / O	# 152	David Law
CI 30 "The note duplicates the text of the behaviour. Remove the note, it is no longer required."	SC 30.3.2.1.6	E / D / O	# 151	David Law
CI 30 Remove the extraneous carriage return after ValidPacketMinTime.	SC 30.4.3.1.10	E / D / O	# 157	David Law
CI 30 Match the enumeration to the actual value. Also place inverted commas around the enumeration.	SC 30.4.3.1.2	E / D / O	# 155	David Law
CI 30 Typo.	SC 30.4.3.1.2	E / D / O	# 153	David Law
CI 30 Place inverted commas around the enumeration.	SC 30.4.3.1.2	E / D / O	# 154	David Law
CI 30 Remove extraneous space.	SC 30.4.3.1.7	E / D / O	# 156	David Law
CI 30 Please correct the format of these two paragraphs. They should not be hanging paragraphs.	SC 30.5.1.1.2	E / D / O	# 158	David Law
CI 30 Correct the capitalisation of Auto-Negotiation on both of these lines.	SC 30.5.1.1.4	E / D / O	# 160	David Law
CI 30 Suggest new enumeration 'auto negotiation error' should be changed to 'auto neg error' so that it fits within the size of the other e	SC 30.5.1.1.4	E / D / O	# 159	David Law
CI 30 "Text 'auto negotiation, applies only ...' should read 'Auto-Negotiation error ...'. I assume this text runs into the enumeration due to the le	SC 30.5.1.1.4	E / D / O	# 161	David Law
CI 30 "Text '... (RF1)as ...' and '... (RF2)as ...' should read '... (RF1) as ...' and '... (RF2) as ...', that is add a space before 'as' in both cases	SC 30.6.1.1.5	E / D / O	# 162	David Law
CI 30B "Text '... of clause 40 ...' should read '... of clause 40...', that is remove additional space."	SC 30B.2	E / D / O	# 163	David Law

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 31 Typo.	SC 31B.3.7	E / D / O	# 15	Shimon Muller
CI 31B "Typo, missing close ')".	SC 31B.3.7	E / D / O	# 141	David Law
CI 31B Typo.	SC 31B.3.7	E / D / O	# 142	David Law
CI 31B The order of the columns seems to have been changed from that published in<CR>31B.	SC 31B.4.3	E / D / O	# 140	David Law
CI 31B Transcription error.	SC 31B.4.6	E / D / O	# 139	David Law
CI 31B Please remove the strikethrough word 'out' from 'without'. These seems to<CR>be a strikethrough from marking a change made to the last d	SC 31B.4.6	E / D / O	# 138	David Law
CI 34 See comment #555.<CR>This editorial comment was accepted by the editor, but the change was not incor-<CR>porated in the specified tex	SC 34.1	E / D / W	# 16	Shimon Muller
CI 34 Rather than '(under development)' suggest that same text as is used<CR>elsewhere should be used to note that clause 40 is not yet comple	SC 34.1.2	E / D / W	# 130	David Law
CI 35 Text was approved at the 9/30-10/1 intermin in Santa Clara<CR>for insertion at the beginning of clause 35.4.3. Some of<CR>the approved t	SC 35	E / D / O	# 106	Bill Quackenbush
CI 35 "provides" should be singular.	SC 35.1.1	E / D / O	# 112	Bill Quackenbush
CI 35 Period and start of sentence missing.	SC 35.1.2	E / D / O	# 113	Bill Quackenbush
CI 35 Sentence is awkward.	SC 35.1.2	E / D / O	# 114	Bill Quackenbush
CI 35 Awkward usage.	SC 35.1.3	E / D / O	# 115	Bill Quackenbush
CI 35 Incorrect acronym. Reference .3u 1.4.150	SC 35.1.4	E / D / W	# 36	Kevin Daines
CI 35 Typo.	SC 35.2.1.5	E / D / O	# 131	David Law
CI 35 These line are pretty much duplicated again on lines 51 to 54.	SC 35.2.2.10	E / D / O	# 205	Devendra Tripathi
CI 35 Since bit 0.8 defines full duplex mode only when manual configuration is<CR>enabled, the sentence describing CRS and COL<CR>on these	SC 35.2.2.10	T / D / O	# 206	Devendra Tripathi
CI 35 Essentially both paragraphs are identical with the exception of the last line in the 2nd paragraph. Since the two are written differently, it mak	SC 35.2.2.10	E / D / W	# 45	Kevin Daines

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 35 Spelling error.	SC 35.2.2.10	E / D / W	# 44	Kevin Daines
CI 35 "first GTX_CLK" is unclear.	SC 35.2.2.4	E / D / O	# 116	Bill Quackenbush
CI 35 "data" not "data code-groups" are present on TXD. Certain<CR>encodings of TXD, TX_EN and TX_ER request that the PHY generate<CR>	SC 35.2.2.5	E / D / O	# 117	Bill Quackenbush
CI 35 Redundant text. The note about TXD encodings is found in text and in table (line 26, same page).	SC 35.2.2.5	E / D / W	# 43	Kevin Daines
CI 35 Suggest in this case table should not have been changed to have an<CR>uppercase 'T'.	SC 35.2.2.5	E / D / O	# 132	David Law
CI 35 The last word "deasserted" is not correct when used for state. I think<CR>inactive word is more appropriate.	SC 35.2.2.6	E / D / O	# 204	Devendra Tripathi
CI 35 "The text 'The TX_ER signal shall be implemented at the GMII of a PHY and<CR>in a repeater, at the GMII of a port. The TX_ER shall be im	SC 35.2.2.6	E / D / O	# 133	David Law
CI 35 The paragraph is rather unclear, at least to me.	SC 35.2.2.6	E / D / O	# 118	Bill Quackenbush
CI 35 Punctuation error.	SC 35.2.2.6	E / D / W	# 40	Kevin Daines
CI 35 RX_DX does not indicate whether the data on RXD<7:0> is synchronous<CR>to RX_CLK.	SC 35.2.2.7	E / D / O	# 119	Bill Quackenbush
CI 35 Change "shall remain asserted continuously" to "shall be asserted<CR>continuously".	SC 35.2.2.7	E / D / O	# 120	Bill Quackenbush
CI 35 "first RX_CLK" is unclear.	SC 35.2.2.7	E / D / O	# 121	Bill Quackenbush
CI 35 Suggest in this case table should not have been changed to have an<CR>uppercase 'T'.	SC 35.2.2.8	E / D / O	# 134	David Law
CI 35 I think that the sentence should begin "In a DTE".	SC 35.2.2.8	E / D / O	# 122	Bill Quackenbush
CI 35 Redundant text. The note about RXD encodings is found in the text and in table.	SC 35.2.2.8	E / D / W	# 42	Kevin Daines
CI 35 Spelling error.	SC 35.2.2.8	E / D / W	# 41	Kevin Daines
CI 35 "and" should be "an".	SC 35.2.2.9	E / D / O	# 123	Bill Quackenbush
CI 35 Typo.	SC 35.2.2.9	E / D / O	# 135	David Law

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		Author
			Response Status	
CI 35 Spelling error.	SC 35.2.2.9	E / D / W	# 39	Kevin Daines
CI 35 Typo.	SC 35.2.2.9	E / D / O	# 136	David Law
CI 35 In the beginning of the line the text "transmit path" is redundant. It has<CR>already been mentioned in line 41, in the same sentence.	SC 35.2.3.5	E / D / O	# 207	Devendra Tripathi
CI 35 See comment #570. This technical comment was accepted during the ballot comment resolution, but the required change was not incorporat	SC 35.2.4	1 / D / W	# 17	Shimon Muller
CI 35 As written, the paragraph suggests that only the physical layer is<CR>subject to this issue.	SC 35.4.1	E / D / O	# 104	Bill Quackenbush
CI 35 The period 7.5 ns is out of range of 100 ppm tolerance. On what basis it<CR>has been decided ? <CR>Likewise 2.5 ns high comes to abou	SC 35.4.3	1 / D / O	# 208	Devendra Tripathi
CI 35 Text was approved at the 9/30-10/1 intermin in Santa Clara<CR>for insertion at the beginning of clause 35.4.3. Some of<CR>the approved t	SC 35.4.3	E / D / O	# 105	Bill Quackenbush
CI 35 Too any "and"s.	SC 35.4.3	E / D / O	# 107	Bill Quackenbush
CI 35 As written, the AC thresholds apply only to the clocks.	SC 35.4.3	E / D / O	# 108	Bill Quackenbush
CI 35 Sentence needs some clean up.	SC 35.4.3	E / D / O	# 109	Bill Quackenbush
CI 35 The title of Table 35-9 is not symmetric with the title of Table 35-10.	SC 35.4.3	E / D / O	# 111	Bill Quackenbush
CI 35 Change "insure" to ensure"	SC 35.4.3	E / D / O	# 110	Bill Quackenbush
CI 35 Correct to Comment is incorrect.	SC 35.5.3.2	E / D / W	# 61	Brad Booth
CI 35 Suggest that both SF27a and SF27b are both depended on being connected to a<CR><CR>repeater. This may require another condition or	SC 35.5.3.2	E / D / O	# 137	David Law
CI 36 Typos and minor grammatically errors in clause 36.	SC 36	E / D / O	# 101	Scott Mason
CI 36 Clause 36 is inconsistent in its description of the PCS client. At times the<CR>client is called: MAC, reconciliation sub-layer, GMII, repeater,	SC 36	TR / D / O	# 99	Scott Mason
CI 36 New text that reads "for half-duplex PHYs" was added to item b. 1000 Base-X<CR>does not support half-duplex PHYs.<CR><CR>I don't se	SC 36.1.4.1	TR / D / O	# 100	Scott Mason
CI 36 The acronym TBI is not previously defined. Clause 36 describes GMII,<CR>for example, in 36.1.5, even though it was defined in 36.1.4.1, y	SC 36.1.5	E / D / O	# 47	Kevin Daines

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 36 Please define the meaning of 'TBI' before using it.	SC 36.1.5	E / D / O	# 164	David Law
CI 36 TX_ER should also be mentioned as being = 1, to cause the generation of<CR>/R/.	SC 36.2.4.15	E / D / O	# 188	Don Wong
CI 36 On lines 4 & 5, a reference is made to EPD2 and EPD3, however on page <CR>36.20 the definition of EPD2 & EPD3 (lines 41 & 45, respect	SC 36.2.4.15	E / D / O	# 195	Don Wong
CI 36 New text states that "The PCS indicates reception of /V/ or an invalid<CR>code-group on the GMII through the use of RX_DV signal asserte	SC 36.2.4.16	E / D / O	# 97	Scott Mason
CI 36 The second paragraph states that "The conversion from a MAC frame to code-<CR>group stream and back to a MAC frame is transparent t	SC 36.2.4.17	TR / D / O	# 98	Scott Mason
CI 36 The PCS encapsulates packets. We fixed this in the previous paragraph<CR>but missed it on line 46 and on line 49.	SC 36.2.4.17	E / D / O	# 46	Kevin Daines
CI 36 Tables 36-1 Valid data code-groups, 36-2 Valid special code-groups, and <CR>36-3 Defined ordered_sets are inconsistent and confusing. T	SC 36.2.4.7.1	E / D / O	# 11	Don Alderrou
CI 36 Formatting problem.	SC 36.2.5.1.1	E / D / O	# 48	Kevin Daines
CI 36 /INVALID/ is end of the line. should be at the beginning of a line	SC 36.2.5.1.2	E / D / O	# 196	Don Wong
CI 36 Lines 48-50 are duplicates of lines 27-29 and not needed I believe.	SC 36.2.5.1.2	E / D / O	# 49	Kevin Daines
CI 36 Spelling error (or grammatical error).	SC 36.2.5.1.3	E / D / O	# 50	Kevin Daines
CI 36 The Transmit and Receive state diagrams each cover 2 pages. Designing to<CR>these would be much easier if the pairs were on facing pa	SC 36.2.5.2	E / D / O	# 72	Benjamin Brown
CI 36 Recent changes in the receive state diagram have created a problem <CR>in that errors in the // interpacket gap preceding /S/ can cause a	SC 36.2.5.2	T / D / O	# 54	Jon Frain
CI 36 PCS transmit code-group state diagram state : GENERATE_code_groupS should<CR>be uppercased.	SC 36.2.5.2.1	E / D / O	# 73	Benjamin Brown
CI 36 The transitions from PCS transmit states CONFIGURATION and IDLE to state<CR>TX_TEST_XMIT are redundant. Exit from these states is	SC 36.2.5.2.2	E / D / O	# 93	Scott Mason
CI 36 If xmit becomes DATA while the GMII client is sending a packet, the transmit<CR>PCS will place a start delimiter on the packet in progress,	SC 36.2.5.2.2	TR / D / O	# 94	Scott Mason
CI 36 The transition from state IDLE_D to RX_INVALID causes a potential<CR>deadlock situation. Upon completion of autonegotiation, one end	SC 36.2.5.2.2	T / D / O	# 2	Mike Morrison
CI 36 Recent major revisions have been made to the PCS receive state diagram to<CR>enable /C/ and // to be always sent to the auto-negotiatio	SC 36.2.5.2.2	TR / D / O	# 91	Scott Mason

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		Author
			Response Status	
CI 36 The assignment of TRUE to RX_ER in PCS receive state EXTEND_ERR is redundant.<CR>No path exists to this state where RX_ER is not	SC 36.2.5.2.2	E / D / O	# 92	Scott Mason
CI 36 Spelling error.	SC 36.3.3	E / D / O	# 51	Kevin Daines
CI 36 extra period in last sentence of footnote	SC 36.3.6.2	E / D / O	# 27	Brad Booth
CI 36 need a period at the end of the last sentence in the paragraph	SC 36.5.1	E / D / O	# 28	Brad Booth
CI 36 Punctuation mistake.	SC 36.5.1	E / D / O	# 52	Kevin Daines
CI 36 need a space between "CRS" and "de-assert"	SC 36.5.1	E / D / O	# 26	Brad Booth
CI 36 The new variables cgbad and cggood include the comparison:<CR><CR> rx_code_group = /INVALID/<CR><CR>This is not valid syntax. r	SC 36.5.1.3	E / D / O	# 96	Scott Mason
CI 36 In D3.2, a change was introduced that "detects carrier when a two or more bit<CR>difference between [/x/] and the expected /K28.5/ based	SC 36.5.1.4	TR / D / O	# 95	Scott Mason
CI 36A Disparity Flip bytes are no longer necessary. They should have been<CR>removed for D3.2.	SC 36A.4	E / D / O	# 74	Benjamin Brown
CI 36B The page numbers for Annex 36B are give as 36A.1 and 36A.2. These page numbers are the same as for Annex 36A.	SC 36B	E / D / O	# 3	Amrit Kalla
CI 36B << Note: it should be page "36B.1", but Annex 36A and 36B are both <CR>give the same page numbers. >><CR><CR>Punctuation error.	SC 36B	E / D / O	# 53	Kevin Daines
CI 36B Please include an additional 8B/10B coding example (our editorial staff mistakenly omitted this example from the draft D3.2).<CR><CR>This	SC 36B	1 / D / O	# 5	Howie Johnson
CI 36B Page numbering appears incorrect.	SC 36B	E / D / O	# 4	Howie Johnson
CI 37 bad grammar	SC 37.1.4.4	E / D / O	# 1	John Cagle
CI 37 Add helpful text stolen from Clause 28.2.1.2.5 to explain that a <CR>device can be Next Page able but set the NP bit to zero.	SC 37.2.1.7	E / D / O	# 69	Linda Cheng
CI 37 This comment will be subject to interpretation. The line in question<CR>reads "The first /C/ ordered_sets exchanged ... after [reset] ... <CR>	SC 37.2.2	1 / D / O	# 56	Kevin Daines
CI 37 "Auto-Negotiation protocol error" has not been defined anywhere. I believe<CR>it is referring to "Auto-Negotaion_Error".	SC 37.2.2	E / D / O	# 209	Devendra Tripathi
CI 37 Statement is incorrect. While receiving a // ordered_set, a RUDI(/I) is always set by the PCS receive process.	SC 37.2.3.1	E / D / O	# 30	Brad Booth

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 37 Missing the phrase "and the NP bit set to logic zero".	SC 37.2.4.3	E / D / O	# 75	Benjamin Brown
CI 37 Add helpful text taken and modified from Clause 28.2.3.4.11 to explain <CR>that a device must send a null next page if it is willing to receive	SC 37.2.4.3	E / D / O	# 70	Linda Cheng
CI 37 Next page operation is also controlled by the Next Page Able bit in register 6.	SC 37.2.4.3	E / D / O	# 29	Brad Booth
CI 37 Statement is invalid. No next page transmission will happen after the base page if the link partner didn't advertise next page ability, if the loc	SC 37.2.4.3	E / D / O	# 32	Brad Booth
CI 37 The phrase "standard Auto-Negotiation" is confusing.	SC 37.2.4.3	E / D / O	# 210	Devendra Tripathi
CI 37 1. One line 49, the phrase "normal Auto-Negotiation" is confusing. <CR>2. On line 54, "a" in "a next page exchange ..." is awkward.	SC 37.2.4.3	E / D / O	# 211	Devendra Tripathi
CI 37 "... is invoked unless either the local device or link partner ..." is<CR>confusing and if am getting the sentence right, it is wrong<CR>even. It	SC 37.2.4.3.11	E / D / O	# 213	Devendra Tripathi
CI 37 Wrong polarity.	SC 37.2.4.3.11	E / D / O	# 58	Kevin Daines
CI 37 Statement is not clear and not correct.	SC 37.2.4.3.11	E / D / O	# 33	Brad Booth
CI 37 The usage of "may be" here is not consistent with "shall" on line 38.	SC 37.2.4.3.12	E / D / O	# 214	Devendra Tripathi
CI 37 "This bit take the opposite..." should be "This bit takes the opposite ..."	SC 37.2.4.3.6	E / D / O	# 212	Devendra Tripathi
CI 37 Spelling mistake.	SC 37.2.4.3.6	E / D / O	# 55	Kevin Daines
CI 37 Missing "s" in "takes"	SC 37.2.4.3.6	E / D / O	# 31	Brad Booth
CI 37 Extra end square bracket.	SC 37.2.4.3.8	E / D / O	# 76	Benjamin Brown
CI 37 Since here "shall" is used, I believe we should mention here that<CR>"registers 7 and 8 need not be implemented if next page is<CR>not su	SC 37.2.5.1	E / D / O	# 215	Devendra Tripathi
CI 37 Since next page is optional we should add bit 6.3 as "Link Partner Next<CR>Page Able". Please refer to 802.3u pp 251 table 28-5.	SC 37.2.5.1.5	T / D / O	# 216	Devendra Tripathi
CI 37 "For next pages ..." is confusing because Page Recieved bit is always<CR>cleared upon read whether it is because of base page or next pa	SC 37.2.5.1.5	E / D / O	# 217	Devendra Tripathi
CI 37 Statement is not correct. Register 15 doesn't indicate the status of Auto-Negotiation.	SC 37.2.5.1.8	E / D / O	# 34	Brad Booth

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		Author
			Response Status	
CI 37	SC 37.2.5.1.9	E / D / O	# 218	Devendra Tripathi
The word signal has been used at some places instead of variable. Some<CR>places it should be variable like on line 12. On lines 15 and 1				
CI 37	SC 37.3	E / D / O	# 19	Mike Morrison
In fig 37-6, state AN_ENABLE, the action:<CR><CR>IF (mr_an_enable=TRUE) THEN<CR> tx_Config_Reg<D15:D0> <=0<CR> xmit<=C				
CI 37	SC 37.3.1.1	1 / D / O	# 219	Devendra Tripathi
Two times it is said here that "mr_page_rx" or "mr_lp_np_rx" must be read<CR>for next page exchange to progress. It is incorrect becuae s				
CI 37	SC 37.3.1.1	E / D / O	# 57	Kevin Daines
Punctuation mistake.				
CI 37	SC 37.3.1.1	1 / D / O	# 65	Rich Taborek
Auto-Negotiation protocol should be invoked whenever the condition<CR>signal_detect=FAIL occurs and subsequently signal_status=OK.<				
CI 37	SC 37.3.1.2	1 / D / O	# 10	Don Alderrou
The first sentence of the definition for the ability_match function <CR>which starts at line 41 is not clear. The complete sentence is: <CR>"				
CI 37	SC 37.3.1.5	TR / D / O	# 89	Myles Kimmitt
There appears to be a state missing in the Autonegotiation State Diagram as<CR>it relates to bringing up a port when autonegotiation is dis				
CI 37	SC 37.4	1 / D / O	# 71	Linda Cheng
When mr_np_able = TRUE and mr_adv_ability<16>= 0 there is no condition<CR>for exit from the complete_acknowledge state. When this c				
CI 37	SC Fig. 37-6	TR / D / O	# 90	Steve Dreyer
One invalid /C/ code will cause autonegotiation to restart because RUD(INVALID) is an input to AN_ENABLE. It was decided in previous m				
CI 38	SC	TR / D / O	# 187	Geoff Thompson
I can not approve a standard that has such a large unsolved technical deficiency as that alluded to in the rather cryptic note on page 38.6 &				
CI 38	SC 38.1.1	E / D / O	# 165	David Law
Suggest text 'These PMD sublayers within 1000BASE-X PMD services are<CR>described in an abstract manner and ...' is not clear.				
CI 38	SC 38.1.1	E / D / O	# 166	David Law
General comment on clause. '... of encoded 8B/10B characters ...'. Is it<CR>correct that the 8B/10B characters are encoded or are the char				
CI 38	SC 38.1.1	E / D / O	# 167	David Law
General comment on clause. I don't think the style used for the note is<CR>correct. For example 'Note -Delay ...' should read 'Note-Delay ...'				
CI 38	SC 38.10	1 / D / O	# 103	Ray Lin
Insert recommendation (standard reference) for optical power loss<CR>measurements of installed multimode fiber cable plant.				
CI 38	SC 38.10	TR / D / O	# 79	Joe Gwinn
Table 38-11 "Channel insertion loss" is a bit confusing as it nowhere <CR>explicitly states the ranges in meters used to compute the given <				
CI 38	SC 38.11	E / D / O	# 174	David Law
Suggest '... the optical connector plug specified in 38.11.3.' is not<CR>correct as 38.11.3 is an informative drawing of the connector. The<C				
CI 38	SC 38.11.2.3	E / D / O	# 175	David Law
I may have missed it but I cannot find the PICSS entries for the two new<CR>shalls added here.				
CI 38	SC 38.12.3	E / D / O	# 176	David Law
Suggest that the SD entry in the Major options table is not longer required<CR><CR>as this is no longer an option. SD is also no longer req				

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 38	SC 38.12.4.1	E / D / O	# 177	David Law
Delete the condition 'SD' from entries FN6 to FN8 as Signal detect is now<CR>mandatory.				
CI 38	SC 38.12.4.2	E / D / O	# 81	Joe Gwinn
A "lessor" is someone who leases something; "lesser" was intened.				
CI 38	SC 38.2.4	E / D / O	# 168	David Law
"Text '... PMD_SIGNAL.indicate (SIGNAL_DETECT)' should read'...<CR>PMD_SIGNAL.indicate(SIGNAL_DETECT)', that is remove the inc				
CI 38	SC 38.3	E / D / O	# 169	David Law
This note is no longer is complete.				
CI 38	SC 38.3	TR / D / O	# 185	Howie Johnson
Clause 38 includes references to non-international<CR>standards. Here are the six locations I found (has<CR>anyone spotted any others?				
CI 38	SC 38.3	TR / D / O	# 186	Howie Johnson
The fundamental issue underlying D3.1 comment #754 has not yet been resolved. Attached is a copy of the record for D3.1 comment #754.				
CI 38	SC 38.3, 38.4, 38	TR / D / O	# 88	Ray Lin
The Annex 38A physical media dependent link model used to establish link <CR>penalties may need to include a differential mode delay (D				
CI 38	SC 38.3.2 & 38.4	E / D / O	# 102	Vince Melendy
The receiver specification for sensitivity the min and max words are reversed on both of these tables. The highest positive number is the mini				
CI 38	SC 38.4	E / D / O	# 170	David Law
Suggest that the diameter of the singlemode fibre supported should be<CR>listed in the same way as the multimode fibre is.				
CI 38	SC 38.4	E / D / O	# 171	David Law
This note is no longer is complete.				
CI 38	SC 38.5	TR / D / O	# 86	Paul Kolesar
Due to the recently discovered jitter generation caused by the possible<CR>equal-amplitude split-impulse response of multimode fiber when				
CI 38	SC 38.6.6	E / D / O	# 77	Joe Gwinn
The term "backed out" is colloquial, and not clear.				
CI 38	SC 38.6.8	E / D / O	# 172	David Law
Suggest text '... shall substitute use of the BT filter ...' should read<CR>'... shall substitute the use of the Bessel-Thompson filter ...'				
CI 38	SC 38.9	E / D / O	# 173	David Law
"I do not understand what parameter labelling is required by the statement<CR>'... include 62.5 mm MMF, 50 mm MMF', please clarify."				
CI 38A	SC 38A.2	E / D / O	# 178	David Law
I note that the extra space at the beginning of the paragraph has been<CR>removed. If you want to remove these additional spaces note tha				
CI 38A	SC 38A.5	E / D / O	# 179	David Law
On the basis of previous changes I have noted suggest that micrometers<CR>should use the symbol.				
CI 38A	SC 38A.6	E / D / O	# 180	David Law
"Is there reference to 38L.7 correct, suggest it should be to 38A.3."				
CI 38B	SC 38B.1	T / D / O	# 83	Joe Gwinn
Reference problem: "This method" actually points to restricted launch, <CR>while OFL was intended.				

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		Response Status	Author
		E / D / O	#		
CI 38B Stray character.	SC 38B.2	E / D / O	# 82		Joe Gwinn
CI 38B Are the document references exact? Specifically, aren't the <CR>parenthetical references to "TIA-455-xxx" incomplete, as the "EIA/" <CR>p	SC 38B.2	1 / D / O	# 84		Joe Gwinn
CI 38B Paragraph numbers are wrong. This is annex 38B, but 38A is used.	SC global	E / D / O	# 80		Joe Gwinn
CI 39 typographical error? in Table 39-2	SC 39.3.1	E / D / O	# 192		Kelly McClellan
CI 39 a Differential Sensitivity - Maximum of 2000mV is specified,<CR>but the intent seems to be specifying a maximum input level<CR>tolerance	SC 39.3.2	E / D / O	# 194		Kelly McClellan
CI 39 "Differerential Sensitivity" is used in Table 39-4<CR>but "receiver sensitivity" is used in line 7 of pg. 39-7	SC 39.3.2	E / D / O	# 193		Kelly McClellan
CI 39 "Is the reference to Table 38-8 correct, suggest it should be to Table 38-<CR>10."	SC 39.3.3	E / D / O	# 181		David Law
CI 39 Typo in <CR>'A 1000Base-CX compliant jumper cable assembly shall consist of two<CR>polarized, shielded PLUG as described in 39.5.1 a	SC 39.4	E / D / O	# 21		Steve Brewer
CI 39 Typo & wording in <CR>'-3, having pinouts matching those in Figure 39.6, and the signal quality<CR>AND AND electrical requirements of thi	SC 39.5	E / D / O	# 22		Steve Brewer
CI 39 Typo in 'Style-1 or style-2 connectrors may be used....'	SC 39.5.1	E / D / O	# 20		Steve Brewer
CI 39 Similar to previous comment for style 1 connectors...<CR>(Note the typo 39-7-<CR>'-103, having pinouts matching those shown in Figure 3	SC 39.5.1.2	E / D / O	# 23		Steve Brewer
CI 39 Pin 5 for a style-2 connector has been reserved for two functions.<CR><CR>ie PWR from line 42 and Output Disable from line 47.<CR>Not	SC 39.5.1.2	1 / D / O	# 24		Steve Brewer
CI 39 Type<CR>'Electrical measurements shall be PERFORMMED as described in this...'	SC 39.6	1 / D / O	# 25		Steve Brewer
CI 39 Reference to 11801 seems to be incorrect. If comment accepted also need to<CR>correct PICS item OR14 in 39.8.4.4	SC 39.7	E / D / O	# 182		David Law
CI 39 Suggest that the SD entry in the Major options table is not longer required<CR><CR>as this is no longer an option. SD is also no longer req	SC 39.8.3	E / D / O	# 183		David Law
CI 39 The text in this sub-clause is not consistent with the resoution of<CR>comment 204 of draft 3.1.	SC 4	TR / D / O	# 6		Robert Campbell
CI 39 Differentiate this specification from the skew measurement between<CR>pairs in a cable.	SC 6.5	1 / D / O	# 9		Robert Campbell
CI 39 Change `NEXT' to `NEXT Loss'.	SC 6.7	1 / D / O	# 8		Robert Campbell

**P802.3z Draft 3.2
Summary Report**

	CommentType	Comment Status		
			Response Status	
CI 39 Add 'loss' after '(NEXT)'.	SC 6.7	TR / D / O	# 7	Robert Campbell
CI 41 I believe we agreed that all the notes under the figures should be deleted.	SC 41.1.1	E / D / O	# 18	Shimon Muller
CI 42 SFD has the wrong acronym definition. <CR><CR>Reference - .3z 35.2.2.7 (page 35.11, line 22)<CR>	SC 42.3.1	E / D / O	# 59	Kevin Daines - .3 3.2.2 (page 13)