Seq. #	Section number	your ini-tials	Cmnt type E, e, T, t	Part of NO vote	Corrected Text/Comment	Rationale	Disposition/Rebuttal

Section 7 comments from Ballot on Draft Standard D2 (Vic Hayes, Chair, AT&T WCND)

Seq. #	Section number	your ini-tials	Cmnt type	Part of NO vote	Corrected Text/Comment	Rationale	Disposition/Rebuttal
1	7.1	BTh	t		**Figure 7-1 has two interfaces with the same name, PLME_SAP. Change one**	This is same figure as 2-11 and I had the same comment there. How can two different SAPs have the same name? Change one of them. If the last paragraph of this section is true then eliminate on of the SAPs in the picture or show it as a ghost SAP.	See resolution of comment in section 2 - author withdrew it and so this comment was withdrawn also.
2	7.1	MB	e		**4th paragraph, second sentence.. add Acronym.... via a Service Access Point (SAP)**		declined **defined in 802 reference docs and Clause 1.**
3	7.1	TM	e		in third paragraph change The following figure .... to Figure 7-1 ...	there is no guarantee that the final document will be organized such that the illustrations fall into these locations	This was corrected - the figure was a duplicate of 2-11, and was replaced with a reference to the original figure.
4	7.2	TM	e		in second paragraph change The following figure .... to Figure 7-2	there is no guarantee that the final document will be organized such that the illustrations fall into these locations	This was corrected - the figure was a duplicate of 2-11, and was replaced with a reference to the original figure.
5	7.2	TM	e		under XX_SET.request and XX_SET.confirm change .... that that .... to that the		corrected
6	7.3	ZJ	T	N	Delete MLME_SCAN and MLME_POWER_MGT primitives	Scanning and power management should be controlled through MIB variables, along with bit-rate and all that other stuff.	after discussion with author, he decided that the curetn text was ok - comment withdawn.