

comments

Cl 33 SC 2.8.5 P43 L16 # 104
Darshan, Yair Microsemi Corporation

Comment Type T Comment Status D annex

Draft 1.0:

In many occasions the normative text send the reader to see figures 33C.4 and 33C.6 which contains valuable data.

These drawings should be at the normative text as it was in early drafts of 802.3af and were moved to the informative section due to editing considerations.

SuggestedRemedy

Move figures 33C.4 and 33C.6 (after updating them per my previous comment) to the normative section at the location where they are mentioned for the first time.

Proposed Response Response Status O

opposite comment of Fred 138 which asks to delete reference to these figures

Cl 33 SC 2.8.8 P44 L5 # 138
Schindler, Fred Cisco Systems

Comment Type TR Comment Status D annex

The reference to "Figure 33C.4 and Figure 33C.6" are no longer correct. The information provided in Figure 33-9a supersedes them.

SuggestedRemedy

Remove reference to "Figure 33C.4 and Figure 33C.6."

Proposed Response Response Status O

opposite comment of Yair 104 which asks to pull these into the normative text.