

P2MP Sub Task Force Report

Gerry Pesavento

May 2003, Seoul

Work ahead

Clause	E	T	TR	Total per Clause
4	6	1		7
31A	1	1		2
64	150	152	16	318
65	38	25		63
Total	195	179	16	390

Key issues

- Clocking scheme: Loop timing vs. Independent timing
- Specification of timestamp reference point(s)
- Fixing problems with GATE processing state diagram
- Text description should be harmonized with state diagrams.
- Description of client interfaces should be collected to a single location under 64.3.11 "Service Interfaces".
- Addition of PICS

Naming Conventions

There are naming inconsistencies in 802.3:

Figure 31-2 uses 'length/type' field,
but Figure 31-4 uses 'LengthOrType' field.

We seek input from Editor-in-Chief