

Comment ID 172 **Topic**
Name SambaMurthy
Email
Phone
Fax
Co. XaQti

CI 30 **SC** 30.3.1.1.23 **P** 30.24 **L** 6,9

Comment Type E **Comment Status** A

Length field has been changed to Length/Type field as per 802.3x standard.

SuggestedRemedy

Replace "length" field with "length/type" field and also include the reference to subclause 3.2.6 of the 802.3x standard.

Proposed Response **Response Status** C

Accepted. Fix in D3.1.

Comment ID 173 **Topic**
Name Sumesh kaul
Email skaul@baynetworks.com
Phone 408-495-3418
Fax 408-495-129
Co. Bay Networks

CI 30 **SC** 30.3.1.1.24 **P** 30.24 **L** 15

Comment Type E **Comment Status** A

Since type field has been defined in 802.3x, there should be a reference to that section of the document.

SuggestedRemedy

Right after Type field insert the reference to subclause 3.2.6 of the 802.3x standard.

Proposed Response **Response Status** C

Accepted. Fix in D3.1.