Comments Received

SuggestedRemedy

line in its entirety Proposed Response

IEEE P802.3.1b D1.3 MIB Rev Task Force 3rd Working Group recirculation ballot comments

C/ 6 SC 6.3.2 P88 L 22 # 136 CI 9 SC 9.1.2 P 202 L17 Simms, William **NVIDIA** Simms, William **NVIDIA** Comment Type Comment Status X Comment Type Comment Status X dot3Oam-PeerMode is split between two lines unlike others in the table XGMII is not defined in the terms at bottom of Figure 9-6 which is inconsistent with prior Figures SuggestedRemedy SuggestedRemedy Add newline after the comma and move 'dot3OamPeerMode' on second line in its entirety define XGMII under GMII term defintion Proposed Response Response Status O Proposed Response Response Status O CI 6 SC 6.3.2 P89 L 27 # 137 CI 9 SC 9.2 P 204 L37 Simms, William **NVIDIA** Simms, William **NVIDIA** Comment Type Comment Status X Comment Type Comment Status X dot3OamErr-FramThreshold is split between two lines unlike others in the table Ion the title of Table 9-2 it states 'A single row exists in the table.' It is unclear to me what SuggestedRemedy this means Add newline after the comma and move 'dot3OamErrFrameThreshold' on second line in its SuggestedRemedy entirety no proposed change as this is a question for clarity Proposed Response Response Status O Proposed Response Response Status O CI 6 SC 6.3.2 P89 L 32 # 138 Simms, William **NVIDIA** Comment Type E Comment Status X Same comments as above for dot3OamErrFramePeriodThreshold

Add newline after the comma and move 'dot3OamErrFramePeriodThreshold' on second

Response Status 0

139

140